

Iurp=	Ulfkdug#Vdwnlq
Vhqw=	Z hgqhvqd #D sul#56/#5347#44-44#D P
Wr=	Olvch/#Eudqgl
Ff=	Mrvhsk#R z hqv
Vxemhfw=	5345#DXFHU

Brandi, good morning. ADEM's letter to MDA dated June 24, 2013 provided concurrence on the 2012 LUCER but also requested clarification on the monument. During our meeting in Montgomery on November 14, 2013, we discussed that monument #7 was rotated 180° from proper orientation during the installation process and is unable to be rotated to the proper orientation. There is no damage to the monument and no further comments about its rotation will be noted on the landfill cap inspection checklist unless damage is observed to the monument. Let us know if you need any additional information. Thanks.