APPENDIX E PRIVATE BOAT DOCK CARRYING CAPACITY STUDY

Lake Sidney Lanier, Georgia November 2003

Private Boat Dock Carrying Capacity Study for Lake Sidney Lanier, Georgia

Prepared for

US Army Corps of Engineers Mobile District Mobile, Alabama

and

Lake Lanier Project Office Buford, Georgia

by

Tetra Tech, Inc. 10306 Eaton Place, Suite 340 Fairfax, Virginia 22030 October 22, 2002

Contents

Introduction	1
Background Information	
Lake Lanier	
Lake Lanier Shoreline	
Shoreline Zones	
Shoreline Length	
Physical Factors Related to Private Boat Dock Placement	
Adjacent Landowner Property	
Docks in the LDA	
Dock Length and Width	
Length of Floating Ramps and Walkways	
Placement of Anchoring Cables	
Lake Level	
Cove Width	
Slope and Water Depth	
Approach for Background Data Analysis	
Determining Shoreline Length	
Determining LDA Locations and Lengths.	
Determining Existing Dock Locations	
Determining the Number of Private Boat Docks in Each LDA	
Determining Development Level in Each LDA.	
Results of the Background Data Analysis	
Shoreline Length	
LDA Locations and Lengths	
The Dock-Permitting Scenarios	
Scenario 1: Existing Conditions 50-foot Distance Required Between Docks	
Scenario 2: Average Cable Anchor Spacing, 50 Percent Dock Installation Density, Excess	
Docks in Saturated LDAs Deducted	16
Scenario 3: 50-foot Distance Required Between Docks and 50 Percent Dock Installation Density	
Scenario 4: Average Cable Anchor Spacing and 50 Percent Dock Installation Density	
Scenario 5: 100-foot Distance Required Between Docks and 50 Percent Dock Installation Density	
Scenario 6: 82 Feet of Frontage to Corps Property Required to Obtain a Permit	
Scenario 7: 100-foot Distance Required Between Docks	
Scenario 8: Dock Spacing as Prescribed in 1988 SMP, Average Cable Anchor Spacing, and	
50 Percent Dock Installation Density	20
Scenario 9: SMP Maximum Spacing and 50 Percent Dock Installation Density	20
Results of the Dock-Permitting Scenarios	
LDA Development Level	
Additional and Total Docks Under the Dock-Permitting Scenarios	21
Other Factors That Could Affect Dock-permitting	
Soils	23
Cove Width	24
Sensitive Shoreline Vegetation	26
Sensitive Habitats	27
Endangered and Threatened Species	
Cultural and Historic Resources	28
Visual and Aesthetic Resources	28
Summary	32
Acronyms and Abbreviations	
References	35

APPENDIX A:	Excerpts from 1988 Shoreline Management Plan and				
	Engineer Regulation 1130-2-406	37			
APPENDIX B:	LDA Data	38			
TABLES					
Table 1. Spatial a	and Linear Shoreline Allocation.	14			
	d and Unsaturated LDAs Under Dock-Permitting Scenarios.				
	ry of Private Boat Dock-permitting Scenarios.				
	Table 4. Percent of LDA Shoreline Within Ranges of Slope. Table 5. Scenic Attractiveness Class Definitions.				
Table 6. Scenic I	ntegrity Definitions.	31			
Table 7. Visual I	Ratings of Photographs With Views of Boat Docks.	31			
FIGURES					
Figure 1. Project	location	2			
	ne allocation.				
Figure 3. Distrib	ution of Lake Lanier shoreline by shoreline use	6			
Figure 4. Sample	LDA	10			
Figure 5. Slopes	along LDA shoreline	25			
Figure 6. Relatio	nship between slope of adjacent land and cove width to provide sufficient water				
depth f	or dock permitting	26			
Figure 7. Existin	g dock viewsheds.	30			

Introduction

This *Boat Dock Carrying Capacity Study* was prepared by Tetra Tech, Inc. of Fairfax, Virginia under contract to the US Army Corps of Engineers, Mobile District (USACE, Corps). The study focuses on one aspect of the future management of Lake Sidney Lanier: The number of private boat docks that could be located along the lake's shoreline at some time in the future when all shoreline areas where boat docks may be permitted are at full capacity for boat dock development. This study, therefore, estimates the maximum number of private boat docks that could be on the lake. That maximum number is estimated under nine different scenarios, which differ primarily in how the private boat docks are spaced along the shoreline; wider spacing results in a smaller maximum number of docks.

This study was conducted to examine the relationship between potential private boat dock-permitting guidelines at the lake, and future shoreline dock density. The study was done in conjunction with updating the Lake Lanier Shoreline Management Plan (SMP). The SMP was last updated in 1988 and an environmental impact statement for the operation and maintenance of the lake, which included an analysis of potential changes to the SMP, was being prepared at the same time that this report was being written.


The study was conducted to:

- Examine data related to the number and location of boat docks on Lake Lanier.
- Determine potential future numbers of private docks based on different dock-permitting scenarios.
- Determine the effects of environmental factors at the lake on dock installation density.

Background Information

Lake Lanier

Lake Lanier is a USACE project in the Chattahoochee and Chestatee River Basins of northern Georgia (Figure 1). Buford Dam forms the multiple-purpose project. Impoundment of the lake was completed in 1957. The lake collects drainage from 1,045 square miles on the southern slopes of the Blue Ridge Mountains. Lake Lanier has 39,038 acres of surface water, 752 miles of total shoreline (mainland and islands), and 17,745 acres of land above the full power pool elevation of 1,071 feet above mean sea level (msl). Authorized purposes of the lake include hydroelectric power production, flood control, water quality protection, water supply, fish and wildlife preservation, navigation, and recreation.



Lake Lanier is north of Atlanta, Georgia, and has been greatly affected by the rapid growth of the Atlanta metropolitan area. The lake's aesthetic and recreational appeal make it one of the most highly used Corps lakes in the country. In addition, only a slim border of government-owned land surrounds the lake, so area residents can live very near the lake in quite attractive settings. Residential development continues in areas surrounding the lake. The development brings more and more landowners with private property adjacent to government property surrounding the lake, and who want to install private boat docks along the shoreline.

As of 2002, Lake Lanier had 8,348 private docks and 11 community docks on its shoreline. Forty-seven percent of Lake Lanier's shoreline is designated as *Limited Development Area*, or LDA, where private and community docks and other private floating facilities may be permitted. Using the current situation as a starting point, each of the permitting scenarios presented later in this report uses a different set of dock-spacing criteria to estimate the number of additional docks that could be accommodated on the lake.

Lake Lanier Shoreline


The number of private boat docks on Lake Lanier has been increasing in tandem with the growth of the metropolitan Atlanta region. By 1974 the Corps had issued permits for some 2,500 private docks. The number of dock permits had increased to approximately 6,500 by the time the SMP was last updated in 1988. The number of private docks had increased to 8,200 by 2000, and as of the date of this report the number stood at 8,348. An additional 11 community docks are also permitted on the lake. Based on the 9 years from 1992 and 2000, an average of 175 new Shoreline Use Permits for docks are issued each year.

Shoreline Zones

The Lake Lanier shoreline is divided into four classifications: Prohibited Access Areas, Protected Shoreline Areas, Public Recreation Areas, and Limited Development Areas (Figure 2).

Prohibited Access Areas are designated to protect project operation areas (Buford Dam, powerhouse intakes, saddle dikes, spillway, tailrace, and Corps marine yard), and the recreational visitor. Restricted access is allowed at most Prohibited Access Areas, and lakeshore use permits are not issued for the areas. Approximately 0.2 percent (1.74 miles) of the shoreline is classified as Prohibited Access Area, all of which is on the mainland shoreline.

Protected Shoreline Areas are designated to preserve the scenic appeal of the lake; to avoid conflict between private and public uses; to protect habitat for fish and wildlife; to protect cultural, historical, and



Shoreline Allocation

Figure 2

archaeological sites; to protect endangered species; to protect navigation channels; to restrict the placement of floating facilities in areas that are too shallow or too exposed to winds and currents; and to protect important natural formations and vistas. Of the 239.86 miles designated *Protected Shoreline Area*, 180.58 miles (75.3 percent) are along the mainland shoreline, constituting 24 percent of that shoreline. The other 59.28 miles (24.7 percent) are on lake islands.

Public Recreation Areas are set aside for intensive recreational development or use. Campgrounds; day use parks; primitive or natural areas; lands leased to public groups and other local, state, or federal agencies for recreational use or development; and marine services are located in Public Recreation Areas. The lake's marinas and Lake Lanier Islands complex, for example, are in these shoreline areas. Public Recreation Areas occur along the mainland shoreline only. Of the 156.61 miles designated Public Recreation Area, 137.08 miles (87.5 percent) are along the mainland shoreline and occupy 18.2 percent of that shoreline. The remaining 19.53 miles (12.5 percent) are on lake islands.

Limited Development Areas are areas where certain private facilities may be permitted on public lands. Private boat docks are the most conspicuous facility type permitted in LDAs. Other facilities that may be permitted include community boat docks, ski jumps, floats, duck blinds, and facilities associated with private boat docks including electrical lines, water lines, steps or walkways, telephone lines, and pumps. Facilities in LDAs are permitted for 5 years. All 353.83 Limited Development Area miles are along the mainland shoreline, occupying 47 percent of that shoreline.

Shoreline Length

The length of the Lake Lanier shoreline, including all islands on the lake, has historically been considered to be 540 miles long. This shoreline length was estimated before the widespread use of geographic information systems (GIS) for the data analysis. Using the best data currently available and GIS technology, the shoreline is now estimated to be 752 miles long.

The revised shoreline length (752 miles) and GIS technology were used to arrive at the revised total lengths of shoreline in each shoreline classification provided above. Figure 3 illustrates the relative abundance of each shoreline classification for both the mainland and islands.

Physical Factors Related to Private Boat Dock Placement

Many physical factors come into play when the Corps decides where a private boat dock may be located. These factors are discussed in this section.




Figure 3. Distribution of Lake Lanier shoreline by shoreline use.

Adjacent Landowner Property

Only adjacent landowners (i.e., landowners who have unrestricted legal access through private property to public lands that are zoned *Limited Development*) are eligible for private boat dock permits. (See Section 12.5.1 of the 1988 SMP [Appendix A]). Docks must be located at the point of the shoreline nearest to the adjacent landowner's property, though deviations of 100 feet to either side of this point are allowed if water depth or dock spacing is an issue. (See Section 12.5.2 of the 1988 SMP [Appendix A].)

Docks in the LDA

Dock location is configured at the full conservation pool level of the lake, which is 1,071 feet above msl. Under the 1988 SMP, docks must be no closer than 50 feet from each other at that level. Current docks in an LDA, therefore, restrict the placement of additional docks. (See Section 12.5.2 of the 1988 SMP [Appendix A].) For instance, an existing dock might be too close to the end of an LDA (i.e., closer than 74 feet¹) to allow another dock to be placed in the available space, or two existing docks might be too close together (i.e., less than 124 feet apart¹) to allow placement of a third dock between them.

.

¹ 74 feet, not 50 feet, is used because docks may be placed no closer than 50 feet from each other, dock edge-to-dock edge. 74 feet would be necessary to achieve this distance for a 24-foot wide dock. 124 feet is used for the minimum spacing of two existing docks to account for the 24-foot wide dock and 50 feet to each side of the dock.

Dock Length and Width

The maximum external dimensions of a dock are 32 feet by 32 feet (1,024 square feet), and the maximum size of an attached platform or deck may not exceed 192 square feet. (See Section 12.5.3.1 of the 1988 SMP [Appendix A].)

Length of Floating Ramps and Walkways

A floating ramp leading to a dock may not exceed 40 feet in length, and a land-based, fixed-section walkway or steps used in conjunction with the ramp may not exceed 10 feet in length. The land-based portion is considered part of the ramp, and therefore the 40-foot limit applies to the combined length of the land-based and floating portions of a ramp. (See Section 12.5.3.4 of the 1988 SMP [Appendix A].) Together, a walkway, ramp, and dock cannot exceed 72 feet in length, which is the combined maximum length of a walkway and ramp (40 feet), and a dock (32 feet).

Placement of Anchoring Cables

Cables used to anchor a dock to the shoreline must be secure, and they should be placed at a 45-degree angle to the dock itself. (See Section 12.5.3.9 of the 1988 SMP [Appendix A].) Anchor cables must not obstruct the public's use of the shoreline or water surface. In addition, the cables of neighboring docks should not cross each other. (See Section 12.5.3.9 of the 1988 SMP [Appendix A].)

Lake Level

As noted previously, dock location is configured at the full conservation pool level of the lake, 1,071 feet above msl. At lake levels marginally below or above this level, the placement of a dock at 1,071 feet above msl is approximated. Dock-permitting may be suspended when the lake falls to a level where accurate judgments of site requirements cannot be made. The lake level at which dock-permitting is suspended is 1,063 feet above msl. Permitting remains suspended until the lake rises to or exceeds 1,063 feet above msl.

Cove Width

Docks are not to be placed in the water such that they extend into the center third of a cove because that area must remain open for navigation. (See Section 12.5.2 of the 1988 SMP [Appendix A].) This restriction is especially important for dock placement in shallow or narrow coves. See the discussion below under *Slope and Water Depth*.

Slope and Water Depth

The slope of the surrounding land is not in itself a factor that often limits dock placement because the shoreline surrounding Lake Lanier is mostly gentle (less than a 50 percent slope; for example, a 10-foot vertical rise over a 20-foot horizontal length of land). However, the slope of the lake bottom can limit dock placement because the 1988 SMP requires that there be at least 5 feet of water below the edge of the dock farthest from the shoreline. (See Section 12.5.2 of the 1988 SMP [Appendix A].) Very gently sloped areas might not provide sufficient depth of water (5 feet) within 72 feet of the shoreline (the maximum combined length of a dock and approach ramp/walkway) (see *Length of Floating Ramps and Walkways* above), or within the third of the cove (see *Cove Width* above) adjacent to the shoreline.

Approach for Background Data Analysis

Determining Shoreline Length

The length of boundary frontage between Corps property and private property (i.e., the property line between government and private property around the lake) and the length of the shoreline within LDAs were used as the primary factors to determine how many additional private docks could ultimately be permitted on the lake. The boundary frontage length is important because a private property owner must have unrestricted access to government property in order to receive a dock permit (ER 1130-2-406, Section 4(f)). The length of the lake's shoreline within LDAs is important because a minimum distance of 50 feet between private docks is required by the 1988 SMP, though a different distance might be specified if the SMP is revised. ER 1130-2-406 also specifies that floating facilities occupy at most 50 percent of the LDA in which they are located, based on the linear feet of shoreline in the LDA. (See ER 1130-2-406, Section 10 [Appendix A]). The location and length of the Corps property boundary line, the lake's total shoreline length, and the shoreline length within LDAs were determined using GIS information obtained from the Corps.

A high-resolution digital image of the frontage boundary line of Corps property surrounding Lake Lanier and a high-resolution digital image of the lake's shoreline at 1,071 feet above msl were used to determine the shoreline length. The two images were combined to create a digital image of the Corps property surrounding the lake, and on islands at the full conservation pool level (i.e., 1,071 feet above msl). The Corps property then was subdivided by shoreline allocation zone using the *Lake Sidney Lanier Shoreline Use Allocations Atlas* as a guide. The result of this effort was a GIS data layer that provides information on shoreline-use classification for each shoreline zone area.

Determining LDA Locations and Lengths

The geographic limits of each LDA were required to determine the lengths of the individual LDAs. The LDA lengths, in turn, were necessary to determine the potential number of boat docks that could be permitted in each LDA. Current shoreline allocation maps in combination with the information developed on the total length of the lake's shoreline were used to determine the limits and lengths of all individual LDAs. Using GIS, the outlines of the LDAs were overlaid on an outline of Corps property around the lake to determine the length of each LDA as accurately as possible.

Two sets of limits for each LDA were necessary for the analysis. First, the boundary frontage limits of each one were necessary (Figure 4). The boundary limits are the start and end points of the government property line of an LDA, and the locations of points where the property line changes direction. With these points the total boundary frontage length of each LDA was determined. Second, the length of each LDA along the shoreline at 1,071 feet above msl was needed. Determining this length was slightly more complicated because many LDAs are dissected along their shorelines by segments of shoreline designated as *Protected Shoreline Area* (Figure 4). The total shoreline length of an LDA was determined by summing the lengths of the individual LDA shoreline segments associated with the entire boundary frontage LDA. There are 435 LDAs as determined by boundary frontage (Appendix B), and within those LDAs there are 619 LDA shoreline segments.²

Because of variations in the configurations of the boundary frontages of LDAs and the associated shorelines, the shoreline length of an LDA might be longer or shorter than the same LDA's boundary frontage length.


Determining Existing Dock Locations

Knowledge of the locations and number of boat docks in each LDA at the time of this report (2002) was necessary to determine the potential level of development for each LDA. The Corps identifies the location of private boat docks by giving each dock a shoreline location code. The location codes are assigned to docks according to their distance along the shoreline from Buford Dam moving in a clockwise direction from the dam around the lake (i.e., moving north from the dam and continuing around the lake through Forsyth, Dawson, Lumpkin, Hall, and Gwinnett counties, in that order) (Figure 2). The dock location codes, however, are not accurate enough to determine the precise location of each dock, or the distances

-

² Unless otherwise noted, use of the acronym "LDA" throughout the rest of this report refers to LDAs as determined by boundary frontage.





between docks, because the measurements used to assign the location codes were based on an erroneous shoreline length. The codes, however, proved valuable for identifying the LDA in which each dock is located.

Aerial photography imagery from 1999 was used in conjunction with the Lake Lanier dock permit database, which contains the location codes referred to above, to develop a GIS coverage of the locations of the 8,348 private boat docks, and 11 community docks on Lake Lanier. Once a dock on the aerial image was matched to the dock's shoreline location code in the Corps permit database, the dock was digitized. The actual point for the dock was digitized as the center of the boathouse on the edge of the dock closest to the shoreline. In many cases, docks were so close together, forming "clusters," that it was impossible to identify precisely which dock on the image matched each record in the permit database. This was solved by observing the dock clusters and the gaps (the dockless areas that separated the clusters) in the database and finding corresponding clusters and gaps on the aerial photos. This approach minimized the error of points digitized from the image not matching the information in the database.

The Corps dock permit database contains 254 docks that were installed after March 1999 (the date of the aerial photographs), so the photographs do not show these docks. The locations of these 254 docks were estimated using their shoreline location codes in the database in conjunction with the codes of the docks in the database nearest to them (determined based on the location codes).

Community docks and the number of overnight slips they contain were also incorporated into the GIS database. A final GIS database of the 8,348 private dock locations and 11 community dock locations—the same number as that in the permit database—was realized.

Determining the Number of Private Boat Docks in Each LDA

The number of boat docks in each LDA was determined by projecting the digitized dock locations in the GIS to the nearest location on the shoreline and coordinating this information with the previously determined boundaries of each LDA shoreline segment. Some projected locations of docks fell outside shorelines designated LDA. In these instances, the LDA shoreline segment nearest to the dock in question was determined and the dock was assigned to the corresponding LDA. The number of digitized points assigned to an LDA was used as the number of private docks along the LDA.

For the purposes of this analysis, it was desirable somehow to equate the community docks to private docks, and the method chosen was based on slips. The 11 community docks on the lake have a total of 488 slips. Assuming that two slips in a community dock equate to one private boat dock, and taking into

account the distribution of the slips on the lake, the number of slips in community docks equates to 245 private boat docks. Thus, for the analyses in this study of the number of total and additional docks that the lake could accommodate, a total of 8,593 (8,348 + 245) private boat docks was used as the current number of private docks on the lake.

Determining Development Level in Each LDA

Knowing the number of private boat docks along an LDA allowed a determination of whether an LDA is saturated with boat docks. A "saturated" LDA is one that would accommodate no additional docks under a particular scenario. An "unsaturated" LDA would, of course, accommodate additional docks. All but one of the dock-permitting scenarios considered (the scenarios described below) used LDA shoreline length rather than LDA boundary frontage length to determine whether additional docks could be placed in an LDA. Because the shoreline lengths and boundary frontage lengths of LDAs are not equal and the scenarios differ in how docks are spaced, whether a LDA is saturated or unsaturated can differ from scenario to scenario.³

Few LDAs are saturated with docks under the current dock-permitting policy. That is, when the minimum 50-foot buffer distance between docks (per Section 12.5.2 of the SMP [Appendix A]) is applied to existing docks, and a 24-foot wide dock is assumed, few LDAs are shorter than the number of existing docks multiplied by 74 feet—the sum of the width of a dock and its associated dock-to-dock buffer. Thus, when calculating the amount of LDA shoreline currently occupied by docks, the result was rarely larger than the LDA shoreline length. To illustrate this, consider an LDA that has 400 feet of shoreline and six docks. Under the current dock-permitting policy (Scenario 1, see below), the six docks were calculated to occupy 444 feet (6 docks x 74 feet per dock), or an amount of shoreline greater than the length of the LDA shoreline. This LDA would be considered saturated with docks under Scenario 1. Under other dock-permitting scenarios, up to 100 or more LDAs would be considered saturated with docks.

An excess number of docks in LDAs was dealt with in one of two ways under a scenario: (1) The LDAs were considered saturated but the excess docks in saturated LDAs were ignored in all further calculations, or (2) the LDAs were considered saturated and the number of excess docks in saturated LDAs was subtracted from the number of additional docks the lake could accommodate. This approach followed from the requirement of Section 10 of ER 1130-2-406 that in LDAs where the 50 percent density of

³ Example: An LDA 500 feet long with 5 docks would have an occupied shoreline length of 370 feet with a dock-permitting scenario of 50 feet between docks, and assuming that docks are 24 feet wide (5 x [50 + 24] = 370). Under this scenario the LDA would be unsaturated and would be able to accommodate an additional dock. Under a dock permitting scenario of 100 feet between docks and still assuming 24-foot wide docks, the existing 5 docks would occupy a total LDA shoreline length of 620 feet (5 x [100 + 24] = 620), or more than the total length of the LDA. Under this scenario the same LDA would be saturated.

development criterion is exceeded, docks should be removed by attrition until the 50 percent density is attained (Appendix A). Scenario 2 is the only one in which excess docks were dealt with in the second manner.

Results of the Background Data Analysis

Shoreline Length

Using the best data currently available, and GIS technology, the estimate of the lake's shoreline length was updated to 752 miles. This is significantly longer than the currently quoted length, 540 miles.

The 1988 Lake Lanier SMP states that approximately 46 percent of the lake's mainland shoreline, or 248 miles, is designated LDA. The estimate was based on a shoreline length of 540 miles and a lake surface area of 38,024 acres at 1,071 feet above msl. That estimate of the lake's shoreline length was found to be erroneous, however, and this affected the percent and miles of shoreline allocated to each shoreline-use classification. Table 1 presents the updated estimate of Lake Lanier's shoreline length, and the division of its shoreline among the four shoreline-use classifications.

The distribution of shoreline-use classifications was calculated linearly (shoreline miles), and spatially (acreage). According to the calculations, there is a relatively even spatial (acreage) distribution of shoreline classifications, with the exception of *Prohibited Access Areas* (Table 1). LDAs, however, occupy relatively more shoreline miles per acre than other shoreline allocations. LDAs occupy 47 percent of the total shoreline and 35 percent of Corps property (0.057 mile/acre). *Public Recreation Areas*, such as day-use parks, campgrounds, and public boat ramp areas, occupy 20.8 percent of the shoreline and 30 percent of the property (0.029 mile/acre), and *Protected Areas* occupy 31.9 percent of the shoreline and 34.7 percent of the property (0.039 mile/acre). In general, then, LDAs are narrower than either *Public Recreation Areas* or *Protected Areas*, and private property lies closer to the lake along LDAs than along shoreline with other use classifications

LDA Locations and Lengths

LDA identification numbers, the length of LDAs, and the number of existing docks in the LDAs are provided in Appendix B.

Table 1. Spatial and Linear Shoreline Allocation.

Shoreline Allocation	Length (mi)	Percentage of Total Shoreline	Acres	Percentage of Corps Property
LDA (main shoreline)	344.70	45.8%		
LDA in water ¹	9.13	1.2%		
TOTAL LDA	353.83	47.0%	6,186.6	34.9 %
Protected, islands	59.28	7.9%		
Protected, main shoreline	177.44	23.6%		
Protected in water	3.14	0.4%		
TOTAL Protected	239.86	31.9%	6,163.6	34.7 %
Recreation (main shoreline)	156.34	20.8%		
Recreation in water	0.28	0.04%		
TOTAL Recreation	156.61	20.8%	5,329.5	30.0 %
TOTAL Prohibited	1.74	0.2%	64.9	0.4 %
TOTAL	752.05	100.0%	17,744.6	100.0 %

¹ "in water" refers to areas where the Corps boundary runs into the water. It is assumed that the shoreline paralleling these segments is of the same classification as the adjacent shoreline segments.

The Dock-Permitting Scenarios

The maximum number of docks on Lake Lanier was evaluated under nine different dock-permitting scenarios. Scenario 1 reflects existing conditions by using the currently implemented dock-permitting and locating guidelines to determine the number of docks that an LDA could accommodate in the future. Scenario 2 fully complies with the provisions of ER 1130-2-406. Other scenarios base the number of additional docks that the lake could accommodate on variations in the length of shoreline considered to be occupied by a boat dock, whether the 50 percent density of development criterion of ER 1130-2-406 was applied to existing or additional docks, and whether dock attrition (per ER 1130-2-406) was accounted for by deducting the number of excess docks in LDAs from the total number of docks that could be accommodated on the lake under the scenario. Unless otherwise noted, a dock width of 24 feet—the average width of docks on Lake Lanier—was used in the scenarios. Explanations of the nine scenarios are provided below.

Scenario 1: Existing Conditions 50-foot Distance Required Between Docks

Scenario (ey Point

- Current shoreline-use permitting policy.
- 74 feet of LDA shoreline length deducted for each existing dock (24-ft-wide dock + 50-ft buffer = 74 ft).
- Number of additional docks calculated as unoccupied LDA shoreline length ÷ 74.
- Excess number of existing docks was ignored. The number of existing
 docks in excess of the number of docks LDAs should have (based on 74
 feet per dock) was not deducted from the total number of additional docks
 the lake could accommodate in the future.
- Does not comply with ER 1130-2-406.

Under this dock-permitting scenario, which is the permitting policy currently in place at Lake Lanier, the number of docks that a LDA could accommodate was determined based on a spacing of 50 feet between docks, from the nearest edge of one dock to the nearest edge of a neighboring dock. This spacing is required by Section 12.5.2 of the 1988 SMP. The length of shoreline considered to be occupied by a dock itself was 24 feet, because most docks on the lake are 24 feet wide. The amount of shoreline occupied by each existing dock in an LDA, therefore, was 74 feet (i.e., 50 feet between docks plus 24 feet for the width of a dock). The total length of the LDA shoreline minus the total length of shoreline occupied by existing docks in the LDA gave the length of LDA shoreline available for additional docks. Because 74 feet is attributed to each future dock as well, the available shoreline length was divided by 74 to arrive at the number of additional docks, if any, that the LDA could accommodate in the future. If the length of LDA shoreline occupied by existing docks was greater than the actual length of the LDA shoreline, the excess was ignored. That is, the number of existing docks in LDAs in excess of the maximum number of docks LDAs should have under this scenario was not subtracted from the number of additional docks that the lake could accommodate in the future.

The total shoreline length of an LDA, not the length of an LDA along the boundary frontage, was used to determine the number of future docks that could be located in an LDA. (See Figure 4 for an illustration of an LDA shoreline.) This was necessary because the scenario uses the distance between docks to determine the number of additional docks that an LDA could accommodate, and this distance must be measured along the shoreline, not along the private property boundary frontage of an LDA. (All scenarios except Scenario 6 use the length of LDA shoreline to determine the number of additional docks that could be accommodated.)

Scenario 1 does not comply with Section 10 of ER 1130-2-406 (Appendix A) because it does not incorporate the 50 percent density of development criterion nor does it account for dock attrition in saturated LDAs, as required by the regulation.

Scenario 2: Average Cable Anchor Spacing, 50 Percent Dock Installation Density, Excess Docks in Saturated LDAs Deducted

Scenario Key Points

- Uses average cable anchor-to-cable anchor distance of 88 feet.
- 176 feet (88 ft. for moorage length + 88 ft. of unused shoreline) of LDA shoreline length deducted for each existing dock.
- Number of additional docks calculated as unoccupied LDA shoreline length ÷ 176.
- Excess number of existing docks was deducted from the total number of additional docks that would be allowed in the future.
- Fully complies with ER 1130-2-406.

Under Scenario 2, as in Scenario 1, LDA shoreline length was used to determine the number of docks an LDA could accommodate. Each existing dock was considered to occupy 88 feet of LDA shoreline, or the average cable anchor spacing—the distance between the two cable anchors that hold a dock in place (see explanation below). This distance was doubled to 176 feet to account for a 50 percent dock installation density along LDAs, as required by Section 10 of ER 1130-2-406 (see Appendix A). The number of existing docks in LDAs in excess of the maximum number of docks LDAs should have under this scenario was subtracted from the number of additional docks that the lake could accommodate in the future.

Average cable anchor spacing means that 88 feet was used as the average length of LDA shoreline occupied by a dock. The 88-foot average space between cable anchors is based on a series of measurements taken by Lake Lanier Project personnel. In autumn 2001, project personnel measured the distance between the two points at which individual docks are anchored for 345 docks on Lake Lanier. The average of the 345 measurements was 88 feet between cable anchors.

Scenario 2 complies with Section 10 of ER 1130-2-406 (see Appendix A), because it incorporates the 50 percent density of development criterion and it accounts for dock attrition, as required by the regulation, by reducing the number of additional docks that the lake could accommodate in the future by the number of excess docks in saturated LDAs.

Scenario 3: 50-foot Distance Required Between Docks and 50 Percent Dock Installation Density

Scenario (ey Points

- 148 feet (24-ft wide dock + 50-ft buffer [dock-to-dock] + 74 ft [to account for 50% LDA utilization]) of LDA shoreline length deducted for each existing dock.
- Number of additional docks calculated as occupied LDA shoreline length ÷ 148.
- Excess number of existing docks was ignored.
- Does not fully comply with ER 1130-2-406.

This scenario duplicates Scenario 1, except that docks are installed at a density of 50 percent in LDAs, as required by ER 1130-2-406. A 24-foot wide dock with its 50-foot buffer was considered to occupy 74 feet of LDA shoreline. The 50 percent dock installation density was accounted for by doubling this distance, or attributing 148 feet to each existing and additional dock. Excess docks in saturated LDAs were ignored, as in Scenario 1.

Scenario 3 does not comply with Section 10 of ER 1130-2-406 (see Appendix A) because it does not account for dock attrition in saturated LDAs, as required by the regulation.

Scenario 4: Average Cable Anchor Spacing and 50 Percent Dock Installation Density

Scenario key Points

- Uses average cable anchor-to-cable anchor distance of 88 feet.
- 176 feet (88 ft. for moorage length + 88 ft. of unused shoreline) of LDA shoreline length deducted for each existing dock.
- Number of additional docks calculated as *unoccupied LDA shoreline* length ÷ 176.
- Excess number of existing docks was ignored.
- Does not fully comply with ER 1130-2-406.

This scenario duplicates Scenario 2 except that, as in Scenario 1, excess docks in saturated LDAs were ignored. Because it does not account for dock attrition in saturated LDAs, as required by ER 1130-2-406, the scenario does not comply with the regulation.

Scenario 5: 100-foot Distance Required Between Docks and 50 Percent Dock Installation Density

Scenario Key Points

- 248 feet (24-ft wide dock + 100-ft buffer [dock-to-dock] + 124 ft [to account for 50% LDA utilization]) of LDA shoreline length deducted for each existing dock.
- Number of additional docks calculated as *unoccupied LDA shoreline* length ÷ 248.
- Excess number of existing docks was ignored.
- Does not fully comply with ER 1130-2-406.

This scenario duplicates Scenario 3, except that the buffer distance required between docks was increased from 50 feet to 100 feet. The combined width of a dock (24 feet) and the 100-foot buffer was 124 feet, and application of the 50 percent density of development criterion meant that each existing and additional dock was considered to occupy 248 feet of LDA shoreline. Excess docks in saturated LDAs were ignored, as in Scenario 1. Because Scenario 5 does not account for dock attrition in saturated LDAs, as required by ER 1130-2-406, the scenario does not comply with the regulation.

Scenario 6: 82 Feet of Frontage to Corps Property Required to Obtain a Permit

Scenario (ey Points

- LDA boundary frontage length used rather than LDA shoreline length.
- 74 feet of boundary frontage deducted for each existing dock (24-ft wide dock width + 50-ft buffer distance).
- 82 feet of boundary frontage (50-ft buffer + 32-ft wide dock [the maximum allowable dock width]) required to receive a dock permit.
- Number of additional docks calculated as unoccupied LDA boundary frontage length ÷ 82.
- Excess number of existing docks was ignored.
- Does not fully comply with ER 1130-2-406.

Under this future dock-permitting scenario, only landowners who have 82 feet (50-foot buffer between docks + the maximum allowable dock width of 32 feet) or more of private property frontage with Corps property designated as LDA would be eligible to apply for a dock permit. (See Figure 4 for an illustration of a LDA frontage segment.) The purpose of the scenario would be to discourage the existing practice of developers of creating property boundaries that give adjacent landowners narrow slices of land abutting LDAs, sometimes as narrow as 8 feet, to satisfy the 1988 SMP requirement that a landowner have legal access to the lake shoreline to apply for a dock permit. It would also discourage existing landowners with property frontage along LDAs from selling narrow strips of their property to other property owners to give these other landowners legal access to the shoreline. These types of boundary layouts create situations in which far more property owners have land with frontage along an LDA than the number of docks the LDA can accommodate.

A LDA's development level under this scenario was determined by subtracting 74 feet for each dock in the LDA from the total length of the LDA boundary frontage. The distance of 74 feet was chosen for existing docks because it is the length of LDA shoreline attributed to docks under the dock-permitting policy currently employed. After subtracting 74 feet for each existing dock from the LDA boundary frontage length, the LDA boundary frontage length remaining, if any, was divided by 82 feet to arrive at the number of additional docks the LDA could accommodate in the future. Excess docks in saturated LDAs were ignored in this scenario.

Scenario 6 does not comply with Section 10 of ER 1130-2-406 (see Appendix A) because it is not based on dock spacing along LDA shoreline. Because of this, it also cannot account for the dock attrition policy in saturated LDAs, as stated in the regulation.

This scenario would be most applicable to currently undeveloped land next to LDAs, and not to landowners who currently have land abutting LDAs because it would be unfair to deny the latter group the right to apply for a dock permit when they had that right when they purchased their land. Under this scenario, therefore, landowners who currently own private property that has less than 82 feet of frontage abutting a LDA would not be denied the right to apply for a permit for a boat dock.

Note that this dock-permitting policy, if adopted, would not prevent developers from creating land parcels with less than 82 feet of frontage to a LDA. Once the policy was in place, however, persons purchasing such parcels would do so with the knowledge that they would not be eligible to apply for a boat dock permit. The policy could also encourage developers to create common property access to LDAs for the installation and use of community docks.

Scenario 7: 100-foot Distance Required Between Docks

Scenario (ev Points

- 74 feet (24-ft wide dock + 50-ft buffer) of LDA shoreline length deducted for each existing dock.
- Number of additional docks calculated as *unoccupied LDA shoreline* length ÷ 124.
- Excess number of existing docks was ignored.
- Does not fully comply with ER 1130-2-406.

This dock-permitting scenario duplicates Scenario 1 except that the buffer distance required between additional docks was increased from 50 feet to 100 feet. A dock width of 24 feet was used. An LDA shoreline length of 74 feet was deducted for each existing dock, and a length of 124 feet was deducted for each additional dock. Excess docks in saturated LDAs were ignored, as in Scenario 1.

Scenario 7 does not comply with Section 10 of ER 1130-2-406 (see Appendix A) because it does not incorporate the 50 percent density of development criterion nor does it account for dock attrition in saturated LDAs, as required by the regulation.

Scenario 8:

Dock Spacing as Prescribed in 1988 SMP, Average Cable Anchor Spacing, and 50 Percent Dock Installation Density

Scenario Key Points

- Uses average cable anchor-to-cable anchor distance of 88 feet.
- 74 feet (24-ft dock + 50-ft buffer) of LDA shoreline length deducted for each existing dock.
- Number of additional docks calculated as unoccupied LDA shoreline length ÷ 176.
- Excess number of existing docks was ignored.
- Does not fully comply with ER 1130-2-406.

This dock-permitting scenario has characteristics of Scenarios 1 and 4. Existing docks were ascribed a length of 74 feet, or the most common dock width (24 feet) plus the 1988 SMP dock-to-dock buffer distance of 50 feet, as in Scenario 1. This reflects the conditions under which docks have been permitted to date. Additional docks, however, were considered to occupy 176 feet of LDA shoreline, or twice the average cable anchor-to-cable anchor distance of 88 feet, as in Scenario 4.

Excess docks in saturated LDAs were ignored, as in both Scenarios 1 and 4.

Scenario 8 does not comply with Section 10 of ER 1130-2-406 (see Appendix A) because it does not incorporate the 50 percent density of development criterion for existing docks, nor does it account for dock attrition in saturated LDAs, as required by the regulation.

Scenario 9:

SMP Maximum Spacing and 50 Percent Dock Installation Density

Scenario (ey Points

- Assumed cable anchor-to-cable anchor distance of 112 feet.
- 224 feet of LDA shoreline length deducted for each existing dock.
- Number of additional docks calculated as *unoccupied LDA shoreline length* ÷ 224.
- Excess number of existing docks was ignored.
- Does not fully comply with ER 1130-2-406.

This scenario was based on maximum specifications for dock installation as stated in Section 12.5.3 of the 1988 SMP. The SMP states that the maximum permissible dock width is 32 feet, the maximum permissible walkway length for a dock is 40 feet, and cable anchors must be extended from a dock at 45-degree angles. This equates to a cable anchor-to-cable anchor distance of 112 feet (32-foot wide dock + 40 feet to either side). According to ER 1130-2-406, all shoreline between cable anchor points is "occupied" by a dock and no more than 50 percent of LDA shoreline can be occupied by docks. Thus, under this scenario the 112 feet occupied by each dock was doubled to attribute 224 feet of LDA shoreline to each existing and additional dock.

Excess docks in saturated LDAs were ignored, as in Scenario 1.

Scenario 9 does not comply with Section 10 of ER 1130-2-406 (see Appendix A) because it does not account for dock attrition in saturated LDAs, as required by the regulation. In addition, although docks may be installed using the maximum measurements stated in the 1988 SMP, empirical evidence has shown that these dimensions are not representative of how most boat docks are installed on Lake Lanier. As previously mentioned, measurements from 345 docks resulted in an average cable anchor-to-cable anchor distance of 88 feet, not 112 feet.

Results of the Dock-Permitting Scenarios

LDA Development Level

As would be expected, the various scenarios resulted in different numbers of saturated and unsaturated LDAs depending on how much shoreline length was attributed to existing docks. LDA development levels under the scenarios are summarized in Table 2.

Table 2. Saturated and Unsaturated LDAs Under Dock-Permitting Scenarios.

	Saturated LDAs	Unsaturated LDAs				
Scenarios 1, 6, 7, and 8	4	431				
Scenarios 2 and 4	157	278				
Scenario 3	103	332				
Scenario 5	259	176				
Scenario 9	229	206				

Note: Scenarios 1, 6, 7, and 8 are based on existing docks occupying 74 feet; Scenarios 2 and 4 are based on existing docks occupying 176 feet; Scenario 3 is based on existing docks occupying 148 feet; Scenario 5 is based on existing docks occupying 248 feet; and Scenario 9 is based on existing docks occupying 224 feet.

Additional and Total Docks Under the Dock-Permitting Scenarios

The results of the nine dock-permitting scenarios are summarized in Table 3.

Other Factors That Could Affect Dock-permitting

Several other factors could affect the maximum number of private boat docks that could be accommodated on Lake Lanier.

Percent Change in Number of Docks 116 195 194 35 15 20 24 82 53 Potential Total 10,615 11,646 25,327 13,118 25,270 18,580 15,629 10,309 9,884 Additional **Potential** Docks 16,734 16,677 6,987 7,036 1,716 2,022 3,053 4,525 1,291 Spacing of 88 ft Cable Anchor Uses Average Yes Yes % 8 $^{\circ}$ $^{\circ}_{
m N}$ $^{\circ}$ $\frac{9}{2}$ 8 N (distance Required between additional Buffer docks) existing 100 ft 100 ft docks docks 50 ft Consumed by Boat Docks 74 ft of boundary frontage for existing docks 82 ft boundary frontage for 74 ft for existing docks 124 ft for additional docks 176 ft for additional docks 176 ft for additional docks 248 ft for additional docks 224 ft for existing docks 224 ft for additional docks 148 ft for additional docks 176 ft for additional docks 74 ft for existing docks 74 ft for additional docks 176 ft for existing docks 176 ft for existing docks 148 ft for existing docks 248 ft for existing docks Length of Shoreline 74 ft for existing docks additional docks **Dock Attrition** Considered Yes Š $^{\circ}$ S_O 8 N å Š 8 N Š Compliance 1130-2-406 Fully in with ER Yes 8 N ž 8 N No % ž å ž (Existing Conditions) Scenario 9 Scenario 5 Scenario 7 Scenario 8 Scenario 1 Scenario 2 Scenario 3 Scenario 4 Scenario 6 Scenario

Table 3. Summary of Private Boat Dock-permitting Scenarios.

Soils

Soil type is considered a potential limiting factor for dock-permitting because in many cases dock owners need to create some sort of access path to the shoreline where their dock is anchored. Soil characteristics, such as high erodibility and excessive slope, might be unsuitable for access paths and would be considered in dock-permitting. Shoreline soils of Lake Lanier were evaluated by examining U.S. Geological Survey (USGS) soil surveys for Dawson, Lumpkin, Hall, and Gwinnett counties. A soil survey for Forsyth County was also available, but it was published prior before Lake Lanier was created and, therefore, it does not show the shoreline.

Descriptions of all soil types found along the Lake Lanier shoreline in each of the four county soil surveys investigated were read to determine whether any soil characteristics might be limiting for access path use. USGS soil surveys categorize soils by their suitability for different types of uses and for particular applications within those use categories. *Recreational Development* is one use category, and *Paths and Trails* (Gwinnett and Hall Counties) and *Campsites* (Dawson and Lumpkin Counties) are applications within that category. All soil types are rated as having *slight*, *moderate*, or *severe* limitations for all applications within the use categories. A slight limitation means that little to no adjustment (surface treatment or other engineering modification) is necessary for the intended application. A moderate limitation means that some adjustment might be necessary, but the adjustment could be accomplished easily and at little cost. A severe limitation means that the soil type could be used for the application, but doing so would require extensive adjustment(s) at considerable cost. Because the ratings in the soil surveys were based on using soils for intensive recreational use, not the light use that would be expected for a dock access path, only soil types rated to have severe limitations for *Paths and Trails* or *Campsites* were considered to be potentially limiting for dock access paths. Limiting soil types were further narrowed to those soils with slopes of 50 percent (equivalent to 27 degrees) or more.

No soils along the Lake Lanier shoreline in Gwinnett or Hall Counties were rated severely limiting due to slope. Two soil types that occur along the shoreline in Dawson and Lumpkin Counties were rated severely limiting due to slopes of 25 to 70 percent. Because generally only soils with a slope of 50 percent or more are considered limiting for access paths on Corps property, only a subset of the soils would be considered limiting due to slope for the purposes of this study. That is, those soils within the slope range of 50 to 70 percent. By relating the soil survey information to slope information available from the GIS, it was found that areas with slopes of 50 percent or more are very uncommon along the lake's shoreline, representing only 0.09 percent of the total lake shoreline and 0.2 percent of the shoreline within LDAs. Therefore, soil type, including the soil type characteristics of slope and erodibility, was not considered a

critical factor in future dock-permitting. The distribution of slopes along LDA shoreline on Lake Lanier is presented in Table 4 and in Figure 5.

Table 4. Percent of LDA Shoreline Within Ranges of Slope.


Slope (percent)	Percent of LDA Shoreline
0 – 10	39
10 – 15	25
15 – 20	17
20 – 49	19
> 49	0

Another soil characteristic that could be limiting for access path placement is perpetual or seasonal wetness, which would indicate the presence of wetlands. The 1987 LMP indicates that because of the scarcity of wetlands in northern Georgia, Lake Lanier's wetlands should be preserved to promote the region's ecological integrity. Also contained in the LMP is the policy that to maintain wetlands, no permit that involves general or specific use or alteration of wetlands will be issued unless concurrence is gained from the Corps of Engineers, the U.S. Fish and Wildlife Service, and the Georgia Department of Natural Resources.

Wetlands are scarce along the Lake Lanier shoreline, and soils listed in the soil surveys as limiting for *Paths and Trails* or *Campsites* due to seasonal or periodic flooding occur mostly at the ends of coves where tributaries or creeks enter the lake. The limited occurrences of wetlands along the lake's shoreline and the small extent of wetlands along the shoreline where they do occur were factors considered unlikely to create a situation in which an adjacent landowner would not be able to find a suitable location for an access path. Wetlands, therefore, were not considered to be a critical factor in future dock-permitting.

Cove Width

The 1988 Lake Lanier SMP (Section 12.5.2) and ER 1130-2-406 (Section 10) require that the center third of a cove remain open to permit unobstructed navigation. When docks are permitted, the Corps sites them to ensure that they do not extend into the center third of a cove at a lake level of 1,071 feet above msl. When the lake level is lower than 1,071 feet above msl, however, landowners may move their docks out from the shoreline to achieve sufficient depth for their boats, but a dock is not to be moved out into the center third of a cove. The combination of the factors of the slope of the adjacent land and the width of a cove determines whether the guideline that the center third of a cove should remain open for navigation is a limiting condition for dock-permitting. The relationship between slope and cove width is shown in Figure 6. The figure shows the minimum cove width necessary to provide the minimum 5 feet of water depth (per SMP guidelines) below a private boat dock at a specified slope of land below the water



Slopes Along LDA Shoreline

Figure 5




Figure 6. Relationship between slope of adjacent land and cove width to provide sufficient water depth for dock permitting.

surface. For instance, a cove must be at least 150 feet wide at 1,071 feet above msl to accommodate docks if the slope below the water surface is 10 percent. This follows because the water depth would be 5 feet at 50 feet from the shoreline, which is the limit of dock placement to keep the center third of the cove open for navigation. Seventy-two feet is the farthest distance from the lake shoreline at 1,071 feet above msl that a dock may be positioned, given the limit of 32 feet for dock length and 40 feet for walkway length.

Sensitive Shoreline Vegetation

Information about protected and sensitive species of vegetation surrounding the lake was gathered from counties in which the lake lies, The Nature Conservancy, the Georgia Natural Heritage Program, the Lake Lanier Project Office, photographs, and other sources. Several sensitive plant species are known to occur in the Piedmont Physiographic Province of the southeastern United States, which is the physiographic province in which Lake Lanier lies. These species include the black-spored quillwort (*Isoetes melanospora*), little amphianthus (*Amphianthus pusillus*), Michaux's sumac (*Rhus michauxii*), Georgia aster (*Aster georgianus*), and white fringeless orchid (*Platanthera integrilabia*) (Natureserve, 2001a,b; USFWS, 1993a,b).

Only one of these plant species, the Georgia aster, might occur near the lake. Georgia Natural Heritage Program (2001) data indicate there is one population of Georgia aster on Corps property along the Lake Lanier shoreline, directly north of Buford Dam and the powerplant. It is not known whether the population is still extant. No other areas along the lake shoreline appear to support protected or sensitive plant species recommended for protection from disturbance (see below). The lack (or apparent lack) of special vegetative associations, however, does not reduce the importance of protecting natural shoreline vegetation to achieve shoreline and bank stabilization and a visually appealing lake environment.

Sensitive Habitats

The Piedmont region in which Lake Lanier is located is noteworthy for its biological diversity, but the plant communities in this region of the southeastern United States have been extensively altered since European settlement nearly 300 years ago (GDNR, 1997). Cotton and tobacco farming since colonial times has depleted and eroded Piedmont soils. Timber harvest and clearing for agriculture peaked in the early 20th century. Most forest communities in the Piedmont today are second-growth forests that have grown on abandoned agricultural lands (GDNR, 1997). The vegetative communities surrounding Lake Lanier consist of a mixture of pine forest, mixed hardwood–pine forest, and nonforested land. Sensitive habitats, which are habitats that support sensitive species or that are easily harmed by and do not recover easily from disturbance, are not known to occur along the Lake Lanier shoreline. However, sensitive habitats might occur along the shoreline and the impact of dock-permitting on such habitats, if they do occur, would be determined best by surveying specific areas of shoreline as they are proposed for development (including dock-permitting).

Endangered and Threatened Species

The effect of the presence of endangered and threatened species on the installation of boat docks is likely to be small. A few endangered and threatened species are reported from the counties in which Lake Lanier is located, but none appear to use habitat offered by the lake. Bald eagles (*Haliaeetus leucocephalus*) have been reported in Dawson, Forsyth, Gwinnett, Hall, and Lumpkin counties, and red-cockaded woodpeckers (*Picoides borealis*) are reported from Forsyth, Gwinnett, and Hall counties (Tucker, 2001). However, Georgia Natural Heritage Program (2001) data does not report any bald eagle nests or red-cockaded woodpecker nesting areas within 1 mile of the lake. Populations of bluestripe shiner (*Cyprinella callitaenia*)—a rare minnow endemic to the Appalachicola River drainage in Florida, Alabama, and Georgia—have been observed in the upper Appalachicola River, the upper and middle Chattahoochee River, and the middle Flint River (Natureserve, 2001e). The impoundment of 15 reservoirs (including Lake Lanier), however, has eliminated bluestripe shiner habitat because the species cannot

tolerate lentic (nonflowing) conditions. Endangered and threatened species, therefore, are not expected to play a significant role in limiting dock development at the lake.

Cultural and Historic Resources

Consultations with the Georgia State Historic Preservation Officer (SHPO) determined that all project lands with a high potential for historic properties have been surveyed, with the exception of isolated tracts of the upper Chattahoochee and Chestatee rivers. Six prehistoric and historic period archaeological sites exist within the project area that are eligible or potentially eligible for the National Register of Historic Places (NRHP) (Gibbens, 2002, USACE, Mobile District, personal communication; USACE, Mobile District, 1997). Three historic cemeteries, the Little Hall Cemetery, the Shockley Cemetery, and one unnamed cemetery, are also located within the fee-owned lands. No standing structures are located within the government-owned lands.

Historic sites along the shoreline of Lake Lanier could be affected by dock placement. To protect the resources, their locations are shown in this report. The presence of these resources could limit dock placement in some areas, and archaeological surveys specific to proposed shoreline developments (including dock-permitting) would be necessary to determine the significance of these resources to dock-permitting decisions. If sites identified as significant (eligible for the NRHP) would be adversely affected by the presence of a dock or soil disturbance, impacts would have to be mitigated through data recovery excavations or other mitigation measures, in consultation with the Georgia SHPO and the USACE, Mobile District.

Visual and Aesthetic Resources

Visual and aesthetic resources are natural resources, landforms, vegetation, and manmade structures in the environment, that generate one or more sensory reactions and evaluations by the observer, particularly with respect to pleasurable responses (Table 5). Sensory reactions are traditionally categorized as visual, auditory, and olfactory responses—sight, sound, and smell. The visual sense is so predominant in the observer's reaction and evaluation that visual resources are the focus of this section.

The visual appearance of the shoreline can affect the quality of a person's recreational experience, but the experience of the visual appearance of the shoreline is personal. Some people might seek a wilderness type of recreational experience, in which case the sight of boat docks might be offensive. Other people might prefer a developed look and appreciate or not be bothered by boat docks along the shoreline.

Table 5. Scenic Attractiveness Class Definitions.

Class A Distinctive: Areas where landform, vegetation patterns, water characteristics, and cultural features combine to provide unusual, unique, or outstanding scenic quality. These landscapes have strong positive attributes of variety, unity, vividness, mystery, intactness, order, harmony, uniqueness, pattern, and balance.


Class B Typical: Areas where landform, vegetation patterns, water characteristics, and cultural features combine to provide ordinary or common scenic quality. These landscapes have generally positive, yet common, attributes of variety, unity, vividness, mystery, intactness, order, harmony, uniqueness, pattern, and balance. Normally they would form the basic matrix within the ecological unit.

Class C Indistinctive: Areas where landform, vegetation patterns, water characteristics, and cultural land use have low scenic quality. Often water and rockform features of any consequence are missing in Class C landscapes. These landscapes have weak or missing attributes of variety, unity, vividness, mystery, intactness, order, harmony, uniqueness, pattern, and balance.

Source: USFS, 1995.

During scoping meetings held in autumn 2001 for the environmental impact statement being prepared to address operation and maintenance activities at Lake Lanier, several residents expressed the opinion that the distance allowed between boat docks should be increased to create safer boating conditions and a more pleasing visual appearance of shorelines with docks (USACE, 2001). Others were concerned about old, deteriorating docks that cause trash and aesthetic problems. A map of the lake showing areas from which docks are visible, and the number of docks visible from those areas, visually verifies that except for the central area of the southern portion of the lake (i.e., south of Browns Bridge), docks are visible from nearly all areas on the lake (Figure 7). Docks are most likely visible from many locations in this southern-central area as well, but "visibility" on the map is limited to a ¾-mile distance.

A visual assessment survey of Lake Lanier was conducted from July 10 through 13, 2001. Eighty-five locations were surveyed, 45 of which were assessed from randomly assigned locations on a boat on the lake and 40 of which were assessed from representative park, campground, road, or other vantage points on land surrounding the lake. Photographs of the lake were taken from each location and rated according to scenic attractiveness (Table 5) and scenic integrity (Table 6). As a rough indication of the impact of private boat docks on visual attractiveness and integrity, the ratings of those photographs that showed docks were compared to the ratings of all of the photographs (Table 7). Compared to the ratings for all photographs taken, the highest percentage of photographs showing boat docks rates lower on the scales for scenic attractiveness and scenic integrity. Only a small percentage of photographs showing boat docks rates higher on these scales. This pattern would be expected with respect to scenic integrity because the rating depends heavily on how altered a landscape appears, and docks would be expected to give a scene an altered look. But the pattern also holds for scenic attractiveness as well.



Existing Dock Viewsheds

Table 6. Scenic Integrity Definitions.

Very High (Unaltered): Landscapes where the valued landscape character *is* intact with only minute, if any, deviations. The existing landscape character and sense of place is expressed at the highest possible level.

High (Appears Unaltered): Landscapes where the valued landscape *appears* intact. Deviations may be present but must repeat the form, line, color, texture, and pattern common to the landscape character so completely and at such scale that they are not evident.

Moderate (Slightly Altered): Landscapes where the valued landscape *appears slightly altered*. Noticeable deviations must remain visually subordinate to the landscape character being viewed.

Low (Moderately Altered): Landscapes where the valued landscape character *appears moderately altered*. Deviations begin to dominate the valued landscape character being viewed but they borrow valued attributes such as size, shape, edge effect, and pattern of natural openings; vegetative type changes; or architectural styles outside the landscape being viewed. They should only appear as valued character outside the landscape being viewed but compatible or complimentary to the character within.

Very Low (Heavily Altered): Landscapes where the valued landscape character *appears heavily altered*. Deviations may strongly dominate the valued landscape character. They may not borrow from valued attributes such as size, shape, edge effect, and pattern of natural openings; vegetative type changes; or architectural styles within or outside the landscape being viewed.

Unacceptably Low: Landscapes where the valued landscape character being viewed *appears extremely altered*. Deviations are extremely dominant and borrow little, if any form, line, color, texture, pattern, or scale from the landscape character.

Source: USFS, 1995.

Table 7. Visual Ratings of Photographs With Views of Boat Docks.

			Somia Administration and							
			Scenic Attractiveness							
Scenic	Percent of	Distinctive		Typical			Indistinctive			
Integrity:	Photos (↓):	Fore	Middle	Back	Fore	Middle	Back	Fore	Middle	Back
Very High	0 (10)									
High	2.6 (14.5)				1					
Moderate	7.7 (13)	1					2			
Low	56.4 (34)				11	3		8		
Very Low	33.3 (28.5)				7			6		
	Percent of Photos (\rightarrow) :	2.6 (12.5)		61.5 (62)		35.9 (25.5)				

How to read this table: The columns at the right rate the scenic attractiveness of the photographs as distinctive, typical, or indistinctive. Additionally, a row below these three ratings indicates from what viewing distance the photograph was taken, foreground (fore), middle ground (middle), or background (back). The leftmost column indicates the scenic integrity of the photograph. Thus, a bold face number in the table indicates the scenic integrity rating, scenic attractiveness rating, and distance from which the photograph was taken. The number indicates how many photographs with views of boat docks had that rating.

In the second column and bottom row, the percent of photographs that showed boat docks in the scenic integrity and scenic attractiveness categories (the first number) is compared to the percent of all photographs in the categories (the number in parentheses). For instance, 2.6% of photographs showing boat docks were rated to have high scenic integrity, while 14.5% of all photographs were rated this way; 61.5% of photographs showing boat docks were rated to have typical scenic attractiveness, while 62% of all photographs were rated this way.

The ratings of scenic attractiveness depend more on the quality of an overall scene to create a sense of order, harmony, or balance. Conceivably, docks well integrated into a landscape could improve scenic attractiveness. At Lake Lanier, however, they seem to decrease scenic attractiveness.

Protecting the visual appearance of the lake is one of the duties of project staff, and controlling the placement of private boat docks around the lake is one way to accomplish that goal. Project staff want to ensure that a variety of visual experiences are available to visitors at Lake Lanier. Thus, they want to

manage the issuance of boat dock permits such that docks are not equally visible from all portions of the lake and a variety of visual experiences are available in similar types of lake settings (e.g., coves).

Summary

There are currently 8,348 private boat docks and 11 community docks on Lake Lanier. The number of additional docks that the lake could accommodate was determined under nine potential future dock-permitting scenarios. The number of boat docks that would be permitted on the lake under each scenario is presented in Table 3. Application of a 50 percent dock installation density policy per ER 1130-2-406 would reduce the number of docks on the lake compared with scenarios that do not incorporate such a policy. Other factors, such as buffer distance between docks and assumed width of dock, also affect the maximum number of docks that the lake could accommodate.

The influence of soil type, cove width, shoreline vegetation, sensitive habitats, endangered and threatened species, and cultural and historic resources on dock-permitting were also examined. Cove width was found to have the greatest potential to limit dock placement, and potentially the number of docks that could be placed in shallow coves. The other factors were not found to be limiting with respect to dock placement or the number of docks that an LDA could accommodate. In addition, the visual and aesthetic influence of docks on the lake was examined. The presence of docks was found to decrease both the scenic integrity and scenic attractiveness of an area.

Acronyms and Abbreviations

CFR Code of Federal Regulations

Corps US Army Corps of Engineers; US Army Corps of Engineers, Mobile District

EIS environmental impact statement

ER Engineer Regulation

ESRI Environmental Systems Research Institute

ft feet, foot

GIS geographic information system LDA Limited Development Area LMP Lakeshore Management Plan

mi mile

msl mean sea level

NRCS Natural Resources Conservation Service SHPO State Historic Preservation Officer SMP Shoreline Management Plan

US, U.S. United States USACE see "Corps"

USGS United States Geological Survey

References

Georgia Department of Natural Resources Environmental Protection Division (GDNR). 1997. *Chattahoochee River Basin Management Plan 1997*. Web address: http://www.dnr.state.ga.us/dnr/environ. Accessed June 26, 2001.

Georgia Natural Heritage Program (GNHP). 2001. Special Concern Species Known from within One Mile of Lake Sidney Lanier (listed by quadrangle), Dawson, Forsyth, Gwinnett, and Hall Counties, Georgia. Georgia Department of Natural Resources, Wildlife Resources Division, Social Circle, Georgia. Report generated August 2, 2001.

Gibbens, D. 2002. Personal communication. US Army Corps of Engineers, Mobile District. January 31, 2002.

Natureserve: An online encyclopedia of life. 2001a. Species Report: *Aster georgianus*. Version 1.5. Arlington, Virginia: Association for Biodiversity Information. Web address: http://www.natureserve.org. Accessed November 29, 2001.

Natureserve: An online encyclopedia of life. 2001b. Species Report: *Platanthera integrilabia*. Version 1.5. Arlington, Virginia: Association for Biodiversity Information. Web address: http://www.natureserve.org. Accessed November 29, 2001.

Rehner, R. 1988. *An Update for the Soil Survey of Gwinnett County, Georgia*. U.S. Department of Agriculture, Soil Conservation Service, Athens, Georgia.

Tucker, S.S. 2001. Letter from Sandra S. Tucker, Field Supervisor, U.S. Fish and Wildlife Service, Athens, Georgia, to Eric Dohner, Tetra Tech, Inc., Lawrenceville, Georgia. August 13, 2001.

US Army Corps of Engineers (USACE). 1985. *Study of Recreational Boating and Lakeshore Management Needs at Lake Sidney Lanier Georgia*. US Army Corps of Engineers, Mobile District.

US Army Corps of Engineers (USACE). 1987. *Updating of the Master Plan Lake Sidney Lanier, Chattahoochee River, Georgia*. Volume 1. US Army Corps of Engineers, Mobile District Office, Mobile, Alabama. June.

US Army Corps of Engineers (USACE). 1997. *Historic Properties Management Plan*. US Army Corps of Engineers, Mobile District Office, Mobile, Alabama.

- U.S. Department of Agriculture Soil Conservation Service (USDA-SCS). 1972. *Soil Survey of Dawson, Lumpkin, and White Counties, Georgia*. U.S. Department of Agriculture, Soil Conservation Service and Forest Service, Washington, DC. April.
- U.S. Department of Agriculture Soil Conservation Service (USDA-SCS). 1977. *Soil Survey of Barrow, Hall and Jackson Counties, Georgia*. U.S. Department of Agriculture, Soil Conservation Service, Washington, DC. May.
- U.S. Department of Agriculture Soil Conservation Service (USDA-SCS). 1966. *Soil Survey of Gwinnett County, Georgia*. U.S. Department of Agriculture, Soil Conservation Service, Washington, DC.

- U.S. Fish and Wildlife Service (USFWS). 1993a. Recovery Plan for Three Granite Outcrop Plant Species. U.S. Fish and Wildlife Service, Region , Jackson, Mississippi.
- U.S. Fish and Wildlife Service (USFWS). 1993b. *Michaux's Sumac Recovery Plan*. U.S. Fish and Wildlife Service, Region 5, Atlanta, Georgia.
- U.S. Forest Service (USFS). 1995. *Landscape Aesthetics: A Handbook for Scenery Management*. Agriculture Handbook No. 701. U.S. Department of Agriculture and U.S. Forest Service, Washington, DC. December.

Lake Sidney Lanier

Boat Dock Carrying Capacity Study

APPENDIX A:

Excerpts from 1988 Shoreline Management Plan and

Engineer Regulation 1130-2-406

Appendix A Excerpts from the 1988 Shoreline Management Plan and the USACE Engineer Regulation 1130-2-406

Sections of the 1988 Lake Lanier Shoreline Management Plan Pertinent to Private Boat Docks

Many sections of the 1988 Lake Lanier Shoreline Management Plan (SMP) are referenced in the body of this report. The referenced sections and others that are relevant to dock permitting are presented below verbatim. The full text of the SMP can be read on the Lake Lanier website (http://lanier.sam.usace.army.mil/Lakeshore.htm).

Section 12.5. Permit/License for Lakeshore Use

This is a permit used to authorize certain specific private use of public shoreline designated as "Limited Development." Authority to issue these permits has been delegated to the Project Manager and are issued for the purpose of recreational use only. New as well as "grandfathered" (see Section 12.5.5) facilities authorized are identified in Exhibit XIII [of the SMP].

Section 12.5.1. Eligibility Requirements

Lakeshore Use Permits may be issued in 'Limited Development' zoned areas only. The permit will be issued for a five year period. The permit may be reissued when the current term expires if the permitted facilities and uses of public land are in compliance with the conditions of the permit and CFR [Code of Federal Regulations] Title 36, part 327. Permits are not transferable.

To be eligible for a permit an applicant must have unrestricted legal access through private property to public lands that are zoned "Limited Development."

Proof of unrestricted legal access through private land adjacent to public property may be satisfied by submitting either a copy of a recorded deed or closing statement. Failure to provide proof of access will result in denial of a permit.

Property owners may establish an association for a jointly owned facility on public land where private lands provide common access to public property. Such facilities are for all residents of a specific subdivision. Floating facilities authorized through associations are for courtesy use only, not for overnight storage or mooring purposes. Courtesy docks may not exceed 192 square feet.

Only one permit will be issued per adjacent landowner. Multiple persons listed on a deed will be considered as one adjacent landowner. Only one permit will be issued per adjacent household/family membership. Permits will be issued on a first applicant basis. Permits are not issued for speculative purposes or for enhancement of private property. Permits are not

issued to persons renting private property. The permittee must be the primary user and owner of facilities permitted Permits are not issued to minors.

Permits are temporary in nature with termination dates. The issuance of a permit does not infer private ownership or rights to public lands. Structures placed on public lands via a Lakeshore Use Permit are private property on public lands authorized only for the term of the permit.

Section 12.5.2. Site Requirements

Locations selected for placement of facilities via permit must conform with the Lakeshore Management Allocation Map (Exhibit I [of the SMP]) and be located along "Limited Development" shoreline. The location and proposed facilities must not cause a safety hazard to the applicant/user or general public.

The selected site for any floating facility must be at the nearest point of shoreline to the adjacent owner's private property. Distance to the nearest point on water has no bearing on the issuance or denial of a permit. Deviations of not more than one hundred (100) feet left or right of this point may be considered if water depth or spacing is a problem. However, placement should not be made that would produce a crossing or cross-over situation; meaning that an applicant's facilities should not go beyond existing neighboring facilities. Cross-over situations cause community discord and therefore, should be avoided. Only under the most unusual situations may crossovers be approved by the Project Manager. Private property lines do not extend onto public lands and do not indicate rights or privileges to or on government property not afforded any other member of the general public; nor does adjacent land ownership guarantee privacy or imply exclusive use of public shoreline.

The proposed location for any new floating facility must provide at least a fifty (50) foot buffer area between the proposed structure and any existing facilities at 1071 MSL [MSL: feet above mean sea level]. This buffer is from the nearest point of one facility to the nearest point of a second facility.

All intended boat mooring sites will allow for five (5) feet of water under the dock at the dock's lakeside or slip end to prevent damage to boating equipment and to allow for slight water fluctuation. Sites or coves with slightly less than five (5) feet, but not less than four (4) feet of water are only suitable for platform/t-docks that do not normally accommodate vessels.

At locations selected for any floating facility the center one-third of the cove or channel must be left open for navigation. At no time may the length of any dock including any moored vessel extend into this center one-third channel at 1071 MSL. Corps policy is to regain this navigable space when considering new permits for old facilities. All new structures will be placed in such a way as to have the least impact on navigation. During periods of low water navigation channels will not be obstructed.

Permits may not be issued in "Limited Development" zoned locations where endangered species exist, at archeological sites, within historical sites, or in areas determined to be wetlands in accordance with CFR Title 33. Such locations will be rezoned to 'Protected' shoreline.'

Section 12.5.3. Floating and Landbased Facilities

The Lake Lanier Project Manager is authorized to issue Lakeshore Use Permits for floating facilities, utility rights-of-way, improved shoreline access, etc. For a complete list of the items currently authorized as well as those "grandfathered" see Exhibit XIII [of the SMP].

Section 12.5.3.1. Floating Facility Types

In accordance with ER [Engineer Regulation] 1130-2-406 [Shoreline Management at Civil Works Projects] floating facilities will be permitted for the purpose of docking or mooring a vessel for private, not commercial use. It is important to note that the permit calls for a floating facility, not fixed or suspended and the permit is issued for the purpose of boat storage and related boating apparatus only.

Private floating facilities eligible for permitting are as follows: <u>Boatdock</u>: A structure with or without roof, with or without sides/walls (completely enclosed) with a storage slip(s) for docking or mooring a vessel. Such structures will not exceed the maximum external dimensions of 32' X 32' (see Exhibit II [of the SMP]). The <u>aggregate</u> slip size will not exceed 20'(feet wide) by 28' (feet long). The maximum dimension will include any platform/deck added or constructed to the docking facility. The maximum dimension of any attached platform/deck will not exceed 192 square feet. For the purposes of determining width from length on any type of floating facility, width will always be that portion parallel to the shoreline; length will always be that portion perpendicular to the shoreline...

Section 12.5.3.4. Dock Ramps and Walkways (excerpts)

Unless otherwise approved dock walkways shall be at least four (4) feet, but not more than six (6) feet wide. Walkways less than four feet wide are not allowed due to safety considerations. ... For the purpose of determining the dimensions of an affixed or attached platform/sundeck, the four to six feet of approved walkway adjacent to the slip are not considered a portion of the affixed or attached platform/sundeck.

Floating ramps leading to docks will not be less than four (4) nor more than six (6) feet in width nor exceed forty (40) feet in length. If a land-based fixed section of walkway is approved, in conjunction with a floating approach ramp, it shall not exceed six (6) feet in width by ten (10) feet in length. Any combination of fixed and floating approach walkway shall not cumulatively exceed a total of forty (40) feet. ... All approach ramps must be floating unless otherwise approved by the Project Manager. All floating facilities must have an approach ramp. The minimum approach ramp dimension is eight (8) feet long by four (4) feet wide.

Section 12.5.3.9. Dock Anchoring

An anchorage system shall be provided which will insure secure anchoring of the floating facility taking into consideration the water depth, exposure to wave action, and wind. Shoreline trees or other natural features will not be used as anchors. To prevent stress floating facilities should be anchored perpendicular to the shoreline with anchor cables placed at 45 degree angles to the shoreline. Anchor posts with sleeves set into the lake bottom are

optional but may only be placed on two corners of the structure. A combination of cable and anchor posts with sleeves is acceptable. Anchor cables may be secured to the shoreline with metal or wooden posts, or screw augers placed so not to endanger visitors or damage vegetation. Metal anchor posts are preferred since additional grounding is afforded in case of electrical failure. ... The floating facility must be either floating or resting on the ground at all times; the structure may not be suspended on pilings.

Anchor cables may not obstruct the public's use of the shoreline or water surface. Excessive cabling is not allowed if it blocks off an area for private use. Cables exceeding 45 degree angles may require reinstallation upon inspection. Cables shall be maintained in a taut condition. Cables shall not cross those of an adjacent facility. No cable or anchoring device other than poles with sleeves will be permitted on the lake's bottom. Cables may not be lined with styrofoam or plastic jugs, etc. due to aesthetics. Floating facilities should not share the same anchor post.

Section 20. Wetlands

... To maintain wetlands, no permit will be issued that involves general or specific use or alteration of wetlands unless concurrence is gained from the Corps of Engineers, the U.S. Fish and Wildlife Service, and the State of Georgia Department of Natural Resources. ...

Section 22. Endangered Species

... Permits will not be issued that conflict with the preservation of endangered species. Any permit issued in violation of the Endangered Species Act either past or present will be rescinded....

Section 23. Cultural, Historical, and Archeological

... Permits will not be issued that involve general or specific use or alteration of historic sites unless culturally cleared by appropriate agencies. ...

Corps Regulations Pertinent to Private Boat Docks on Lake Lanier Excerpts from Engineer Regulation 1130-2-406

Engineer Regulation (ER) 1130-2-406, revised and adopted in May 1999, authorizes Lake Lanier Project Operations Manager to issue Shoreline Use Permits, which allow certain private, recreational uses of those segments of the public shoreline that have been designated *Limited Development Area*. Shoreline Use Permits are issued for 5 years. They may be reissued at the end of the permit term if the permitted facilities and uses of public land are in compliance with the conditions of the permit and the 36 CFR Title 36, part 327. Permits are not transferable. Relevant sections from ER 1130-2-406 are provided below verbatim.

Section 4. Policy

- (c). A Shoreline Management Plan ... will be prepared for each Corps project where private shoreline use is allowed. This plan will honor past written commitments. The plan will be reviewed at least once every five years and revised as necessary...
- (d). Where commercial or other public launching and/or moorage facilities are not available within a reasonable distance, group owned mooring facilities may be allowed in Limited Development Areas to limit the proliferation of individual facilities...
- (e). The issuance of a private shoreline use permit does not convey any real estate or personal property rights or exclusive use rights to the permit holder. The public's right of access and use of the permit area must be maintained and preserved. Owners of permitted facilities may take necessary precautions to protect their property from theft, vandalism or trespass, but may in no way preclude the public right of pedestrian or vessel access to the water surface or public land adjacent to the facility.
- (f). Shoreline Use Permits will only be issued to individuals or groups with legal right of access to public lands.

Section 10. Density of Development

The density of private floating recreation facilities will be established in the Shoreline Management Plan for all portions of Limited Development Areas consistent with ecological and aesthetic characteristics and prior written commitments. The facility density in Limited Development Areas should, if feasible, be determined prior to the development of adjacent private property. The density of facilities will not be more than 50 per cent of the Limited Development Area in which they are located. Density will be measured by determining the linear feet of shoreline as compared to the width of facilities plus associated moorage arrangements which restrict the full unobstructed use of that portion of the shoreline. When a Limited Development Area or a portion of a Limited Development Area reaches maximum density, notice should be given to the public and facility owners in that area that no additional facilities will be allowed. In all cases, sufficient open area will be maintained for safe maneuvering of watercraft. Docks should not extend out from the shore more than one-third of the width of a cove at normal recreation or multipurpose pool. In those cases where current density of development exceeds the density level established in the Shoreline Management Plan, the density will be reduced to the prescribed level through attrition.

Lake Sidney Lanier Boat Dock Carrying Capacity Study

APPENDIX B:

LDA Data

LDA_ID	Boundary Frontage LDA Length (ft)	Boundary Frontage LDA Total Shoreline Length (ft)	Number of Docks (in 2002)*
Total	1,997,654.8	1,868,227.4	8,593
. Otal	1,007,00110	1,000,22111	0,000
1	702.4	967.1	1
2	724.9	779.8	2
3	13,052.5	11,749.5	62
4	635.0	674.8	6
5	6,337.0	6,027.5	21
6	4,215.7	3,372.9	24
7	9,345.3	6,564.3	39
8	584.6	561.2	7
9	414.9	244.4	2
10	16,068.8	13,476.8	102
11	1,175.9	1,581.7	7
12	8,148.8	8,417.5	52
13	3,464.0	3,912.6	25
14	8,451.4	8,188.0	56
15	2,764.6	3,116.0	19
16	6,476.0	6,260.6	52
17	14,334.0	15,816.6	95
18	1,854.3	1,544.4	6
19	3,812.0	4,224.1	18
20	2,376.7	2,428.8	17
21	6,175.4	6,556.1	27
22	277.1	475.9	2
23	10,490.9	9,148.5	26
24	20,306.9	18,152.4	100
25	1,559.0	1,970.4	4
26 27	6,247.0	5,060.4	<u>38</u> 55
2 <i>1</i> 28	7,913.6	7,318.0	
29	3,188.5 3,446.8	3,202.8 3,399.7	14 17
30	7,796.6	7,503.5	53
31	115.6	240.3	
32	5,944.7	4,609.5	<u>0</u> 6
33	11,489.6	10,546.5	14
34	18,405.8	16,614.1	3
35	14,784.6	14,892.5	73
36	6,435.4	6,399.1	21
37	1,637.2	1,287.5	12
38	2,084.0	1,623.3	10
39	674.6	480.7	3
40	1,068.7	975.8	5
41	348.4	205.9	1
42	4,168.3	3,727.5	7
72	7,100.0	0,121.0	•

LDA_ID	Boundary Frontage LDA Length (ft)	Boundary Frontage LDA Total Shoreline Length (ft)	Number of Docks (in 2002)*
43	1,962.5	1,963.4	0
44	1,443.4	1,365.5	1
45	1,154.8	1,100.5	1
46	2,641.7	2,059.3	8
47	872.0	1,065.8	1
48	9,837.1	8,735.2	20
49	3,001.9	3,080.2	0
50	1,987.0	1,996.0	0
51	31,347.0	30,956.0	72
52	352.8	295.6	1
53	25,085.0	26,166.6	95
54	9,476.9	7,732.5	47
55	499.0	476.3	1
56	1,498.0	1,452.5	13
57	2,381.6	2,333.8	14
58	10,642.4	10,931.4	64
59	2,435.1	1,824.1	8
60	897.6	830.9	7
61	3,275.8	3,490.2	12
62	6,058.1	6,070.5	20
63	528.4	378.5	0
64	606.2	832.4	0
65	4,056.8	4,538.6	16
66	8,973.9	8,975.4	32
67	672.5	694.4	5
68	14,478.8	15,080.6	108
70	9,003.5	7,421.0	59
72	22,445.3	21,017.6	110
73	6,822.9	6,543.1	25
75	31,089.2	29,539.9	122
76	1,757.2	2,799.2	2
78	20,657.0	21,794.5	89
79	3,427.8	3,793.3	14
80	998.2	1,721.3	1
82	7,559.2	6,909.0	35
84	2,130.5	2,104.0	6
86	5,361.9	4,729.1	17
88	2,728.6	3,212.7	0
89	997.9	1,059.5	0
90	7,966.9	7,236.0	33
92	745.5	719.6	7
94	4,013.6	3,987.7	22
96	677.0	584.5	4
98	1,266.2	1,192.5	2 2
100	226.1	226.1	
101	2,244.6	1,354.5	12

LDA_ID	Boundary Frontage LDA Length (ft)	Boundary Frontage LDA Total Shoreline Length (ft)	Number of Docks (in 2002)*
102	967.2	899.0	0
103	527.5	527.5	1
104	22,047.2	18,550.1	103
105	2,188.3	1,826.0	4
106	3,632.6	3,238.5	3
107	1,082.3	1,325.8	0
108	5,378.7	3,695.2	21
109	1,244.0	1,053.1	0
110	1,103.2	1,101.9	1
111	5,527.0	5,365.2	25
112	2,482.2	3,278.6	15
113	10,992.9	9,926.6	29
114	6,656.5	4,962.2	34
115	1,697.5	1,559.4	9
116	2,540.1	1,936.8	8
117	1,859.9	1,777.6	0
118	150.3	186.4	2
119	428.0	717.0	
120	760.0	751.7	6
121	2,813.6	2,962.2	6
122	2,154.0	1,700.3	5
123	2,100.3	3,288.5	2
124	70.9	658.1	4
125	786.0	1,031.1	7
126	3,670.6	3,135.9	6
127	3,694.4	3,844.4	15
128	2,695.7	2,441.9	14
129	4,686.6	4,611.1	25
130	900.8	1,248.1	1
131	22.8	22.8	0
132	5,943.0	6,009.9	49
133	4,701.4	4,794.2	23
134	5,913.5	5,676.1	39
135	16,024.9	14,864.5	76
136	5,713.7	6,502.7	18
137	876.3	950.9	4
138	3,367.2	4,955.2	17
139	10,258.0	11,650.0	44
140	7,192.0	5,294.6	23
141	3,682.1	3,832.3	8
142	2,009.2	1,599.0	9
143	1,995.2	1,976.6	15
144	2,418.4	1,414.4	0
145	470.6	467.3	0
146	7,591.2	6,288.6	42
147	5,445.1	5,309.0	28

148 4,048,6 4,224,0 26 149 7,007,5 5,671,6 24 150 2,096,9 1,888,8 8 151 1,646,3 619,2 4 152 4,972,3 4,281,4 41 153 2,209,0 1,828,8 15 154 406,0 596,6 4 155 4,644,1 4,564,0 31 156 2,369,6 2,400,0 21 157 1,655,7 1,412,0 3 158 7,665,6 5,915,8 42 159 4,049,9 4,109,0 21 160 8,036,3 7,105,9 57 161 4,724,3 4,517,6 38 162 1,433,6 999,8 14 163 6,190,2 5,994,3 47 164 5,555,5 4,817,2 4 165 2,025,7 2,600,6 17 166 1,492,3 2,156,9 <th>LDA_ID</th> <th>Boundary Frontage LDA Length (ft)</th> <th>Boundary Frontage LDA Total Shoreline Length (ft)</th> <th>Number of Docks (in 2002)*</th>	LDA_ID	Boundary Frontage LDA Length (ft)	Boundary Frontage LDA Total Shoreline Length (ft)	Number of Docks (in 2002)*
150	148	4,048.6	4,224.0	26
151 1,646.3 619.2 4 152 4,972.3 4,281.4 41 153 2,209.0 1,828.8 15 154 406.0 596.6 4 155 4,644.1 4,564.0 31 156 2,369.6 2,400.0 21 157 1,655.7 1,412.0 3 158 7,665.6 5,915.8 42 159 4,049.9 4,109.0 21 160 8,036.3 7,105.9 57 161 4,724.3 4,517.6 38 162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3<	149	7,007.5	5,671.6	24
152 4,972.3 4,281.4 41 153 2,209.0 1,828.8 15 154 406.0 596.6 4 155 4,644.1 4,564.0 31 156 2,369.6 2,400.0 21 157 1,655.7 1,412.0 3 158 7,665.6 5,915.8 42 159 4,049.9 4,109.0 21 160 8,036.3 7,105.9 57 161 4,724.3 4,517.6 38 162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,1	150			8
153 2,209.0 1,828.8 15 154 406.0 596.6 4 155 4,644.1 4,564.0 31 156 2,369.6 2,400.0 21 157 1,655.7 1,412.0 3 158 7,665.6 5,915.8 42 159 4,049.9 4,109.0 21 160 8,036.3 7,105.9 57 161 4,724.3 4,517.6 38 162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,7	151	1,646.3	619.2	4
153 2,209.0 1,828.8 15 154 406.0 596.6 4 155 4,644.1 4,564.0 31 156 2,369.6 2,400.0 21 157 1,655.7 1,412.0 3 158 7,665.6 5,915.8 42 159 4,049.9 4,109.0 21 160 8,036.3 7,105.9 57 161 4,724.3 4,517.6 38 162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,7	152	4,972.3	4,281.4	41
154 406.0 596.6 4 155 4,644.1 4,564.0 31 156 2,369.6 2,400.0 21 157 1,655.7 1,412.0 3 158 7,665.6 5,915.8 42 159 4,049.9 4,109.0 21 160 8,036.3 7,105.9 57 161 4,724.3 4,517.6 38 162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17	153			15
155 4,644.1 4,564.0 31 156 2,369.6 2,400.0 21 157 1,655.7 1,412.0 3 158 7,665.6 5,915.8 42 159 4,049.9 4,109.0 21 160 8,036.3 7,105.9 57 161 4,724.3 4,517.6 38 162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6	154			4
156 2,369.6 2,400.0 21 157 1,655.7 1,412.0 3 158 7,665.6 5,915.8 42 159 4,049.9 4,109.0 21 160 8,036.3 7,105.9 57 161 4,724.3 4,517.6 38 162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5	155	4,644.1		31
157 1,655.7 1,412.0 3 158 7,665.6 5,915.8 42 159 4,049.9 4,109.0 21 160 8,036.3 7,105.9 57 161 4,724.3 4,517.6 38 162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 <	156	2,369.6		21
159 4,049.9 4,109.0 21 160 8,036.3 7,105.9 57 161 4,724.3 4,517.6 38 162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4	157	1,655.7	1,412.0	3
159 4,049.9 4,109.0 21 160 8,036.3 7,105.9 57 161 4,724.3 4,517.6 38 162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4	158	7,665.6	5,915.8	42
160 8,036.3 7,105.9 57 161 4,724.3 4,517.6 38 162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 <td< td=""><td>159</td><td></td><td></td><td>21</td></td<>	159			21
161 4,724.3 4,517.6 38 162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23				
162 1,433.6 999.8 14 163 6,190.2 5,994.3 47 164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,72				38
164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,	162			14
164 5,555.5 4,817.2 4 165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,		·		47
165 2,025.7 2,600.6 17 166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1			4,817.2	4
166 1,492.3 2,156.9 14 167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7	165			17
167 6,365.4 6,770.2 37 168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7	166		2,156.9	14
168 1,574.3 1,639.3 9 169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5	167		6,770.2	37
169 17,836.8 18,562.3 84 170 14,169.1 15,111.3 86 171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 <t< td=""><td>168</td><td></td><td>1,639.3</td><td>9</td></t<>	168		1,639.3	9
171 9,030.6 9,742.1 41 172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7	169			84
172 18,479.9 17,919.2 53 173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3	170			86
173 11,167.6 12,400.9 45 174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12 </td <td>171</td> <td>9,030.6</td> <td>9,742.1</td> <td>41</td>	171	9,030.6	9,742.1	41
174 753.5 1,006.0 7 175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 </td <td>172</td> <td>18,479.9</td> <td>17,919.2</td> <td>53</td>	172	18,479.9	17,919.2	53
175 5,350.5 6,086.0 25 176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	173	11,167.6	12,400.9	45
176 3,844.6 4,051.2 18 177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	174			7
177 1,050.4 695.9 3 178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	175	5,350.5	6,086.0	25
178 4,130.0 3,968.8 28 179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	176	3,844.6	4,051.2	18
179 922.6 844.8 9 180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	177	1,050.4	695.9	3
180 5,009.7 4,722.8 23 181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	178	4,130.0	3,968.8	28
181 1,775.2 1,426.9 15 182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	179	922.6	844.8	9
182 3,574.4 3,951.8 22 183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	180	5,009.7	4,722.8	23
183 1,868.8 1,666.8 12 184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	181	1,775.2	1,426.9	15
184 9,125.4 7,482.8 44 185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	182	3,574.4	3,951.8	22
185 7,190.4 7,523.0 42 186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	183	1,868.8	1,666.8	12
186 11,394.5 10,296.6 79 187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	184	9,125.4	7,482.8	44
187 4,124.3 3,787.6 24 188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	185	7,190.4	7,523.0	42
188 4,654.0 4,639.8 29 189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	186	11,394.5	10,296.6	79
189 2,099.6 1,799.4 9 190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	187	4,124.3	3,787.6	24
190 1,706.7 4,547.6 7 191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	188	4,654.0		29
191 1,784.4 1,880.0 3 192 1,579.6 1,586.1 12	189	2,099.6	1,799.4	
192 1,579.6 1,586.1 12	190	1,706.7	4,547.6	7
	191		1,880.0	3
193 2,736.8 2,180.7 18	192	1,579.6	1,586.1	12
	193	2,736.8	2,180.7	18

LDA_ID	Boundary Frontage LDA Length (ft)	Boundary Frontage LDA Total Shoreline Length (ft)	Number of Docks (in 2002)*
194	4,915.0	4,872.0	36
195	3,455.7	2,695.0	19
196	1,038.7	1,076.6	7
197	4,109.2	3,457.8	24
198	3,360.9	2,968.8	26
199	1,433.1	2,174.9	16
200	2,863.1	3,037.6	22
201	2,408.7	1,848.4	3
202	1,138.8	703.2	1
203	462.0	679.3	6
204	4,855.8	4,142.4	22
205	1,983.8	1,296.9	12
206	1,089.6	917.6	8
207	11,904.7	11,776.6	78
208	2,726.9	2,252.3	0
209	12,717.7	11,577.7	55
210	8,248.6	6,663.4	29
211	1,034.2	1,619.5	1
212	5,716.5	6,350.9	35
213	4,780.7	3,729.5	25
214	1,384.5	1,086.2	7
215	3,168.3	3,426.5	21
216	2,029.5	1,337.1	13
217	3,373.5	3,054.0	32
218	8,277.4	7,027.9	40
219	5,834.8	4,671.7	26
220	4,745.1	4,779.8	41
221	1,790.2	1,681.5	13
222	4,315.3	3,302.4	29
223	7,085.9	6,791.9	13
224	6,371.8	6,481.0	30
225	1,352.4	1,830.7	7
226	6,515.4	5,926.4	36
227	4,298.1	3,607.0	23
228	4,691.8	4,272.7	12
229	3,849.2	4,291.3	21
230	12,779.9	12,685.4	101
231	9,073.1	8,367.4	57
232	5,408.1	5,575.5	27
233	580.5	618.6	0
234	5,925.2	7,284.3	32
235	2,542.6	2,848.2	17
236	10,063.5	8,767.0	63
237	2,758.9	2,366.6	21
238	10,554.2	9,627.2	60
239	9,977.4	8,510.6	72

LDA_ID	Boundary Frontage LDA Length (ft)	Boundary Frontage LDA Total Shoreline Length (ft)	Number of Docks (in 2002)*
240	453.8	456.7	0
241	2,113.8	2,350.7	18
242	10,566.9	9,594.4	47
243	6,014.2	5,367.1	33
244	9,246.0	9,113.5	46
245	718.2	570.2	6
246	5,375.4	4,773.7	27
247	10,184.9	8,041.1	82
248	3,370.7	2,732.9	9
249	1,417.0	1,537.3	10
250	1,938.5	1,666.5	11
251	5,859.7	6,226.1	38
252	608.0	727.6	3
253	2,398.4	2,376.1	5
254	763.3	848.5	6
255	246.5	338.3	2
256	241.6	342.1	1
257	1,399.6	1,303.2	7
258	2,768.0	2,000.7	18
259	4,606.7	3,771.0	20
260	4,344.4	2,582.8	16
261	18,161.1	15,107.9	78
262	1,299.0	1,709.0	17
263	2,372.1	2,636.8	23
264	1,190.8	1,702.5	0
265	3,647.9	3,684.2	19
266	2,558.6	2,423.2	8
267	2,984.5	2,576.1	15
268	5,484.3	5,583.6	18
269	19,258.8	15,681.5	63
270	1,413.3	1,140.5	4
271	8,409.2	7,254.9	18
272	2,810.0	2,988.9	12
273	16,609.7	15,676.1	58
274	4,916.2	4,876.4	22
275	1,750.8	2,075.0	3
276	1,262.5	513.7	2
277	3,304.2	1,952.2	1
278	2,122.2	1,975.8	4
279	4,110.5	2,266.8	8
280	10,444.5	7,982.8	13
281	3,153.1	1,949.4	14
282	4,456.3	5,020.4	19
283	11,310.6	10,414.3	46
284	2,255.7	2,249.9	
285	1,676.2	1,238.4	9

LDA_ID	Boundary Frontage LDA Length (ft)	Boundary Frontage LDA Total Shoreline Length (ft)	Number of Docks (in 2002)*
286	830.7	877.6	8
287	920.6	1,245.2	8
288	202.7	260.8	0
289	1,717.1	1,475.8	14
290	3,682.8	3,214.2	115
291	494.9	318.5	0
292	1,435.9	2,515.1	9
293	822.1	1,109.8	2
294	2,650.6	1,882.5	7
295	3,904.6	3,902.1	14
296	8,579.3	7,678.7	52
297	942.8	535.8	4
298	24,080.0	21,235.1	65
299	4,938.6	4,169.3	30
300	6,377.1	7,211.5	5
301	3,995.9	3,829.6	24
302	1,636.9	2,266.8	0
303	4,601.6	3,942.6	22
304	1,417.5	1,425.7	3
305	14,113.8	13,157.3	59
306	8,611.3	8,508.6	40
307	7,479.4	7,079.7	22
308	2,131.9	1,242.2	2
309	4,375.1	3,044.8	7
310	6,358.8	5,326.2	22
311	1,674.4	1,746.2	5
312	4,442.1	4,573.0	17
313	9,918.1	8,482.1	45
314	2,893.5	2,367.3	6
315	2,783.3	2,525.9	15
316	4,605.4	3,656.6	17
317	1,419.5	1,261.8	9
318	686.7	495.7	4
319	2,043.6	1,522.2	0
320	8,656.2	6,346.8	28
321	2,580.1	2,753.4	17
322	4,463.1	4,478.3	18
323	3,952.8	3,774.0	19
324	1,516.8	2,564.3	5
325	1,045.0	1,561.5	5
326	12,446.8	10,296.0	34
327	1,452.0	1,316.6	1
328	899.2	788.5	2
329	14,085.7	13,173.9	<u>12</u> 4
330	3,075.5	3,389.1	
331	1,944.4	1,841.3	11

LDA_ID	Boundary Frontage LDA Length (ft)	Boundary Frontage LDA Total Shoreline Length (ft)	Number of Docks (in 2002)*
332	4,547.8	3,423.2	23
333	923.0	914.6	5
334	10,906.1	9,888.0	37
335	5,123.0	4,524.9	23
336	3,858.0	4,159.5	13
337	4,855.0	4,708.3	12
338	5,372.7	5,184.1	10
339	15,792.7	13,859.1	60
340	1,814.2	2,133.3	11
341	2,340.2	2,093.6	7
342	3,010.8	2,068.3	8
343	586.2	255.6	2
344	1,260.7	1,180.6	6
345	1,224.6	677.7	7
346	1,180.0	1,097.4	8
347	772.6	398.7	3
348	11,646.8	9,102.3	42
349	2,298.8	1,724.1	11
350	2,842.4	1,750.2	4
351	1,453.0	1,372.0	6
352	809.5	831.5	7
353	972.0	900.0	7
354	4,783.3	4,361.6	26
355	5,153.7	5,677.6	15
356	1,110.3	1,497.8	1
357	1,834.0	1,753.6	1
358	2,220.2	1,960.8	9
359	3,690.5	3,660.2	21
360	1,754.2	1,875.5	0
361	983.7	1,007.5	0
362	2,795.4	2,457.6	3
363	5,779.2	3,334.0	0
364	5,758.8	4,860.3	0
365	1,604.9	1,155.8	0
366	6,995.7	7,111.7	0
367	1,829.6	816.3	0
368	7,090.5	5,687.9	1
369	1,706.6	1,317.0	1
370	859.6	1,376.2	3
371	1,831.9	2,326.7	7
372	904.9	274.4	2
373	2,212.8	1,733.3	13
374	1,006.3	1,043.8	10
375	3,836.1	2,632.7	18
376	3,045.8	2,441.3	16
377	3,517.6	2,805.7	0

378 1,027.1 1,000.7 379 1,872.7 2,098.7 380 2,560.8 2,449.4 381 3,248.3 2,810.1 382 937.4 709.0 383 4,311.7 3,433.3
380 2,560.8 2,449.4 381 3,248.3 2,810.1 382 937.4 709.0
380 2,560.8 2,449.4 381 3,248.3 2,810.1 382 937.4 709.0
382 937.4 709.0
382 937.4 709.0
384 1,128.1 651.6
385 384.4 255.4
386 6,142.7 6,860.4 14
387 12,469.3 9,617.6 4
388 804.7 573.7
389 208.3 239.2
390 245.7 331.3
391 2,457.7 1,716.5
392 1,974.9 1,407.2
393 113.5 120.4
394 96.3 107.4
395 2,990.4 2,533.4 1
396 683.3 948.6
397 1,551.8 1,243.3
398 5,561.8 5,882.8 23
399 2,011.6 3,155.6 1
400 1,266.3 2,030.4
401 3,863.7 3,489.2 1
402 4,144.1 5,131.0
403 4,560.4 4,666.0 10
404 2,296.8 1,910.7
405 3,775.5 4,360.0
406 5,107.6 4,788.6 18
407 597.1 551.8
408 3,053.3 3,269.2
409 671.5 786.5
410 3,880.7 2,955.3 12
411 557.4 532.0
412 1,743.4 1,675.8
413 6,688.2 5,596.5 10
414 1,400.1 1,662.8 10
415 3,427.0 3,470.3 15
416 4,409.4 4,005.1
417 21,590.5 22,901.9 70
418 6,298.9 6,871.2 33
419 392.6 731.8
420 523.2 1,219.9
421 8,069.7 8,592.6 26
422 23,486.8 19,671.3 83
423 2,865.6 2,878.4

	Boundary Frontage	Boundary Frontage LDA	Number of
LDA_ID	LDA Length (ft)	Total Shoreline Length (ft)	Docks (in 2002)*
424	4,593.8	4,583.9	11
425	1,120.7	642.3	6
426	3,155.2	2,523.0	9
427	1,725.3	1,836.3	0
428	8,933.7	7,558.1	40
429	3,500.0	4,010.0	21
430	4,255.4	4,812.9	27
431	5,152.3	4,955.5	27
432	4,533.4	4,197.6	1
433	5,774.5	5,284.5	30
434	4,486.8	3,468.8	24
435	1,080.6	696.6	6
436	14,686.9	11,791.4	36
437	7,666.1	4,622.1	19
438	1,474.0	491.6	4
439	10,100.4	11,537.2	52
440	2,319.6	2,403.5	15
441	5,430.2	4,445.7	21
442	3,269.5	2,386.0	12
443	3,376.0	3,120.2	23
444	2,714.1	2,347.5	17
445	10,690.1	10,144.2	46
446	7,215.4	5,820.5	32
447	797.7	718.4	2
448	1,006.9	817.1	9
Total	1,997,654.8	1,868,227.4	8,593

^{*} Includes private dock equivalents for community docks.

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
1	8024.7	21	00027839	Hall
2	3334.8	13	00027938	Hall
3	196.1			Hall
4	235.9			Hall
5	4622.1	18	00027998	Hall
6	491.6	4	00028047	Hall
7	5262.0	19	00028138	Hall
8	253.7	1	00028131	Hall
9	5118.2	23	00028091	Hall
10	903.3	7	00028053	Hall
11	3490.2	11	00028470	Hall
12	6070.5	18	00028532	Hall
13	1109.7	4	00028595	Hall
14	1293.8	9	00028575	Hall
15	4445.7	21	00028632	Hall
16	179.5			Hall
17	2206.5	8	00028686	Hall
18	3120.2	18	00028718	Hall
19	1248.1	1	00028748	Hall
20	2347.5	17	00029020	Hall
21	7048.0	36	00029102	Hall
22	23.1			Hall
23	390.6			Hall
24	480.2			Hall
25	415.0	2	00029077	Hall
26	1787.3	6	00029040	Hall
27	4371.5	20	00029412	Hall
28	1449.1	12	00029370	Hall
29	718.4	2	00029466	Hall
30	817.1	6	00029508	Hall
31	967.1	1	00029606	Hall
32	779.8	2	00029662	Hall
33	4424.6	25	00029789	Hall
34	248.5	1	00029770	Hall
35	7076.4	33	00029696	Hall
36	674.8	4	00029955	Hall
37	6027.5	21	00030086	Hall
38	3372.9	24	00030142	Hall
39	6564.3	39	00030179	Hall
40	561.2	6	00030296	Hall
41	244.4	1	00030282	Hall
42	12753.5	92	00030555	Hall
43	1692.4	14	00030525	Hall
44	612.6	1	00030514	Hall
45	2809.4	12	00030997	Gwinnett
46	1817.2	13	00030969	Hall
47	3790.9	27	00030926	Hall
48	3912.6	25	00031041	Gwinnett
49	8188.0	56	00031096	Gwinnett
50	3138.8	18	00031187	Gwinnett

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
51	6260.6	51	00031218	Gwinnett
52	12467.4	75	00031285	Gwinnett
53	3349.2	20	00031403	Gwinnett
54	1544.4	6	00031438	Gwinnett
55	4224.1	17	00031453	Gwinnett
56	1716.6	12	00031512	Hall
57	712.2	4	00031499	Hall
58	6556.1	27	00031557	Gwinnett
59	475.9	2	00007002	Forsyth
60	719.6	6	00006974	Forsyth
61	3170.9	6	00017492	Hall
62	7260.6	23	00001953	Forsyth
63	1970.4	4	00002857	Forsyth
64	3987.7	22	00004804	Forsyth
65	5060.4	37	00007926	Forsyth
66	958.4	9	00008510	Forsyth
67	648.8	3	00009707	Dawson
68	2554.0	10	00009681	Dawson
69	3399.7	17	00010449	Dawson
70	7503.5	52	00010821	Dawson
71	584.5	2	00012292	Hall
72	3935.5	21	00013025	Hall
73	2617.8			Hall
74	5406.4	9	00013942	Hall
75	4649.1			Hall
76	10569.2	1	00014070	Hall
77	502.1			Hall
78	4108.4	16	00016568	Hall
79	856.0	4	00016548	Hall
80	1465.6	4	00016499	Hall
81	6458.4	34	00016425	Hall
82	2004.1	13	00016395	Hall
83	5869.9	16	00017971	Hall
84	232.6	1	00017967	Hall
85	296.6	3	00017961	Hall
86	1287.5	9	00017951	Hall
87	1623.3	9	00019972	Hall
88	480.7	3	00019990	Hall
89	975.8	5	00020033	Hall
90	186.4			Hall
91	205.9			Hall
92	994.2			Hall
93	2733.3	7	00022539	Hall
94	1963.4			Hall
95	1365.5	1	00022710	Hall
96	1100.5	1	00022704	Hall
97	2059.3	8	00023194	Hall
98	1223.6	1	00023342	Hall
99	2064.9	1	00023333	Hall
100	1065.8	1	00024301	Hall

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
101	8735.2	20	00024939	Hall
102	3080.2		00021000	Hall
103	1996.0			Hall
104	1263.6	3	00025104	Hall
105	1843.8	3	00025097	Hall
106	4968.0	2	00025499	Hall
107	295.6		00020100	Hall
108	1604.2	5	00026675	Hall
109	7288.4	35	00026610	Hall
110	6136.9	15	00026555	Hall
111	11137.1	37	00026458	Hall
112	188.6	<u> </u>	00020400	Hall
113	7543.9	45	00027437	Hall
114	476.3	1	00030688	Hall
115	1452.5	12	00027123	Hall
116	2333.8	13	00027123	Hall
117	17488.4	103	00002702	Forsyth
118	1824.1	8	0002702	Hall
119	830.9	7	00028988	Hall
120	659.3	2	00022969	Hall
121	378.5		00022909	Hall
122	832.4			Hall
123	3427.1	14	00024051	Hall
123	1111.5	1	00024031	Hall
125	632.2	<u></u>	00024040	Forsyth
126	708.6	·	00000040	Forsyth
127	527.5	1	00007269	Forsyth
128	18550.1	96	00007203	Dawson
129	363.4	<u>50</u>	00010161	Dawson
130	3238.5	3	00010101	Dawson
131	1325.8	<u> </u>	00010322	Hall
131	1053.1			Hall
133	1101.9	1	00015542	Hall
134	5365.2	24	00013342	Hall
135	3278.6	12	00017013	Hall
136	2301.3	2	00018023	Hall
137	4962.2	34	00019498	Hall
137	1559.4	8	00019847	Hall
139	1936.8	<u>8</u>	00019916	Hall
140	1777.6	U	00013343	Hall
140	2962.2	6	00022920	Hall
141	1700.3	5	00022920	Hall
142	490.6	<u>5</u> 1	00025237	Hall
143	1689.2	9	00025237	Hall
144	2441.9	<u>9</u> 14	00026725	Hall
145	4611.1			Hall
		25	00027390	
147	4212.8	33	00000578	Forsyth
148	6724.8	30	00004141	Forsyth
149	4955.2	17	00023146	Hall
150	9775.0	33	00002990	Forsyth

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
151	5294.6	23	00022381	Hall
152	3832.3	8	00023275	Hall
153	1599.0	8	00019232	Hall
154	1976.6	14	00022660	Hall
155	1414.4			Hall
156	467.3			Hall
157	3606.4	21	00000331	Forsyth
158	6604.9	46	00000262	Forsyth
159	275.5			Forsyth
160	443.6	3	00000247	Forsyth
161	1178.7	9	00000229	Forsyth
162	614.7	1	00000218	Forsyth
163	2318.4	14	00000188	Forsyth
164	4614.5	29	00000494	Forsyth
165	1674.1	11	00000473	Forsyth
166	1797.1	15	00000535	Forsyth
167	5309.0	28	00000635	Forsyth
168	4224.0	23	00000674	Forsyth
169	1686.7	2	00000778	Forsyth
170	329.9	1	00000777	Forsyth
171	711.3	2	00000767	Forsyth
172	2943.6	15	00000734	Forsyth
173	1888.8	8	00000935	Forsyth
174	619.2	4	00000958	Forsyth
175	1841.8	10	00000985	Forsyth
176	1641.9	20	00001028	Forsyth
177	225.1			Forsyth
178	572.5	5	00001007	Forsyth
179	1828.8	14	00001064	Forsyth
180	596.6	4	00001096	Forsyth
181	4056.0	26	00001163	Forsyth
182	508.0	4	00001152	Forsyth
183	2400.0	20	00001206	Forsyth
184	1412.0	2	00001231	Forsyth
185	7310.9	45	00001288	Forsyth
186	1934.0	4	00001272	Forsyth
187	765.1	3	00001373	Forsyth
188	460.4	2	00001362	Forsyth
189	1786.0	9	00001475	Forsyth
190	1156.3	10	00001446	Forsyth
191	2973.5	22	00001409	Forsyth
192	4109.0	21	00001497	Forsyth
193	7105.9	55	00001541	Forsyth
194	3991.2	30	00001628	Forsyth
195	526.3	5	00001616	Forsyth
196	999.8	12	00001673	Forsyth
197	4225.8	32	00001821	Forsyth
198	1929.8	15	00001790	Forsyth
199	1265.4	9	00001771	Forsyth
200	5847.5	42	00002093	Forsyth

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
201	5044.3	30	00002029	Forsyth
202	5994.3	46	00002260	Forsyth
203	5310.1	9	00002377	Forsyth
204	3383.1	1	00002469	Forsyth
205	510.0	2	00002449	Forsyth
206	924.2	1	00002431	Forsyth
207	1073.9	4	00002689	Forsyth
208	4491.2	18	00002642	Forsyth
209	2904.9	20	00002612	Forsyth
210	1161.5	6	00002596	Forsyth
211	650.3	3	00002583	Forsyth
212	4178.8	15	00002524	Forsyth
213	2600.6	16	00002882	Forsyth
214	2156.9	12	00002943	Forsyth
215	1875.0	11	00002965	Forsyth
216	6770.2	36	00003086	Forsyth
217	1639.3	9	00003154	Forsyth
218	15487.5	75	00003215	Forsyth
219	3074.7	9	00003182	Forsyth
220	1822.5	11	00003347	Forsyth
221	7270.4	41	00003450	Forsyth
222	474.5	2	00003439	Forsyth
223	577.6	1	00003426	Forsyth
224	4966.3	27	00003370	Forsyth
225	3774.2	14	00003588	Forsyth
226	5968.0	25	00003522	Forsyth
227	10572.3	19	00003763	Forsyth
228	2160.0	8	00003863	Forsyth
229	2765.7	12	00003896	Forsyth
230	1205.6	3	00003952	Forsyth
231	1215.5	7	00003930	Forsyth
232	11126.3	39	00003980	Forsyth
233	1274.6	6	00004080	Forsyth
234	8139.7	46	00004204	Forsyth
235	1006.0	7	00004420	Forsyth
236	6086.0	23	00004460	Forsyth
237	4051.2	18	00004515	Forsyth
238	428.4	2	00004616	Forsyth
239	161.9			Forsyth
240	105.5		00004070	Forsyth
241	3578.2	24	00004652	Forsyth
242	390.6	1	00004699	Forsyth
243	844.8	9	00004732	Forsyth
244	4722.8	23	00004852	Forsyth
245	1426.9	13	00004905	Forsyth
246	260.7	2	00004996	Forsyth
247	3691.1	20	00004952	Forsyth
248	1666.8	11	00005123	Forsyth
249	7482.8	43	00005148	Forsyth
250	499.4	4	00005402	Forsyth

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
251	318.8	2	00005390	Forsyth
252	6704.8	36	00005335	Forsyth
253	5073.0	37	00005408	Forsyth
254	3925.0	33	00005472	Forsyth
255	1298.5	8	00005451	Forsyth
256	3787.6	23	00005601	Forsyth
257	2519.2	12	00005690	Forsyth
258	2120.6	14	00005664	Forsyth
259	1076.6	7		Forsyth
260	722.7	1	00005855	Forsyth
261	4547.6	6	00005912	Forsyth
262	1880.0	3	00005970	Forsyth
263	1586.1	11	00005987	Forsyth
264	417.5	6	00006066	Forsyth
265	304.8	1	00006055	Forsyth
266	2180.7	18	00006097	Forsyth
267	4872.0	34	00006217	Forsyth
268	2695.0	19	00006269	Forsyth
269	1076.6	6	00006302	Forsyth
270	3457.8	22	00006313	Forsyth
271	2035.2	15	00006368	Forsyth
272	933.6	6	00006354	Forsyth
273	3037.6	20	00006445	Forsyth
274	1848.4	2	00006580	Forsyth
275	703.2	1	00006657	Forsyth
276	679.3	6	00006813	Forsyth
277	4142.4	22	00006824	Forsyth
278	1296.9	10	00006898	Forsyth
279	917.6	8	00006928	Forsyth
280	11776.6	77	00007059	Forsyth
281	2252.3			Forsyth
282	190.4			Forsyth
283	7918.8	33	00007298	Forsyth
284	3658.9	21	00007371	Forsyth
285	6663.4	29	00007450	Forsyth
286	6543.1	25	00007572	Forsyth
287	1619.5	1	00007640	Forsyth
288	6350.9	35	00007658	Forsyth
289	1355.4	8	00007752	Forsyth
290	2374.0	17	00007717	Forsyth
291	1086.2	7	00008010	Forsyth
292	3426.5	21	00008067	Forsyth
293	5498.1	11	00008225	Forsyth
294	1052.9	2	00008194	Forsyth
295	4161.0	21	00008145	Forsyth
296	864.0	5	00008131	Forsyth
297	9072.4	38	00008309	Forsyth
298	3955.8	18	00008267	Forsyth
299	11295.2	68	00008399	Forsyth
300	1070.2	10	00008566	Forsyth

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
301	266.9	2	00008584	Forsyth
302	837.8	8	00008634	Forsyth
303	1554.6	12	00008616	Forsyth
304	661.6	5	00008603	Forsyth
305	7027.9	39	00008652	Forsyth
306	4671.7	25	00008717	Forsyth
307	4779.8	40	00008790	Forsyth
308	1681.5	12	00008840	Forsyth
309	2399.1	21	00008885	Forsyth
310	903.4	6	00008874	Forsyth
311	6791.9	13	00008924	Forsyth
312	6481.0	29	00008978	Dawson
313	1830.7	7	00009462	Dawson
314	5926.4	36	00009473	Dawson
315	1601.4	5	00009558	Dawson
316	2005.6	18	00009524	Dawson
317	4272.7	12	00009586	Dawson
318	4291.3	20	00009628	Dawson
319	4434.9	31	00009757	Dawson
320	8250.4	68	00009801	Dawson
321	4966.0	30	00009928	Dawson
322	1690.9	12	00010006	Dawson
323	1710.5	14	00009982	Dawson
324	5575.5	27	00010043	Dawson
325	1462.6	3	00010040	Dawson
326	618.6	<u> </u>	00010100	Dawson
327	7284.3	32	00010205	Dawson
328	2848.2	17	00010287	Dawson
329	8767.0	63	00010207	Dawson
330	2366.6	21	00010485	Dawson
331	5356.5	29	00010403	Dawson
332	4270.7	29	00010557	Dawson
333	4583.6	42	00010337	Dawson
334	3927.0	29	00010710	Dawson
335	456.7	20	00010000	Dawson
336	2350.7	17	00010791	Dawson
337	7401.7	25	00010791	Dawson
338	2192.7	16	00010890	Dawson
339	5367.1	32	00010974	Dawson
340	9113.5	42	00010990	Dawson
341	570.2	3	00011072	Dawson
342	4773.7	26	00011234	Dawson
343	8041.1	81	00011200	Dawson
344	2732.9	9	00011340	Dawson
345	1537.3	10	00011447	Dawson
346	1666.5	8	00011497	Dawson
347	6226.1	37	00011537	Lumpkin
348	727.6	2	00011339	Hall
349	2376.1	5	00012212	Hall
350	848.5	6	00012241	Hall

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
351	338.3	2	00012274	Hall
352	342.1		00012271	Hall
353	1303.2	7	00012315	Hall
354	1499.1	12	00012342	Hall
355	501.6	3	00012330	Hall
356	3771.0	20	00012358	Hall
357	2582.8	16	00012411	Hall
358	15107.9	78	00012440	Hall
359	1709.0	15	00012741	Hall
360	2636.8	22	00012717	Hall
361	1702.5		00012702	Hall
362	1768.0			Hall
363	1031.2	1	00012935	Hall
364	3684.2	19	00012952	Hall
365	2423.2	8	00012983	Hall
366	2576.1	14	00012903	Hall
367	5583.6	18	00013130	Hall
368	15681.5	61	00013188	Hall
369	735.4	2	00013166	Hall
370	405.1		00013334	Hall
370	1991.7	6	00013410	Hall
371	7254.9	18	00013410	Hall
372	2988.9	12	00013449	Hall
373	10349.1	31	00013503	Hall
375	1085.0	2	00013516	Hall
376	3430.4	17	00013590	Hall
377	811.6	5	00013536	Hall
378	4876.4	22	00013330	Hall
379	2075.0	3	00013737	Hall
380	513.7	2	00013720	Hall
381	1952.2	1	00013790	Hall
382	1981.4	<u> </u>	00013032	Hall
383	3032.1	3	00013903	Hall
384	126.6	<u> </u>	00013903	Hall
385	1975.8	4	00013997	Hall
386	893.6	1	00013997	Hall
387	2266.8	8	00014170	Hall
388	2443.3	o 1	00014343	Hall
389	1192.9	I	00014470	Hall
390	1607.1	1	00014413	Hall
390	1809.3	<u> </u>	00014413	Hall
391	930.3	3	00014359	Hall
392	1949.4	<u>3</u> 14	00014359	Hall
393	5020.4	14 17	00014555	Hall
394	1175.4	8	00014847	Hall
395	759.4	9	00014847	Hall
396	4504.4	20	00014834	Hall
397	3975.0		00014797	Hall
399	2249.9	3	00014744	Hall
400	695.4	5	00014896	Hall

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
401	543.1	1	00014884	Hall
402	877.6	8	00014908	Hall
403	1245.2	7	00014918	Hall
404	260.8		00011010	Hall
405	295.2	2	00015001	Hall
406	1180.6	10	00014986	Hall
407	7374.0	44	00015014	Hall
408	9364.8	48	00015117	Hall
409	1838.3	9	00015092	Hall
410	7010.7	<u> </u>	00015212	Hall
411	3214.2	114	00015212	Hall
412	318.5	117	00010200	Hall
413	2515.1	9	00015469	Hall
414	1109.8	2	00015491	Hall
415	1882.5	7	00015501	Hall
416	1721.3		00015527	Hall
417	3902.1	13	00015562	Hall
418	3397.4	19	00015502	Hall
419	4281.3	31	00015580	Hall
420	535.8	3	00015300	Hall
421	19843.1	62	00015878	Hall
422	1392.0	3	00015076	Hall
423	2953.7	20	00016036	Hall
424	1215.7	8	00016109	Hall
425	3706.6	<u></u>	00016090	Hall
426	3504.9	4	00016134	Hall
427	2341.8	12	00016134	Hall
428	1487.8	9	00016247	Hall
429	2266.8	3	00010247	Hall
430	3942.6	22	00016332	Hall
430	1425.7	3	00016332	Hall
431	13157.3	59	00016655	Hall
433	5631.9	28	00016832	Hall
434	2876.7	10	00016832	Hall
434	7079.7	22	00016801	Hall
436	1242.2	2	00016973	Hall
436	6909.0	34	00016972	Hall
437	651.2	2	00017053	Hall
439	301.3	۷	00017310	Hall
440	2092.2	4	00017272	Hall
440	5326.2	22	00017272	Hall
441	5977.7	18	00017331	Hall
442	1746.2	16 5	00017524	Hall
443	4515.8	5 17	00017659	Hall
444		1 /	00017001	Hall
445	57.3	45	00017920	Hall
446	8482.1	45 6	00017829	Hall
	2367.3		00017898	
448	2525.9	14	00018049	Hall
449	3656.6	17	00018073	Hall
450	1261.8	8	00018107	Hall

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
451	495.7	3	00018129	Hall
452	2104.0	6	00018138	Hall
453	1522.2	_		Hall
454	6346.8	28	00018237	Hall
455	2753.4	16	00018348	Hall
456	4478.3	18	00018417	Hall
457	3774.0	19	00018378	Hall
458	2564.3	4	00018471	Hall
459	1561.5	2	00018516	Hall
460	10296.0	33	00018678	Hall
461	1316.6	1	00018775	Hall
462	788.5	2	00018811	Hall
463	9660.0	4	00018902	Hall
464	1490.7	3	00018821	Hall
465	2023.2	3	00018936	Hall
466	3389.1	4	00018968	Hall
467	797.6	3	00019008	Hall
468	1043.8	7	00018985	Hall
469	3423.2	22	00019013	Hall
470	914.6	5	00019048	Hall
471	9888.0	36	00019063	Hall
472	4524.9	23	00019159	Hall
473	4159.5	12	00019194	Hall
474	4366.6	11	00019261	Hall
475	341.7			Hall
476	5184.1	10	00019405	Hall
477	7625.2	26	00019430	Hall
478	13859.1	60	00019652	Hall
479	2133.3	11	00019772	Hall
480	2093.6	7	00019826	Hall
481	2068.3	8	00019899	Hall
482	255.6	1	00019986	Hall
483	1180.6	5	00020002	Hall
484	677.7	5	00020014	Hall
485	1097.4	7	00020024	Hall
486	398.7	1	00020057	Hall
487	9102.3	42	00020059	Hall
488	1029.4	6	00020282	Hall
489	694.7	5	00020277	Hall
490	1750.2	3	00020296	Hall
491	1372.0	6	00020317	Hall
492	831.5	6	00020336	Hall
493	900.0	7	00020352	Hall
494	1829.6	5	00020400	Hall
495	1902.0	7	00020376	Hall
496	997.5	3	00020364	Hall
497	1665.2	8	00020490	Hall
498	2696.4	15	00020462	Hall
499	5677.6	14	00020506	Hall
500	1497.8	1	00020550	Hall

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
501	1753.6	1	00020570	Hall
502	1960.8	9	00020576	Hall
503	3660.2	21	00020618	Hall
504	1875.5		00020010	Hall
505	1007.5			Hall
506	2457.6	3	00020716	Hall
507	3334.0	<u> </u>	00020710	Hall
508	4860.3			Hall
509	1155.8			Hall
510	5789.1			Hall
511	1322.7			Hall
512	816.3			Hall
513	1268.2			Hall
514	3004.0			Hall
515	5687.9	1	00022293	Hall
516	1317.0	<u>'</u> 1	00022300	Hall
517	1376.2	2	00022300	Hall
518	2326.7	7	00022319	Hall
519	274.4		00022374	Hall
520	1733.3	12	00022374	Hall
520	1043.8	10	00022463	Hall
521	2632.7	18	00022480	Hall
522	2441.3	16 15	00022460	Hall
		15	00022517	Hall
524	2805.7	4	00000000	
525	1000.7	1	00022688	Hall
526	2098.7	4	00000745	Hall
527	2449.4	1	00022745	Hall
528	2810.1	3	00022776	Hall
529	1468.7	9 7	00022784	Hall
530	709.0		00022805	Hall
531	3433.3	16	00022874	Hall
532	651.6	3	00022950	Hall
533	291.6	1	00022978	Hall
534	255.4	2	00022982	Hall
535	6860.4	14	00022995	Hall
536	3220.6	16	00023070	Hall
537	6154.1	26	00023102	Hall
538	242.9	4	00000040	Hall
539	573.7	1	00023218	Hall
540	239.2			Hall
541	331.3		00000057	Hall
542	1716.5	3	00023257	Hall
543	1407.2	8	00023352	Hall
544	120.4	4	00023383	Hall
545	107.4	4	00023415	Hall
546	2533.4	10	00023457	Hall
547	948.6	1	00023505	Hall
548	1243.3	3	00023563	Hall
549	5882.8	23	00023646	Hall
550	3155.6	11	00023687	Hall

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
551	2030.4	5	00023708	Hall
552	3489.2	17	00023742	Hall
553	7236.0	31	00023742	Hall
554	5131.0	2	00023810	Hall
555	4666.0	10	00023944	Hall
556	470.1	10	00023944	Hall
557	1440.6	ı	00023333	Hall
558	4360.0	8	00024011	Hall
559	1852.6	11	00024011	Hall
560	2749.9	7	00024007	Hall
561	186.1	ı	00024110	Hall
562	551.8	1	00024141	Hall
563	3269.2	7	00024141	Hall
564	214.1	ı	00024131	Hall
565	572.4	5	00024364	Hall
566	701.3	2	00024304	Hall
567	701.3	2	00024410	Hall
568	1550.0	8	00024410	Hall
569	532.0	3	00024581	Hall
570	1675.8	<u>3</u>		Hall
			00024615	
571	5596.5	16	00024653	Hall
572	1662.8	10	00024704	Hall
573	3470.3	15	00024724	Hall
574	4005.1	5	00024759	Hall
575	4813.8	16	00025040	Hall
576	9209.7	26	00025361	Hall
577	7102.5	11	00025285	Hall
578	3789.0	12	00025250	Hall
579	4849.0	16	00025446	Hall
580	547.3	2	00025429	Hall
581	14388.2	46	00025684	Hall
582	3227.5	8	00025647	Hall
583	5163.1	21	00025600	Hall
584	123.1	1	00025590	Hall
585	4823.1	24	00025862	Hall
586	2048.1	7	00025840	Hall
587	731.8	4	00025903	Hall
588	260.8	1	00025961	Hall
589	959.1	3	00025952	Hall
590	8592.6	28	00026047	Hall
591	4812.9	21	00026179	Hall
592	1131.0	9	00026160	Hall
593	4092.2	10	00026112	Hall
594	1891.5	13	00026288	Hall
595	6014.5	17	00026236	Hall
596	1729.3	11	00026216	Hall
597	2147.8	4	00026353	Hall
598	730.7	1	00026383	Hall
599	4583.9	11	00026404	Hall
600	642.3	5	00026762	Hall

LDA Segment	LDA Segment	Number of	Approx. Shoreline	
ID	Length (Feet)	Docks (2002)	Location Code	County
601	2523.0	9	00026819	Hall
602	1836.3			Hall
603	7558.1	40	00026871	Hall
604	4010.0	21	00026945	Hall
605	4812.9	27	00026981	Hall
606	4144.9	22	00027044	Hall
607	334.2	1	00027039	Hall
608	476.4	1	00027034	Hall
609	3715.8	1	00027261	Hall
610	481.7			Hall
611	6980.3	21	00027294	Hall
612	5284.5	30	00027514	Hall
613	1527.1	11	00027623	Hall
614	1941.7	13	00027598	Hall
615	696.6	6	00027816	Hall
616	3666.3	23	00002341	Forsyth
617	2174.9	14	00006392	Forsyth
618	696.2	4	00012642	Hall
619	38.4	10	00000370	Forsyth