

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.	
										Page 1 of 123	
CONTRACT NO.		CONTRACT TITLE			CONTRACTOR			REPORT NO.			
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC			Inland Dredging			24			
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL					DATE				
							11/15/2019				
DREDGE		NAME AND TYPE			SHIFTS PER DAY		DAYS PER WEEK				
		Kelly L - Cutter/Suction			2		7				
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS				
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL	
		24	0	3500	24	0	0	0	0	0	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)		
							0		0		
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER	
		0%	0%	0%	0%	0%	0%	0%	0%	100%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING		AFTER DREDGING				
					0		0				
RIVER/TIDE STAGE		MIN		TIME		MAX		TIME		GAGE LOCATION	
		0		00:00		0		00:00			
		MIN		TIME		MAX		TIME		GAGE DATUM	
		0		00:00		0		00:00			
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND		
		Weather Caused No Delay			0 °F / 0 °F		MI		MPH		
WORK PERFORMED					DISTRIBUTION OF WORK						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)			HR.	MIN.	
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING			0	0	
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME			0%		
TOTAL ADVANCE PREVIOUSLY		FT		0		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		0		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES			0	0	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES			0	0	
FLOATING PIPE		0		SHORE PIPE		0		SUBMERGED PIPE		0	
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		CLEARING PUMP AND PUMP LINES			0	0	
						CLEARING CUTTER AND SUCTION HEAD			0	0	
						WAITING FOR SCOWS			0	0	
						TO AND FROM WHARF OR ANCHORAGE			0	0	
						CHANGING LOCATION OF PLANT ON JOB			0	0	
CUBIC YARDS REMOVED		GROSS		CREDITED		LOSS DUE TO OPPOSING NATURAL ELEMENTS			0	0	
AMOUNT DREDGE THIS DATE		0		0		SHORE LINE AND SHORE WORK			0	0	
AMOUNT PREVIOUSLY REPORTED		0		0		WAITING FOR BOOSTER			0	0	
TOTAL AMOUNT DREDGED TO DATE		0		0		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)			0	0	
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		WAITING FOR ATTENDANT PLANT			0	0	
						PREPARATION AND MAKING UP TOW			0	0	
						TRANSFERRING PLANT BETWEEN WORKS			0	0	
COMMODITY		CONSUMED		CREDITED		LAY TIME OFF SHIFT AND SATURDAYS			0	0	
ITEM		UNIT		QUANTITY		SUNDAYS AND HOLIDAYS			0	0	
FUEL		BBL		0		FIRE DRILL			0	0	
ELECTRICITY		KW		0		MOVING OUT OF WAY OF TRAFFIC			0	0	
LUBRICANTS		GAL		0		MISCELLANEOUS (EXPLAIN IN REMARKS)			0	0	
MOB DATE		DREDGE START		DEMOB DATE		TOTAL NON-EFFECTIVE TIME			0	0	
11/15/2019		11/15/2019				PCT. OF NON-EFFECTIVE			0%		
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)			0	0	

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 2 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		1	
DREDGE		Kelly L - Cutter/Suction				DATE	
						11/15/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	00:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	00:00	CESSATION		0	0
Tender Vessel	Tiger	0	00:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	00:00	MISCELLANEOUS		24	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		24	0
Barge	Anchor 028-954	0	00:00	PERCENTAGE OF TOTAL TIME	100%		
Barge	Deck 028-951	0	00:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.	
										Page 3 of 123	
CONTRACT NO.		CONTRACT TITLE			CONTRACTOR			REPORT NO.			
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC			Inland Dredging			2			
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL					DATE				
							11/16/2019				
DREDGE		NAME AND TYPE			SHIFTS PER DAY		DAYS PER WEEK				
		Kelly L - Cutter/Suction			2		7				
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS				
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL	
		24	0	3500	24	0	0	0	0	0	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)		
							0		0		
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER	
		0%	0%	0%	0%	0%	0%	0%	0%	100%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING		AFTER DREDGING				
					0		0				
RIVER/TIDE STAGE		MIN		TIME		MAX		TIME		GAGE LOCATION	
		0		00:00		0		00:00			
		MIN		TIME		MAX		TIME		GAGE DATUM	
		0		00:00		0		00:00			
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND		
		Weather Caused No Delay			0 °F / 0 °F		MI		MPH		
WORK PERFORMED					DISTRIBUTION OF WORK						
ITEM		UNIT		QUANTITY	EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.	
AVERAGE WIDTH OF CUT		FT		0	PUMPING OR DREDGING				0	0	
TOTAL ADVANCE THIS PERIOD		FT		0	PCT OF EFFECTIVE TIME				0%		
TOTAL ADVANCE PREVIOUSLY		FT		0	BOOSTER (IN LINE)						
TOTAL ADVANCE TO DATE		FT		0	NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)						
SCOWS LOADED		NUMBER		0	HANDLING PIPE LINES				0	0	
AVERAGE LOAD PER SCOW		CY		0	HANDLING ANCHOR LINES				0	0	
FLOATING PIPE 0		SHORE PIPE 0		SUBMERGED PIPE 0	CLEARING PUMP AND PUMP LINES				0	0	
					CLEARING CUTTER AND SUCTION HEAD				0	0	
TOTAL LENGTH OF DISCHARGE PIPE		FT		0	WAITING FOR SCOWS				0	0	
					TO AND FROM WHARF OR ANCHORAGE				0	0	
CUBIC YARDS REMOVED		GROSS		CREDITED	CHANGING LOCATION OF PLANT ON JOB				0	0	
AMOUNT DREDGE THIS DATE		0		0	LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0	
AMOUNT PREVIOUSLY REPORTED		0		0	SHORE LINE AND SHORE WORK				0	0	
TOTAL AMOUNT DREDGED TO DATE		0		0	WAITING FOR BOOSTER				0	0	
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA	MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0	
					WAITING FOR ATTENDANT PLANT				0	0	
					PREPARATION AND MAKING UP TOW				0	0	
					TRANSFERRING PLANT BETWEEN WORKS				0	0	
COMMODITY		CONSUMED		CREDITED	LAY TIME OFF SHIFT AND SATURDAYS				0	0	
ITEM		UNIT		QUANTITY	SUNDAYS AND HOLIDAYS				0	0	
FUEL		BBL		0	FIRE DRILL				0	0	
ELECTRICITY		KW		0	MOVING OUT OF WAY OF TRAFFIC				0	0	
LUBRICANTS		GAL		0	MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0	
MOB DATE		DREDGE START		DEMOB DATE	TOTAL NON-EFFECTIVE TIME				0	0	
11/15/2019		11/15/2019			PCT. OF NON-EFFECTIVE				0%		
					TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				0	0	

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 4 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		2	
DREDGE		Kelly L - Cutter/Suction				DATE	
						11/16/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	00:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	00:00	CESSATION		0	0
Tender Vessel	Tiger	0	00:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	00:00	MISCELLANEOUS		24	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		24	0
Barge	Anchor 028-954	0	00:00	PERCENTAGE OF TOTAL TIME	100%		
Barge	Crane	0	00:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.			
										Page 5 of 123			
CONTRACT NO.		CONTRACT TITLE			CONTRACTOR			REPORT NO.					
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC			Inland Dredging			3					
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE		11/17/2019			
DREDGE		NAME AND TYPE				SHIFTS PER DAY		DAYS PER WEEK					
		Kelly L - Cutter/Suction				2		7					
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS						
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL			
		24	0	3500	24	0	0	0	0	0			
LOCATION/CHANNEL OF WORK													
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)				
							0		0				
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER			
		0%	0%	0%	0%	0%	0%	0%	0%	100%			
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING			AFTER DREDGING					
					0			0					
RIVER/TIDE STAGE		MIN		0	TIME	00:00	MAX		0	TIME	00:00	GAGE LOCATION	
		MIN		0	TIME	00:00	MAX		0	TIME	00:00	GAGE DATUM	
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND				
		Weather Caused No Delay			0 °F / 0 °F		MI		MPH				
WORK PERFORMED						DISTRIBUTION OF WORK							
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.		
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING				0	0		
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME				0%			
TOTAL ADVANCE PREVIOUSLY		FT		0		BOOSTER (IN LINE)							
TOTAL ADVANCE TO DATE		FT		0		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)							
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				0	0		
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				0	0		
FLOATING PIPE		0		SHORE PIPE		0		SUBMERGED PIPE		0			
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		CLEARING PUMP AND PUMP LINES				0	0		
						CLEARING CUTTER AND SUCTION HEAD				0	0		
						WAITING FOR SCOWS				0	0		
						TO AND FROM WHARF OR ANCHORAGE				0	0		
						CHANGING LOCATION OF PLANT ON JOB				0	0		
CUBIC YARDS REMOVED		GROSS		CREDITED		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0		
AMOUNT DREDGE THIS DATE		0		0		SHORE LINE AND SHORE WORK				0	0		
AMOUNT PREVIOUSLY REPORTED		0		0		WAITING FOR BOOSTER				0	0		
TOTAL AMOUNT DREDGED TO DATE		0		0		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0		
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		WAITING FOR ATTENDANT PLANT				0	0		
						PREPARATION AND MAKING UP TOW				0	0		
						TRANSFERRING PLANT BETWEEN WORKS				0	0		
COMMODITY		CONSUMED		CREDITED		LAY TIME OFF SHIFT AND SATURDAYS				0	0		
ITEM		UNIT		QUANTITY		SUNDAYS AND HOLIDAYS				0	0		
FUEL		BBL		0		FIRE DRILL				0	0		
ELECTRICITY		KW		0		MOVING OUT OF WAY OF TRAFFIC				0	0		
LUBRICANTS		GAL		0		MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0		
MOB DATE		DREDGE START		DEMOB DATE		TOTAL NON-EFFECTIVE TIME				0	0		
11/15/2019		11/15/2019				PCT. OF NON-EFFECTIVE				0%			
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				0	0		

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 6 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		3	
DREDGE		Kelly L - Cutter/Suction				DATE	
						11/17/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	00:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	00:00	CESSATION		0	0
Tender Vessel	Tiger	0	00:00	COLLISIONS		24	0
Tender Vessel	Rebel	0	00:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		24	0
Barge	Anchor 028-954	0	00:00	PERCENTAGE OF TOTAL TIME	100%		
Barge	Crane	0	00:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS	DATE	

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.	
										Page 7 of 123	
CONTRACT NO.		CONTRACT TITLE			CONTRACTOR			REPORT NO.			
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC			Inland Dredging			4			
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL					DATE		11/18/2019		
DREDGE		NAME AND TYPE				SHIFTS PER DAY		DAYS PER WEEK			
		Kelly L - Cutter/Suction				2		7			
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS				
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL	
		24	0	3500	24	0	0	0	0	0	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)		
							0		0		
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER	
		0%	0%	0%	0%	0%	0%	0%	0%	100%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING		AFTER DREDGING				
					0		0				
RIVER/TIDE STAGE		MIN		00:00		MAX		00:00		GAGE LOCATION	
		MIN		00:00		MAX		00:00		GAGE DATUM	
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND		
		Weather Caused No Delay			0 °F / 0 °F		MI		MPH		
WORK PERFORMED					DISTRIBUTION OF WORK						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING				0	0
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME				0%	
TOTAL ADVANCE PREVIOUSLY		FT		0		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		0		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				0	0
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				0	0
FLOATING PIPE		0		SHORE PIPE		0		SUBMERGED PIPE		0	
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		CLEARING PUMP AND PUMP LINES				0	0
CUBIC YARDS REMOVED		GROSS		CREDITED		CLEARING CUTTER AND SUCTION HEAD				0	0
AMOUNT DREDGE THIS DATE		0		0		WAITING FOR SCOWS				0	0
AMOUNT PREVIOUSLY REPORTED		0		0		TO AND FROM WHARF OR ANCHORAGE				0	0
TOTAL AMOUNT DREDGED TO DATE		0		0		CHANGING LOCATION OF PLANT ON JOB				0	0
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0
OPERATING SUPPLIES						SHORE LINE AND SHORE WORK				0	0
COMMODITY		CONSUMED		CREDITED		WAITING FOR BOOSTER				0	0
ITEM		UNIT		QUANTITY		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0
FUEL		BBL		0		WAITING FOR ATTENDANT PLANT				0	0
ELECTRICITY		KW		0		PREPARATION AND MAKING UP TOW				0	0
LUBRICANTS		GAL		0		TRANSFERRING PLANT BETWEEN WORKS				0	0
MOB DATE		DREDGE START		DEMOB DATE		LAY TIME OFF SHIFT AND SATURDAYS				0	0
11/15/2019		11/15/2019				SUNDAYS AND HOLIDAYS				0	0
						FIRE DRILL				0	0
						MOVING OUT OF WAY OF TRAFFIC				0	0
						MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0
						TOTAL NON-EFFECTIVE TIME				0	0
						PCT. OF NON-EFFECTIVE				0%	
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				0	0

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 8 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		4	
DREDGE		Kelly L - Cutter/Suction				DATE	
						11/18/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	00:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	00:00	CESSATION		0	0
Tender Vessel	Tiger	0	00:00	COLLISIONS		24	0
Tender Vessel	Rebel	0	00:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		24	0
Barge	Anchor 028-954	0	00:00	PERCENTAGE OF TOTAL TIME	100%		
Barge	Crane	0	00:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS	DATE	

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.							
										Page 9 of 123							
CONTRACT NO.		CONTRACT TITLE			CONTRACTOR			REPORT NO.									
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC			Inland Dredging			5									
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE		11/19/2019							
DREDGE		NAME AND TYPE				SHIFTS PER DAY		DAYS PER WEEK									
		Kelly L - Cutter/Suction				2		7									
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS										
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL							
		24	0	3500	24	0	0	0	0	0							
LOCATION/CHANNEL OF WORK																	
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)								
		Mile 0 on the Mobile River					0		0								
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER							
		0%	0%	0%	0%	0%	0%	0%	0%	100%							
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING			AFTER DREDGING									
					0			0									
RIVER/TIDE STAGE		MIN	0	TIME	00:00	MAX	0	TIME	00:00	GAGE LOCATION							
		MIN	0	TIME	00:00	MAX	0	TIME	00:00	GAGE DATUM							
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND								
		Weather Caused No Delay			0 °F / 0 °F		MI		MPH								
WORK PERFORMED						DISTRIBUTION OF WORK											
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.		MIN.					
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING				0		0					
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME				0%							
TOTAL ADVANCE PREVIOUSLY		FT		0		BOOSTER (IN LINE)											
TOTAL ADVANCE TO DATE		FT		0		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)											
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				0		0					
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				0		0					
FLOATING PIPE		0		SHORE PIPE		0		SUBMERGED PIPE		0		CLEARING PUMP AND PUMP LINES		0		0	
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		CLEARING CUTTER AND SUCTION HEAD				0		0					
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS				0		0					
AMOUNT DREDGE THIS DATE		0		0		TO AND FROM WHARF OR ANCHORAGE				0		0					
AMOUNT PREVIOUSLY REPORTED		0		0		CHANGING LOCATION OF PLANT ON JOB				0		0					
TOTAL AMOUNT DREDGED TO DATE		0		0		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0		0					
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		SHORE LINE AND SHORE WORK				0		0					
OPERATING SUPPLIES						WAITING FOR BOOSTER				0		0					
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0		0					
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT				0		0					
FUEL		BBL		0		PREPARATION AND MAKING UP TOW				0		0					
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS				0		0					
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS				0		0					
MOB DATE		11/15/2019		DREDGE START		11/15/2019		DEMOB DATE				SUNDAYS AND HOLIDAYS		0		0	
												FIRE DRILL		0		0	
												MOVING OUT OF WAY OF TRAFFIC		0		0	
												MISCELLANEOUS (EXPLAIN IN REMARKS)		0		0	
												TOTAL NON-EFFECTIVE TIME		0		0	
												PCT. OF NON-EFFECTIVE		0%			
												TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)		0		0	

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 10 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		5	
DREDGE		Kelly L - Cutter/Suction				DATE	
						11/19/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Tender Vessel	Rebel	0	12:00	MAJOR REPAIRS		0	0
Dredge	Kelly L	3600	12:00	CESSATION		0	0
Tender Vessel	Mr. Gus	0	12:00	COLLISIONS		24	0
Tender Vessel	Tiger	0	12:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	12:00	TOTAL LOST TIME		24	0
Barge	Anchor 028-954	0	12:00	PERCENTAGE OF TOTAL TIME	100%		
Barge	Crane	0	12:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS	DATE	

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 6	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 11/20/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL												
24					0		3500		24		0		0		0		0		0												
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION					DISPOSAL AREA USED					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 0													
CHARACTER OF MATERIAL (%)					GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%										
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																		
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 0 °F / 0 °F		VISIBILITY MI		WIND MPH																	
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)							HR.	MIN.													
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING							0	0													
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME					0%																
TOTAL ADVANCE PREVIOUSLY			FT			0				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			0				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES							0	0													
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES							0	0													
FLOATING PIPE			0			SHORE PIPE				0				SUBMERGED PIPE				0													
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				CLEARING PUMP AND PUMP LINES							0	0													
										CLEARING CUTTER AND SUCTION HEAD							0	0													
										WAITING FOR SCOWS							0	0													
										TO AND FROM WHARF OR ANCHORAGE							0	0													
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB							0	0													
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS							0	0													
AMOUNT PREVIOUSLY REPORTED			0			0				SHORE LINE AND SHORE WORK							0	0													
TOTAL AMOUNT DREDGED TO DATE			0			0				WAITING FOR BOOSTER							0	0													
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)							0	0													
										WAITING FOR ATTENDANT PLANT							0	0													
										PREPARATION AND MAKING UP TOW							0	0													
										TRANSFERRING PLANT BETWEEN WORKS							0	0													
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS							0	0													
ITEM			UNIT			QUANTITY				SUNDAYS AND HOLIDAYS							0	0													
FUEL			BBL			0				FIRE DRILL							0	0													
ELECTRICITY			KW			0				MOVING OUT OF WAY OF TRAFFIC							0	0													
LUBRICANTS			GAL			0				MISCELLANEOUS (EXPLAIN IN REMARKS)							0	0													
										TOTAL NON-EFFECTIVE TIME							0	0													
MOB DATE			DREDGE START			DEMOB DATE				PCT. OF NON-EFFECTIVE					0%																
11/15/2019			11/15/2019							TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)							0	0													

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 12 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		6	
DREDGE						DATE	
Kelly L - Cutter/Suction						11/20/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
				MAJOR REPAIRS		0	0
				CESSATION		0	0
				COLLISIONS		24	0
				MISCELLANEOUS		0	0
				TOTAL LOST TIME		24	0
				PERCENTAGE OF TOTAL TIME		100%	
				TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 7	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 11/21/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL															
24		0		3500		24		0		0		0		0		0															
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION				DISPOSAL AREA USED				QTY DEPOSITED GROSS (CY) 0				CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 0															
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 0				AFTER DREDGING 0																			
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																					
WEATHER CONDITION				WEATHER Weather Caused No Delay				TEMP (min/max) 0 °F / 0 °F		VISIBILITY MI		WIND MPH																			
WORK PERFORMED									DISTRIBUTION OF WORK																						
ITEM			UNIT			QUANTITY			EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.	MIN.															
AVERAGE WIDTH OF CUT			FT			0			PUMPING OR DREDGING						0	0															
TOTAL ADVANCE THIS PERIOD			FT			0			PCT OF EFFECTIVE TIME						0%																
TOTAL ADVANCE PREVIOUSLY			FT			0			BOOSTER (IN LINE)																						
TOTAL ADVANCE TO DATE			FT			0			NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																						
SCOWS LOADED			NUMBER			0			HANDLING PIPE LINES						0	0															
AVERAGE LOAD PER SCOW			CY			0			HANDLING ANCHOR LINES						0	0															
FLOATING PIPE			0			SHORE PIPE			0			SUBMERGED PIPE			0			CLEARING PUMP AND PUMP LINES						0	0						
TOTAL LENGTH OF DISCHARGE PIPE			FT			0			CLEARING CUTTER AND SUCTION HEAD						0	0															
CUBIC YARDS REMOVED			GROSS			CREDITED			WAITING FOR SCOWS						0	0															
AMOUNT DREDGE THIS DATE			0			0			TO AND FROM WHARF OR ANCHORAGE						0	0															
AMOUNT PREVIOUSLY REPORTED			0			0			CHANGING LOCATION OF PLANT ON JOB						0	0															
TOTAL AMOUNT DREDGED TO DATE			0			0			LOSS DUE TO OPPOSING NATURAL ELEMENTS						0	0															
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA			SHORE LINE AND SHORE WORK						0	0															
OPERATING SUPPLIES									WAITING FOR BOOSTER						0	0															
COMMODITY			CONSUMED			CREDITED			MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0	0															
ITEM		UNIT	QUANTITY		QUANTITY		WAITING FOR ATTENDANT PLANT						0	0																	
FUEL		BBL	0		0		PREPARATION AND MAKING UP TOW						0	0																	
ELECTRICITY		KW	0		0		TRANSFERRING PLANT BETWEEN WORKS						0	0																	
LUBRICANTS		GAL	0		0		LAY TIME OFF SHIFT AND SATURDAYS						0	0																	
MOB DATE			DREDGE START			DEMOB DATE			SUNDAYS AND HOLIDAYS						0	0															
11/15/2019			11/15/2019						FIRE DRILL						0	0															
									MOVING OUT OF WAY OF TRAFFIC						0	0															
									MISCELLANEOUS (EXPLAIN IN REMARKS)						0	0															
									TOTAL NON-EFFECTIVE TIME						0	0															
									PCT. OF NON-EFFECTIVE						0%																
									TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						0	0															

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO. Page 14 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC		CONTRACTOR Inland Dredging		REPORT NO. 7
DREDGE		Kelly L - Cutter/Suction				DATE 11/21/2019
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)		
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN
				MAJOR REPAIRS	0	0
				CESSATION	0	0
				COLLISIONS	0	0
				MISCELLANEOUS	24	0
				TOTAL LOST TIME	24	0
				PERCENTAGE OF TOTAL TIME	100%	
				TOTAL TIME IN PERIOD	24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 8	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 11/22/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET			DREDGE		SHORE		OTHER		TOTAL											
24					0		3500		24		0			0		0		0													
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION					DISPOSAL AREA USED					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 0													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																		
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 0 °F / 0 °F		VISIBILITY MI			WIND MPH																
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.		MIN.													
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING						0		0													
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME						0%															
TOTAL ADVANCE PREVIOUSLY			FT			0				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			0				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES						0		0													
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES						0		0													
FLOATING PIPE			0			SHORE PIPE				0				SUBMERGED PIPE				0													
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				CLEARING PUMP AND PUMP LINES						0		0													
										CLEARING CUTTER AND SUCTION HEAD						0		0													
										WAITING FOR SCOWS						0		0													
										TO AND FROM WHARF OR ANCHORAGE						0		0													
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB						0		0													
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS						0		0													
AMOUNT PREVIOUSLY REPORTED			0			0				SHORE LINE AND SHORE WORK						0		0													
TOTAL AMOUNT DREDGED TO DATE			0			0				WAITING FOR BOOSTER						0		0													
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0		0													
										WAITING FOR ATTENDANT PLANT						0		0													
										PREPARATION AND MAKING UP TOW						0		0													
										TRANSFERRING PLANT BETWEEN WORKS						0		0													
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS						0		0													
ITEM		UNIT	QUANTITY		QUANTITY		SUNDAYS AND HOLIDAYS						0		0																
FUEL		BBL	0		0		FIRE DRILL						0		0																
ELECTRICITY		KW	0		0		MOVING OUT OF WAY OF TRAFFIC						0		0																
LUBRICANTS		GAL	0		0		MISCELLANEOUS (EXPLAIN IN REMARKS)						0		0																
										TOTAL NON-EFFECTIVE TIME						0		0													
MOB DATE			DREDGE START			DEMOB DATE				PCT. OF NON-EFFECTIVE						0%															
11/15/2019			11/15/2019							TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						0		0													

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 16 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		8	
DREDGE						DATE	
Kelly L - Cutter/Suction						11/22/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN	
				MAJOR REPAIRS	0	0	
				CESSATION	0	0	
				COLLISIONS	0	0	
				MISCELLANEOUS	24	0	
				TOTAL LOST TIME	24	0	
				PERCENTAGE OF TOTAL TIME	100%		
				TOTAL TIME IN PERIOD	24	0	

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS	DATE	

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 9	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 11/23/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER			NO. OF CREW MEMBERS																
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL															
24		0		3500		24		0		0		0		0		0															
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION				DISPOSAL AREA USED				QTY DEPOSITED GROSS (CY) 0				CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 0															
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 0				AFTER DREDGING 0																			
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																					
WEATHER CONDITION				WEATHER Weather Caused No Delay				TEMP (min/max) 0 °F / 0 °F		VISIBILITY MI		WIND MPH																			
WORK PERFORMED									DISTRIBUTION OF WORK																						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.		MIN.																	
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING						0		0																	
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME						0%																			
TOTAL ADVANCE PREVIOUSLY		FT		0		BOOSTER (IN LINE)																									
TOTAL ADVANCE TO DATE		FT		0		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																									
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES						0		0																	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES						0		0																	
FLOATING PIPE 0		SHORE PIPE 0		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES						0		0																	
						CLEARING CUTTER AND SUCTION HEAD						0		0																	
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		WAITING FOR SCOWS						0		0																	
						TO AND FROM WHARF OR ANCHORAGE						0		0																	
CUBIC YARDS REMOVED		GROSS		CREDITED		CHANGING LOCATION OF PLANT ON JOB						0		0																	
AMOUNT DREDGE THIS DATE		0		0		LOSS DUE TO OPPOSING NATURAL ELEMENTS						0		0																	
AMOUNT PREVIOUSLY REPORTED		0		0		SHORE LINE AND SHORE WORK						0		0																	
TOTAL AMOUNT DREDGED TO DATE		0		0		WAITING FOR BOOSTER						0		0																	
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0		0																	
						WAITING FOR ATTENDANT PLANT						0		0																	
						PREPARATION AND MAKING UP TOW						0		0																	
						TRANSFERRING PLANT BETWEEN WORKS						0		0																	
COMMODITY		CONSUMED		CREDITED		LAY TIME OFF SHIFT AND SATURDAYS						0		0																	
ITEM		UNIT		QUANTITY		QUANTITY		SUNDAYS AND HOLIDAYS						0		0															
FUEL		BBL		0		0		FIRE DRILL						0		0															
ELECTRICITY		KW		0		0		MOVING OUT OF WAY OF TRAFFIC						0		0															
LUBRICANTS		GAL		0		0		MISCELLANEOUS (EXPLAIN IN REMARKS)						0		0															
MOB DATE 11/15/2019		DREDGE START 11/15/2019		DEMOB DATE		TOTAL NON-EFFECTIVE TIME						0		0																	
						PCT. OF NON-EFFECTIVE						0%																			
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						0		0																	

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO. Page 18 of 123		
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC		CONTRACTOR Inland Dredging		REPORT NO. 9	
DREDGE		Kelly L - Cutter/Suction				DATE 11/23/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN	
				MAJOR REPAIRS	0	0	
				CESSATION	0	0	
				COLLISIONS	0	0	
				MISCELLANEOUS	24	0	
				TOTAL LOST TIME	24	0	
				PERCENTAGE OF TOTAL TIME	100%		
				TOTAL TIME IN PERIOD	24	0	

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 10	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 11/24/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL												
24					0		3500		24		0		0		0		0		0												
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION					DISPOSAL AREA USED					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 0													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																		
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 0 °F / 0 °F		VISIBILITY MI		WIND MPH																	
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)					HR.		MIN.														
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING					0		0														
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME					0%																
TOTAL ADVANCE PREVIOUSLY			FT			0				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			0				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES					0		0														
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES					0		0														
FLOATING PIPE			0			SHORE PIPE				0				SUBMERGED PIPE				0													
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				CLEARING PUMP AND PUMP LINES					0		0														
										CLEARING CUTTER AND SUCTION HEAD					0		0														
										WAITING FOR SCOWS					0		0														
										TO AND FROM WHARF OR ANCHORAGE					0		0														
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB					0		0														
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS					0		0														
AMOUNT PREVIOUSLY REPORTED			0			0				SHORE LINE AND SHORE WORK					0		0														
TOTAL AMOUNT DREDGED TO DATE			0			0				WAITING FOR BOOSTER					0		0														
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)					0		0														
										WAITING FOR ATTENDANT PLANT					0		0														
										PREPARATION AND MAKING UP TOW					0		0														
										TRANSFERRING PLANT BETWEEN WORKS					0		0														
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS					0		0														
ITEM		UNIT	QUANTITY		QUANTITY			SUNDAYS AND HOLIDAYS					0		0																
FUEL		BBL	0		0			FIRE DRILL					0		0																
ELECTRICITY		KW	0		0			MOVING OUT OF WAY OF TRAFFIC					0		0																
LUBRICANTS		GAL	0		0			MISCELLANEOUS (EXPLAIN IN REMARKS)					0		0																
										TOTAL NON-EFFECTIVE TIME					0		0														
MOB DATE			DREDGE START			DEMOB DATE				PCT. OF NON-EFFECTIVE					0%																
11/15/2019			11/15/2019							TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)					0		0														

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 20 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		10	
DREDGE		Kelly L - Cutter/Suction				DATE	
						11/24/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN	
				MAJOR REPAIRS	0	0	
				CESSATION	0	0	
				COLLISIONS	0	0	
				MISCELLANEOUS	24	0	
				TOTAL LOST TIME	24	0	
				PERCENTAGE OF TOTAL TIME	100%		
				TOTAL TIME IN PERIOD	24	0	

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS	DATE	

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.		
										Page 21 of 123		
CONTRACT NO.		CONTRACT TITLE				CONTRACTOR				REPORT NO.		
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC				Inland Dredging				11		
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE		11/25/2019		
DREDGE		NAME AND TYPE				SHIFTS PER DAY		DAYS PER WEEK				
		Kelly L - Cutter/Suction				2		7				
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS					
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL		
		24	0	3500	24	0	0	0	0	0		
LOCATION/CHANNEL OF WORK												
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)			
							0		0			
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER		
		0%	0%	0%	0%	0%	0%	0%	0%	100%		
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING			AFTER DREDGING				
					0			0				
RIVER/TIDE STAGE		MIN	0	TIME	00:00	MAX	0	TIME	00:00	GAGE LOCATION		
		MIN	0	TIME	00:00	MAX	0	TIME	00:00	GAGE DATUM		
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND			
		Weather Caused No Delay			0 °F / 0 °F		MI		MPH			
WORK PERFORMED						DISTRIBUTION OF WORK						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.	
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING				0	0	
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME			0%			
TOTAL ADVANCE PREVIOUSLY		FT		0		BOOSTER (IN LINE)						
TOTAL ADVANCE TO DATE		FT		0		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)						
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				0	0	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				0	0	
FLOATING PIPE		0	SHORE PIPE		0	CLEARING PUMP AND PUMP LINES				0	0	
			SUBMERGED PIPE		0	CLEARING CUTTER AND SUCTION HEAD				0	0	
TOTAL LENGTH OF DISCHARGE PIPE		FT <th colspan="2">0</th> <td colspan="1"></td> <th colspan="4">WAITING FOR SCOWS</th> <td colspan="1">0</td> <td colspan="1">0</td>	0			WAITING FOR SCOWS				0	0	
CUBIC YARDS REMOVED		GROSS		CREDITED		TO AND FROM WHARF OR ANCHORAGE				0	0	
AMOUNT DREDGE THIS DATE		0	0		0	CHANGING LOCATION OF PLANT ON JOB				0	0	
AMOUNT PREVIOUSLY REPORTED		0	0		0	LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0	
TOTAL AMOUNT DREDGED TO DATE		0	0		0	SHORE LINE AND SHORE WORK				0	0	
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA	NA		NA	WAITING FOR BOOSTER				0	0	
						MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0	
						WAITING FOR ATTENDANT PLANT				0	0	
						PREPARATION AND MAKING UP TOW				0	0	
						TRANSFERRING PLANT BETWEEN WORKS				0	0	
COMMODITY		CONSUMED		CREDITED		LAY TIME OFF SHIFT AND SATURDAYS				0	0	
ITEM		UNIT	QUANTITY		QUANTITY	SUNDAYS AND HOLIDAYS				0	0	
FUEL		BBL	0		0	FIRE DRILL				0	0	
ELECTRICITY		KW	0		0	MOVING OUT OF WAY OF TRAFFIC				0	0	
LUBRICANTS		GAL	0		0	MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0	
MOB DATE		11/15/2019	DREDGE START		11/15/2019	TOTAL NON-EFFECTIVE TIME				0	0	
						PCT. OF NON-EFFECTIVE			0%			
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				0	0	

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 22 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		11	
DREDGE		Kelly L - Cutter/Suction				DATE 11/25/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN	
				MAJOR REPAIRS	0	0	
				CESSATION	0	0	
				COLLISIONS	0	0	
				MISCELLANEOUS	24	0	
				TOTAL LOST TIME	24	0	
				PERCENTAGE OF TOTAL TIME	100%		
				TOTAL TIME IN PERIOD	24	0	

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.	
										Page 23 of 123	
CONTRACT NO.		CONTRACT TITLE			CONTRACTOR			REPORT NO.			
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC			Inland Dredging			12			
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL					DATE				
							11/26/2019				
DREDGE		NAME AND TYPE			SHIFTS PER DAY		DAYS PER WEEK				
		Kelly L - Cutter/Suction			2		7				
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS				
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL	
		24	0	3500	24	0	0	0	0	0	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)		
							0		0		
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER	
		0%	0%	0%	0%	0%	0%	0%	0%	100%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING		AFTER DREDGING				
					0		0				
RIVER/TIDE STAGE		MIN	0	TIME	00:00	MAX	0	TIME	00:00	GAGE LOCATION	
		MIN	0	TIME	00:00	MAX	0	TIME	00:00	GAGE DATUM	
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND		
		Weather Caused No Delay			0 °F / 0 °F		MI		MPH		
WORK PERFORMED					DISTRIBUTION OF WORK						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING				0	0
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME				0%	
TOTAL ADVANCE PREVIOUSLY		FT		0		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		0		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				0	0
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				0	0
FLOATING PIPE		0		SHORE PIPE		0		SUBMERGED PIPE		0	
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		CLEARING PUMP AND PUMP LINES				0	0
						CLEARING CUTTER AND SUCTION HEAD				0	0
						WAITING FOR SCOWS				0	0
						TO AND FROM WHARF OR ANCHORAGE				0	0
						CHANGING LOCATION OF PLANT ON JOB				0	0
CUBIC YARDS REMOVED		GROSS		CREDITED		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0
AMOUNT DREDGE THIS DATE		0		0		SHORE LINE AND SHORE WORK				0	0
AMOUNT PREVIOUSLY REPORTED		0		0		WAITING FOR BOOSTER				0	0
TOTAL AMOUNT DREDGED TO DATE		0		0		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		WAITING FOR ATTENDANT PLANT				0	0
						PREPARATION AND MAKING UP TOW				0	0
						TRANSFERRING PLANT BETWEEN WORKS				0	0
COMMODITY		CONSUMED		CREDITED		LAY TIME OFF SHIFT AND SATURDAYS				0	0
						SUNDAYS AND HOLIDAYS				0	0
ITEM		UNIT		QUANTITY		FIRE DRILL				0	0
FUEL		BBL		0		MOVING OUT OF WAY OF TRAFFIC				0	0
ELECTRICITY		KW		0		MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0
LUBRICANTS		GAL		0		TOTAL NON-EFFECTIVE TIME				0	0
MOB DATE		DREDGE START		DEMOB DATE		PCT. OF NON-EFFECTIVE				0%	
11/15/2019		11/15/2019				TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				0	0

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 24 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		12	
DREDGE		Kelly L - Cutter/Suction				DATE	
						11/26/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN	
				MAJOR REPAIRS	0	0	
				CESSATION	0	0	
				COLLISIONS	0	0	
				MISCELLANEOUS	24	0	
				TOTAL LOST TIME	24	0	
				PERCENTAGE OF TOTAL TIME	100%		
				TOTAL TIME IN PERIOD	24	0	

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS	DATE	

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 13	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 11/27/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET					DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET			DREDGE		SHORE		OTHER		TOTAL								
24					0					3500		24		0			0		0		0										
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION					DISPOSAL AREA USED					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 0													
CHARACTER OF MATERIAL (%)					GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%										
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																		
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 0 °F / 0 °F		VISIBILITY MI			WIND MPH																
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)								HR.		MIN.											
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING								0		0											
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME								0%													
TOTAL ADVANCE PREVIOUSLY			FT			0				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			0				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES								0		0											
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES								0		0											
FLOATING PIPE			0			SHORE PIPE				0				SUBMERGED PIPE				0				0		0							
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				TO AND FROM WHARF OR ANCHORAGE								0		0											
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB								0		0											
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS								0		0											
AMOUNT PREVIOUSLY REPORTED			0			0				SHORE LINE AND SHORE WORK								0		0											
TOTAL AMOUNT DREDGED TO DATE			0			0				WAITING FOR BOOSTER								0		0											
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)								0		0											
										WAITING FOR ATTENDANT PLANT								0		0											
										PREPARATION AND MAKING UP TOW								0		0											
										TRANSFERRING PLANT BETWEEN WORKS								0		0											
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS								0		0											
ITEM			UNIT			QUANTITY				QUANTITY				SUNDAYS AND HOLIDAYS				0		0											
FUEL			BBL			0				0				FIRE DRILL				0		0											
ELECTRICITY			KW			0				0				MOVING OUT OF WAY OF TRAFFIC				0		0											
LUBRICANTS			GAL			0				0				MISCELLANEOUS (EXPLAIN IN REMARKS)				0		0											
														TOTAL NON-EFFECTIVE TIME				0		0											
MOB DATE			DREDGE START			DEMOB DATE				PCT. OF NON-EFFECTIVE								0%													
11/15/2019			11/15/2019											TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				0		0											

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 26 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		13	
DREDGE		Kelly L - Cutter/Suction				DATE	
						11/27/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN	
				MAJOR REPAIRS	0	0	
				CESSATION	0	0	
				COLLISIONS	0	0	
				MISCELLANEOUS	24	0	
				TOTAL LOST TIME	24	0	
				PERCENTAGE OF TOTAL TIME	100%		
				TOTAL TIME IN PERIOD	24	0	

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS	DATE	

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.	
										Page 27 of 123	
CONTRACT NO.		CONTRACT TITLE			CONTRACTOR			REPORT NO.			
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC			Inland Dredging			14			
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL					DATE				
							11/28/2019				
DREDGE		NAME AND TYPE			SHIFTS PER DAY		DAYS PER WEEK				
		Kelly L - Cutter/Suction			2		7				
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS				
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL	
		24	0	3500	24	0	0	0	0	0	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)		
							0		0		
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER	
		0 %	0 %	0 %	0 %	0 %	0 %	0 %	0 %	100 %	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING		AFTER DREDGING				
					0		0				
RIVER/TIDE STAGE		MIN	0	TIME	00:00	MAX	0	TIME	00:00	GAGE LOCATION	
		MIN	0	TIME	00:00	MAX	0	TIME	00:00	GAGE DATUM	
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND		
		Weather Caused No Delay			0 °F / 0 °F		MI		MPH		
WORK PERFORMED					DISTRIBUTION OF WORK						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)			HR.		MIN.
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING			0		0
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME			0%		
TOTAL ADVANCE PREVIOUSLY		FT		0		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		0		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES			0		0
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES			0		0
FLOATING PIPE 0		SHORE PIPE 0		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES			0		0
						CLEARING CUTTER AND SUCTION HEAD			0		0
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		WAITING FOR SCOWS			0		0
						TO AND FROM WHARF OR ANCHORAGE			0		0
CUBIC YARDS REMOVED		GROSS		CREDITED		CHANGING LOCATION OF PLANT ON JOB			0		0
AMOUNT DREDGE THIS DATE		0		0		LOSS DUE TO OPPOSING NATURAL ELEMENTS			0		0
AMOUNT PREVIOUSLY REPORTED		0		0		SHORE LINE AND SHORE WORK			0		0
TOTAL AMOUNT DREDGED TO DATE		0		0		WAITING FOR BOOSTER			0		0
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)			0		0
						WAITING FOR ATTENDANT PLANT			0		0
						PREPARATION AND MAKING UP TOW			0		0
						TRANSFERRING PLANT BETWEEN WORKS			0		0
COMMODITY		CONSUMED		CREDITED		LAY TIME OFF SHIFT AND SATURDAYS			0		0
ITEM		UNIT		QUANTITY		SUNDAYS AND HOLIDAYS			0		0
FUEL		BBL		0		FIRE DRILL			0		0
ELECTRICITY		KW		0		MOVING OUT OF WAY OF TRAFFIC			0		0
LUBRICANTS		GAL		0		MISCELLANEOUS (EXPLAIN IN REMARKS)			0		0
MOB DATE		DREDGE START		DEMOB DATE		TOTAL NON-EFFECTIVE TIME			0		0
11/15/2019		11/15/2019				PCT. OF NON-EFFECTIVE			0%		
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)			0		0

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 28 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		14	
DREDGE		Kelly L - Cutter/Suction				DATE 11/28/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN	
				MAJOR REPAIRS	0	0	
				CESSATION	0	0	
				COLLISIONS	0	0	
				MISCELLANEOUS	24	0	
				TOTAL LOST TIME	24	0	
				PERCENTAGE OF TOTAL TIME	100%		
				TOTAL TIME IN PERIOD	24	0	

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.	
										Page 29 of 123	
CONTRACT NO.		CONTRACT TITLE			CONTRACTOR			REPORT NO.			
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC			Inland Dredging			15			
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE		11/29/2019	
DREDGE		NAME AND TYPE				SHIFTS PER DAY		DAYS PER WEEK			
		Kelly L - Cutter/Suction				2		7			
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS				
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL	
		24	0	3500	24	0	0	0	0	0	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)		
							0		0		
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER	
		0%	0%	0%	0%	0%	0%	0%	0%	100%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING			AFTER DREDGING			
					0			0			
RIVER/TIDE STAGE		MIN		TIME		MAX		TIME		GAGE LOCATION	
		0		00:00		0		00:00			
		MIN		TIME		MAX		TIME		GAGE DATUM	
		0		00:00		0		00:00			
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND		
		Weather Caused No Delay			0 °F / 0 °F		MI		MPH		
WORK PERFORMED						DISTRIBUTION OF WORK					
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING				0	0
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME				0%	
TOTAL ADVANCE PREVIOUSLY		FT		0		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		0		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				0	0
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				0	0
FLOATING PIPE		0		SHORE PIPE		0		SUBMERGED PIPE		0	
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		CLEARING PUMP AND PUMP LINES				0	0
						CLEARING CUTTER AND SUCTION HEAD				0	0
						WAITING FOR SCOWS				0	0
						TO AND FROM WHARF OR ANCHORAGE				0	0
						CHANGING LOCATION OF PLANT ON JOB				0	0
CUBIC YARDS REMOVED		GROSS		CREDITED		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0
AMOUNT DREDGE THIS DATE		0		0		SHORE LINE AND SHORE WORK				0	0
AMOUNT PREVIOUSLY REPORTED		0		0		WAITING FOR BOOSTER				0	0
TOTAL AMOUNT DREDGED TO DATE		0		0		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		WAITING FOR ATTENDANT PLANT				0	0
						PREPARATION AND MAKING UP TOW				0	0
						TRANSFERRING PLANT BETWEEN WORKS				0	0
COMMODITY		CONSUMED		CREDITED		LAY TIME OFF SHIFT AND SATURDAYS				0	0
						SUNDAYS AND HOLIDAYS				0	0
ITEM		UNIT		QUANTITY		FIRE DRILL				0	0
FUEL		BBL		0		MOVING OUT OF WAY OF TRAFFIC				0	0
ELECTRICITY		KW		0		MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0
LUBRICANTS		GAL		0		TOTAL NON-EFFECTIVE TIME				0	0
MOB DATE		DREDGE START		DEMOB DATE		PCT. OF NON-EFFECTIVE				0%	
11/15/2019		11/15/2019				TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				0	0

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 30 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		15	
DREDGE		Kelly L - Cutter/Suction				DATE	
						11/29/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN	
				MAJOR REPAIRS	0	0	
				CESSATION	0	0	
				COLLISIONS	0	0	
				MISCELLANEOUS	24	0	
				TOTAL LOST TIME	24	0	
				PERCENTAGE OF TOTAL TIME	100%		
				TOTAL TIME IN PERIOD	24	0	

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS	DATE	

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.			
										Page 31 of 123			
CONTRACT NO.		CONTRACT TITLE			CONTRACTOR			REPORT NO.					
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC			Inland Dredging			16					
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE		11/30/2019			
DREDGE		NAME AND TYPE				SHIFTS PER DAY		DAYS PER WEEK					
		Kelly L - Cutter/Suction				2		7					
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS						
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL			
		24	0	3500	24	0	0	0	0	0			
LOCATION/CHANNEL OF WORK													
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)				
							0		0				
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER			
		0%	0%	0%	0%	0%	0%	0%	0%	100%			
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING			AFTER DREDGING					
					0			0					
RIVER/TIDE STAGE		MIN	0	TIME	00:00	MAX	0	TIME	00:00	GAGE LOCATION			
		MIN	0	TIME	00:00	MAX	0	TIME	00:00	GAGE DATUM			
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND				
		Weather Caused No Delay			0 °F / 0 °F		MI		MPH				
WORK PERFORMED						DISTRIBUTION OF WORK							
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.		
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING				0	0		
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME				0%			
TOTAL ADVANCE PREVIOUSLY		FT		0		BOOSTER (IN LINE)							
TOTAL ADVANCE TO DATE		FT		0		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)							
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				0	0		
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				0	0		
FLOATING PIPE		0		SHORE PIPE		0		CLEARING PUMP AND PUMP LINES				0	0
SUBMERGED PIPE		0				CLEARING CUTTER AND SUCTION HEAD				0	0		
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		WAITING FOR SCOWS				0	0		
CUBIC YARDS REMOVED		GROSS		CREDITED		TO AND FROM WHARF OR ANCHORAGE				0	0		
AMOUNT DREDGE THIS DATE		0		0		CHANGING LOCATION OF PLANT ON JOB				0	0		
AMOUNT PREVIOUSLY REPORTED		0		0		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0		
TOTAL AMOUNT DREDGED TO DATE		0		0		SHORE LINE AND SHORE WORK				0	0		
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		WAITING FOR BOOSTER				0	0		
OPERATING SUPPLIES						MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0		
COMMODITY		CONSUMED		CREDITED		WAITING FOR ATTENDANT PLANT				0	0		
ITEM	UNIT	QUANTITY		QUANTITY		PREPARATION AND MAKING UP TOW				0	0		
FUEL	BBL	0		0		TRANSFERRING PLANT BETWEEN WORKS				0	0		
ELECTRICITY	KW	0		0		LAY TIME OFF SHIFT AND SATURDAYS				0	0		
LUBRICANTS	GAL	0		0		SUNDAYS AND HOLIDAYS				0	0		
MOB DATE	DREDGE START	DEMOB DATE				FIRE DRILL				0	0		
11/15/2019	11/15/2019					MOVING OUT OF WAY OF TRAFFIC				0	0		
						MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0		
						TOTAL NON-EFFECTIVE TIME				0	0		
						PCT. OF NON-EFFECTIVE				0%			
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				0	0		

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO. Page 32 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC		CONTRACTOR Inland Dredging		REPORT NO. 16
DREDGE		Kelly L - Cutter/Suction				DATE 11/30/2019
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)		
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN
				MAJOR REPAIRS	0	0
				CESSATION	0	0
				COLLISIONS	0	0
				MISCELLANEOUS	24	0
				TOTAL LOST TIME	24	0
				PERCENTAGE OF TOTAL TIME	100%	
				TOTAL TIME IN PERIOD	24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 17	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/01/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER			NO. OF CREW MEMBERS																
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL															
24		0		3500		24		0		0		0		0		0															
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION				DISPOSAL AREA USED				QTY DEPOSITED GROSS (CY) 0				CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 0															
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 0				AFTER DREDGING 0																			
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																					
WEATHER CONDITION				WEATHER Weather Caused No Delay				TEMP (min/max) 0 °F / 0 °F		VISIBILITY MI		WIND MPH																			
WORK PERFORMED									DISTRIBUTION OF WORK																						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.		MIN.																	
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING						0		0																	
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME						0%																			
TOTAL ADVANCE PREVIOUSLY		FT		0		BOOSTER (IN LINE)																									
TOTAL ADVANCE TO DATE		FT		0		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																									
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES						0		0																	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES						0		0																	
FLOATING PIPE		0		SHORE PIPE		0		SUBMERGED PIPE		0		CLEARING PUMP AND PUMP LINES				0		0													
												CLEARING CUTTER AND SUCTION HEAD				0		0													
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		WAITING FOR SCOWS						0		0																	
						TO AND FROM WHARF OR ANCHORAGE						0		0																	
CUBIC YARDS REMOVED		GROSS		CREDITED		CHANGING LOCATION OF PLANT ON JOB						0		0																	
AMOUNT DREDGE THIS DATE		0		0		LOSS DUE TO OPPOSING NATURAL ELEMENTS						0		0																	
AMOUNT PREVIOUSLY REPORTED		0		0		SHORE LINE AND SHORE WORK						0		0																	
TOTAL AMOUNT DREDGED TO DATE		0		0		WAITING FOR BOOSTER						0		0																	
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0		0																	
						WAITING FOR ATTENDANT PLANT						0		0																	
						PREPARATION AND MAKING UP TOW						0		0																	
						TRANSFERRING PLANT BETWEEN WORKS						0		0																	
COMMODITY		CONSUMED		CREDITED		LAY TIME OFF SHIFT AND SATURDAYS						0		0																	
ITEM		UNIT		QUANTITY		QUANTITY		SUNDAYS AND HOLIDAYS						0		0															
FUEL		BBL		0		0		FIRE DRILL						0		0															
ELECTRICITY		KW		0		0		MOVING OUT OF WAY OF TRAFFIC						0		0															
LUBRICANTS		GAL		0		0		MISCELLANEOUS (EXPLAIN IN REMARKS)						0		0															
MOB DATE		DREDGE START		DEMOB DATE		TOTAL NON-EFFECTIVE TIME						0		0																	
11/15/2019		11/15/2019				PCT. OF NON-EFFECTIVE						0%																			
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						0		0																	

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 34 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		17	
DREDGE		Kelly L - Cutter/Suction				DATE 12/01/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN	
				MAJOR REPAIRS	0	0	
				CESSATION	0	0	
				COLLISIONS	0	0	
				MISCELLANEOUS	24	0	
				TOTAL LOST TIME	24	0	
				PERCENTAGE OF TOTAL TIME	100%		
				TOTAL TIME IN PERIOD	24	0	

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 18	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/02/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER			NO. OF CREW MEMBERS																
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL															
24		0		3500		24		0		0		0		0		0															
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION				DISPOSAL AREA USED				QTY DEPOSITED GROSS (CY) 0				CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 0															
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 0				AFTER DREDGING 0																			
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																					
WEATHER CONDITION				WEATHER Weather Caused No Delay				TEMP (min/max) 0 °F / 0 °F		VISIBILITY MI		WIND MPH																			
WORK PERFORMED									DISTRIBUTION OF WORK																						
ITEM			UNIT			QUANTITY			EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.	MIN.															
AVERAGE WIDTH OF CUT			FT			0			PUMPING OR DREDGING						0	0															
TOTAL ADVANCE THIS PERIOD			FT			0			PCT OF EFFECTIVE TIME						0%																
TOTAL ADVANCE PREVIOUSLY			FT			0			BOOSTER (IN LINE)																						
TOTAL ADVANCE TO DATE			FT			0			NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																						
SCOWS LOADED			NUMBER			0			HANDLING PIPE LINES						0	0															
AVERAGE LOAD PER SCOW			CY			0			HANDLING ANCHOR LINES						0	0															
FLOATING PIPE			0			SHORE PIPE			0			SUBMERGED PIPE			0			0	0												
TOTAL LENGTH OF DISCHARGE PIPE			FT			0			WAITING FOR SCOWS						0	0															
CUBIC YARDS REMOVED			GROSS			CREDITED			TO AND FROM WHARF OR ANCHORAGE						0	0															
AMOUNT DREDGE THIS DATE			0			0			CHANGING LOCATION OF PLANT ON JOB						0	0															
AMOUNT PREVIOUSLY REPORTED			0			0			LOSS DUE TO OPPOSING NATURAL ELEMENTS						0	0															
TOTAL AMOUNT DREDGED TO DATE			0			0			SHORE LINE AND SHORE WORK						0	0															
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA			WAITING FOR BOOSTER						0	0															
OPERATING SUPPLIES									MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0	0															
COMMODITY			CONSUMED			CREDITED			WAITING FOR ATTENDANT PLANT						0	0															
ITEM		UNIT	QUANTITY		QUANTITY		PREPARATION AND MAKING UP TOW						0	0																	
FUEL		BBL	0		0		TRANSFERRING PLANT BETWEEN WORKS						0	0																	
ELECTRICITY		KW	0		0		LAY TIME OFF SHIFT AND SATURDAYS						0	0																	
LUBRICANTS		GAL	0		0		SUNDAYS AND HOLIDAYS						0	0																	
MOB DATE 11/15/2019			DREDGE START 11/15/2019			DEMOB DATE			FIRE DRILL						0	0															
									MOVING OUT OF WAY OF TRAFFIC						0	0															
									MISCELLANEOUS (EXPLAIN IN REMARKS)						0	0															
									TOTAL NON-EFFECTIVE TIME						0	0															
									PCT. OF NON-EFFECTIVE						0%																
									TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						0	0															

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO. Page 36 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC		CONTRACTOR Inland Dredging		REPORT NO. 18
DREDGE		Kelly L - Cutter/Suction				DATE 12/02/2019
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)		
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN
				MAJOR REPAIRS	0	0
				CESSATION	0	0
				COLLISIONS	0	0
				MISCELLANEOUS	24	0
				TOTAL LOST TIME	24	0
				PERCENTAGE OF TOTAL TIME	100%	
				TOTAL TIME IN PERIOD	24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 19	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/03/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER			NO. OF CREW MEMBERS																
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL															
24		0		3500		24		0		0		0		0		0															
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION				DISPOSAL AREA USED				QTY DEPOSITED GROSS (CY) 0				CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 0															
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 0				AFTER DREDGING 0																			
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																					
WEATHER CONDITION				WEATHER Weather Caused No Delay				TEMP (min/max) 0 °F / 0 °F		VISIBILITY MI		WIND MPH																			
WORK PERFORMED									DISTRIBUTION OF WORK																						
ITEM			UNIT			QUANTITY			EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.	MIN.															
AVERAGE WIDTH OF CUT			FT			0			PUMPING OR DREDGING						0	0															
TOTAL ADVANCE THIS PERIOD			FT			0			PCT OF EFFECTIVE TIME						0%																
TOTAL ADVANCE PREVIOUSLY			FT			0			BOOSTER (IN LINE)																						
TOTAL ADVANCE TO DATE			FT			0			NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																						
SCOWS LOADED			NUMBER			0			HANDLING PIPE LINES						0	0															
AVERAGE LOAD PER SCOW			CY			0			HANDLING ANCHOR LINES						0	0															
FLOATING PIPE			0			SHORE PIPE			0			SUBMERGED PIPE			0																
TOTAL LENGTH OF DISCHARGE PIPE			FT			0			CLEARING PUMP AND PUMP LINES						0	0															
									CLEARING CUTTER AND SUCTION HEAD						0	0															
									WAITING FOR SCOWS						0	0															
									TO AND FROM WHARF OR ANCHORAGE						0	0															
CUBIC YARDS REMOVED			GROSS			CREDITED			CHANGING LOCATION OF PLANT ON JOB						0	0															
AMOUNT DREDGE THIS DATE			0			0			LOSS DUE TO OPPOSING NATURAL ELEMENTS						0	0															
AMOUNT PREVIOUSLY REPORTED			0			0			SHORE LINE AND SHORE WORK						0	0															
TOTAL AMOUNT DREDGED TO DATE			0			0			WAITING FOR BOOSTER						0	0															
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA			MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0	0															
									WAITING FOR ATTENDANT PLANT						0	0															
									PREPARATION AND MAKING UP TOW						0	0															
									TRANSFERRING PLANT BETWEEN WORKS						0	0															
COMMODITY			CONSUMED			CREDITED			LAY TIME OFF SHIFT AND SATURDAYS						0	0															
ITEM		UNIT	QUANTITY		QUANTITY		SUNDAYS AND HOLIDAYS						0	0																	
FUEL		BBL	0		0		FIRE DRILL						0	0																	
ELECTRICITY		KW	0		0		MOVING OUT OF WAY OF TRAFFIC						0	0																	
LUBRICANTS		GAL	0		0		MISCELLANEOUS (EXPLAIN IN REMARKS)						0	0																	
MOB DATE			DREDGE START			DEMOB DATE			TOTAL NON-EFFECTIVE TIME						0	0															
11/15/2019			11/15/2019						PCT. OF NON-EFFECTIVE						0%																
									TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						0	0															

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 38 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		19	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/03/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
				MAJOR REPAIRS		0	0
				CESSATION		0	0
				COLLISIONS		0	0
				MISCELLANEOUS		24	0
				TOTAL LOST TIME		24	0
				PERCENTAGE OF TOTAL TIME		100%	
				TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS	DATE	

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO. Page 39 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC				CONTRACTOR Inland Dredging				REPORT NO. 20	
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE 12/04/2019			
DREDGE		NAME AND TYPE Kelly L - Cutter/Suction				SHIFTS PER DAY 2		DAYS PER WEEK 7			
		SIZE		HORSEPOWER		NO. OF CREW MEMBERS					
		PIPELINE 24	DIPPER OR BUCKET 0	DREDGE PUMP 3500	SUCTION PIPE JET 24	CUTTER OR BUCKET 0	DREDGE 31	SHORE 0	OTHER 0	TOTAL 31	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION Station 113+70 to Station 115+88			DISPOSAL AREA USED DA 64		QTY DEPOSITED GROSS (CY) 3,997		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 3,997		
CHARACTER OF MATERIAL (%)		GRAVEL 0%	SAND 20%	CLAY 0%	MUD 0%	SILT 80%	HARDPAN 0%	STONE 0%	SHELL 0%	OTHER 0%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING 7.10		AFTER DREDGING 11.50				
RIVER/TIDE STAGE		MIN 0	TIME 00:00	MAX 0	TIME 00:00	GAGE LOCATION Green Day Marker #7					
		MIN 0.50	TIME 21:00	MAX 0.80	TIME 23:00	GAGE DATUM MLLW					
WEATHER CONDITION		WEATHER Weather Caused No Delay			TEMP (min/max) 41 °F / 66 °F		VISIBILITY 5 MI		WIND NE 10 MPH		
WORK PERFORMED						DISTRIBUTION OF WORK					
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)			HR.	MIN.	
AVERAGE WIDTH OF CUT		FT		110		PUMPING OR DREDGING			4	52	
TOTAL ADVANCE THIS PERIOD		FT		218		PCT OF EFFECTIVE TIME			20%		
TOTAL ADVANCE PREVIOUSLY		FT		0		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		218		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES			0	4	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES			0	48	
FLOATING PIPE 8,110		SHORE PIPE 0		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES			0	0	
TOTAL LENGTH OF DISCHARGE PIPE		FT		8,110		CLEARING CUTTER AND SUCTION HEAD			0	0	
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS			0	0	
AMOUNT DREDGE THIS DATE		3,997		3,997		TO AND FROM WHARF OR ANCHORAGE			0	0	
AMOUNT PREVIOUSLY REPORTED		0		0		CHANGING LOCATION OF PLANT ON JOB			0	0	
TOTAL AMOUNT DREDGED TO DATE		3,997		3,997		LOSS DUE TO OPPOSING NATURAL ELEMENTS			0	0	
AMOUNT DREDGED PER PUMPING/CUTTING HR		821.30		821.30		SHORE LINE AND SHORE WORK			0	0	
OPERATING SUPPLIES						WAITING FOR BOOSTER			0	0	
						MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)			0	0	
COMMODITY						WAITING FOR ATTENDANT PLANT			0	0	
						PREPARATION AND MAKING UP TOW			0	0	
ITEM		UNIT		QUANTITY		TRANSFERRING PLANT BETWEEN WORKS			0	0	
FUEL		BBL		775		LAY TIME OFF SHIFT AND SATURDAYS			0	0	
ELECTRICITY		KW		0		SUNDAYS AND HOLIDAYS			0	0	
LUBRICANTS		GAL		0		FIRE DRILL			0	0	
MOB DATE		DREDGE START		DEMOB DATE		MOVING OUT OF WAY OF TRAFFIC			0	0	
11/15/2019		11/15/2019				MISCELLANEOUS (EXPLAIN IN REMARKS)			0	0	
						TOTAL NON-EFFECTIVE TIME			0	52	
						PCT. OF NON-EFFECTIVE			4%		
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)			5	44	

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 40 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		20	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/04/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	12:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	12:00	CESSATION		0	0
Tender Vessel	Tiger	0	12:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	12:00	MISCELLANEOUS		18	16
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		18	16
Barge	Anchor 028-954	0	12:00	PERCENTAGE OF TOTAL TIME	76%		
Barge	Crane	0	12:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS	DATE	

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO. Page 41 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC				CONTRACTOR Inland Dredging				REPORT NO. 21	
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE 12/05/2019			
DREDGE		NAME AND TYPE Kelly L - Cutter/Suction				SHIFTS PER DAY 2		DAYS PER WEEK 7			
		SIZE		HORSEPOWER		NO. OF CREW MEMBERS					
		PIPELINE 24	DIPPER OR BUCKET 0	DREDGE PUMP 3500	SUCTION PIPE JET 24	CUTTER OR BUCKET 0	DREDGE 31	SHORE 0	OTHER 0	TOTAL 31	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION Station 115+88 to Station 123+24			DISPOSAL AREA USED DA 64		QTY DEPOSITED GROSS (CY) 15,506		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 19,503		
CHARACTER OF MATERIAL (%)		GRAVEL 0%	SAND 80%	CLAY 0%	MUD 0%	SILT 20%	HARDPAN 0%	STONE 0%	SHELL 0%	OTHER 0%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING 7.10		AFTER DREDGING 11.50				
RIVER/TIDE STAGE		MIN 0.20	TIME 11:00	MAX 0.80	TIME 02:00	GAGE LOCATION Green Day Marker #7					
		MIN 0	TIME 00:00	MAX 1	TIME 23:00	GAGE DATUM MLLW					
WEATHER CONDITION		WEATHER Weather Caused No Delay			TEMP (min/max) 37 °F / 68 °F		VISIBILITY 5 MI		WIND SE 2.4 MPH		
WORK PERFORMED						DISTRIBUTION OF WORK					
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)			HR.	MIN.	
AVERAGE WIDTH OF CUT		FT		110		PUMPING OR DREDGING			17	52	
TOTAL ADVANCE THIS PERIOD		FT		736		PCT OF EFFECTIVE TIME			74%		
TOTAL ADVANCE PREVIOUSLY		FT		218		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		954		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES			1	43	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES			2	30	
FLOATING PIPE 8,670		SHORE PIPE 0		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES			0	13	
TOTAL LENGTH OF DISCHARGE PIPE		FT		8,670		CLEARING CUTTER AND SUCTION HEAD			1	1	
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS			0	0	
AMOUNT DREDGE THIS DATE		15,506		15,506		TO AND FROM WHARF OR ANCHORAGE			0	0	
AMOUNT PREVIOUSLY REPORTED		3,997		3,997		CHANGING LOCATION OF PLANT ON JOB			0	0	
TOTAL AMOUNT DREDGED TO DATE		19,503		19,503		LOSS DUE TO OPPOSING NATURAL ELEMENTS			0	0	
AMOUNT DREDGED PER PUMPING/CUTTING HR		867.87		867.87		SHORE LINE AND SHORE WORK			0	0	
OPERATING SUPPLIES						WAITING FOR BOOSTER			0	0	
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)			0	0	
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT			0	0	
FUEL		BBL		2,100		PREPARATION AND MAKING UP TOW			0	0	
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS			0	0	
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS			0	0	
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS			0	0	
11/15/2019		11/15/2019				FIRE DRILL			0	0	
						MOVING OUT OF WAY OF TRAFFIC			0	0	
						MISCELLANEOUS (EXPLAIN IN REMARKS)			0	31	
						TOTAL NON-EFFECTIVE TIME			5	58	
						PCT. OF NON-EFFECTIVE			25%		
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)			23	50	

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 42 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		21	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/05/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	10
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	10
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	1%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 22	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/06/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET					DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET			DREDGE		SHORE		OTHER		TOTAL								
24					0					3500		24		0			31		0		0	31									
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION Station 123+24 to Station 129+90					DISPOSAL AREA USED DA 64					QTY DEPOSITED GROSS (CY) 15,044			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 34,547													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 80%		CLAY 0%		MUD 0%		SILT 20%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 0%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 7.10					AFTER DREDGING 11.50																
RIVER/TIDE STAGE		MIN		0.40		TIME		12:00		MAX		1		TIME		01:00		GAGE LOCATION Green Day Marker #7													
		MIN		0		TIME		00:00		MAX		1.10		TIME		21:00		GAGE DATUM MLLW													
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 51 °F / 73 °F					VISIBILITY 5 MI			WIND SW 4.3 MPH													
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM		UNIT			QUANTITY					EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)								HR.		MIN.											
AVERAGE WIDTH OF CUT		FT			110					PUMPING OR DREDGING								15		57											
TOTAL ADVANCE THIS PERIOD		FT			666					PCT OF EFFECTIVE TIME								66%													
TOTAL ADVANCE PREVIOUSLY		FT			954					BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE		FT			1,620					NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED		NUMBER			0					HANDLING PIPE LINES								4		43											
AVERAGE LOAD PER SCOW		CY			0					HANDLING ANCHOR LINES								2		13											
FLOATING PIPE		9,070			SHORE PIPE 0					SUBMERGED PIPE 0					CLEARING PUMP AND PUMP LINES								0		55						
TOTAL LENGTH OF DISCHARGE PIPE		FT			9,070					CLEARING CUTTER AND SUCTION HEAD								0		12											
CUBIC YARDS REMOVED		GROSS			CREDITED					WAITING FOR SCOWS								0		0											
AMOUNT DREDGE THIS DATE		15,044			15,044					TO AND FROM WHARF OR ANCHORAGE								0		0											
AMOUNT PREVIOUSLY REPORTED		19,503			19,503					CHANGING LOCATION OF PLANT ON JOB								0		0											
TOTAL AMOUNT DREDGED TO DATE		34,547			34,547					LOSS DUE TO OPPOSING NATURAL ELEMENTS								0		0											
AMOUNT DREDGED PER PUMPING/CUTTING HR		943.20			943.20					SHORE LINE AND SHORE WORK								0		0											
OPERATING SUPPLIES										WAITING FOR BOOSTER								0		0											
COMMODITY										MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)								0		0											
CONSUMED					CREDITED					WAITING FOR ATTENDANT PLANT								0		0											
ITEM		UNIT		QUANTITY			QUANTITY			PREPARATION AND MAKING UP TOW								0		0											
FUEL		BBL		2,415			2,415			TRANSFERRING PLANT BETWEEN WORKS								0		0											
ELECTRICITY		KW		0			0			LAY TIME OFF SHIFT AND SATURDAYS								0		0											
LUBRICANTS		GAL		0			0			SUNDAYS AND HOLIDAYS								0		0											
MOB DATE					DREDGE START					DEMOB DATE					FIRE DRILL								0		0						
11/15/2019					11/15/2019										MOVING OUT OF WAY OF TRAFFIC								0		0						
										MISCELLANEOUS (EXPLAIN IN REMARKS)								0		0											
										TOTAL NON-EFFECTIVE TIME								8		3											
										PCT. OF NON-EFFECTIVE								34%													
										TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)								24		0											

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 44 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		22	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/06/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.				
										Page 45 of 123				
CONTRACT NO.		CONTRACT TITLE				CONTRACTOR				REPORT NO.				
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC				Inland Dredging				23				
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE		12/07/2019				
DREDGE		NAME AND TYPE				SHIFTS PER DAY		DAYS PER WEEK						
		Kelly L - Cutter/Suction				2		7						
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS							
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL				
		24	0	3500	24	0	31	0	0	31				
LOCATION/CHANNEL OF WORK														
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)					
		Station 129+90 to Station 136+38			DA 64		15,062		49,609					
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER				
		0 %	80 %	0 %	0 %	20 %	0 %	0 %	0 %	0 %				
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING		AFTER DREDGING							
					7.10		11.50							
RIVER/TIDE STAGE		MIN	0.50	TIME	09:00	MAX	1	TIME	02:00	GAGE LOCATION Green Day Marker #7				
		MIN	0	TIME	00:00	MAX	1.20	TIME	21:00	GAGE DATUM MLLW				
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND					
		Weather Caused No Delay			51 °F / 61 °F		5 MI		N 6.9 MPH					
WORK PERFORMED						DISTRIBUTION OF WORK								
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.			
AVERAGE WIDTH OF CUT		FT		110		PUMPING OR DREDGING				14	29			
TOTAL ADVANCE THIS PERIOD		FT		648		PCT OF EFFECTIVE TIME				60%				
TOTAL ADVANCE PREVIOUSLY		FT		1,620		BOOSTER (IN LINE)								
TOTAL ADVANCE TO DATE		FT		2,268		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)								
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				2	21			
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				2	59			
FLOATING PIPE		9,470	SHORE PIPE		0	CLEARING PUMP AND PUMP LINES				0	39			
SUBMERGED PIPE		0	TOTAL LENGTH OF DISCHARGE PIPE				FT		9,470		CLEARING CUTTER AND SUCTION HEAD		0	0
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS				0	0			
AMOUNT DREDGE THIS DATE		15,062		15,062		TO AND FROM WHARF OR ANCHORAGE				0	0			
AMOUNT PREVIOUSLY REPORTED		34,547		34,547		CHANGING LOCATION OF PLANT ON JOB				0	0			
TOTAL AMOUNT DREDGED TO DATE		49,609		49,609		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0			
AMOUNT DREDGED PER PUMPING/CUTTING HR		1,039.95		1,039.95		SHORE LINE AND SHORE WORK				0	0			
OPERATING SUPPLIES						WAITING FOR BOOSTER				0	0			
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				3	32			
ITEM	UNIT	QUANTITY		QUANTITY		WAITING FOR ATTENDANT PLANT				0	0			
FUEL	BBL	1,575		1,575		PREPARATION AND MAKING UP TOW				0	0			
ELECTRICITY	KW	0		0		TRANSFERRING PLANT BETWEEN WORKS				0	0			
LUBRICANTS	GAL	0		0		LAY TIME OFF SHIFT AND SATURDAYS				0	0			
MOB DATE	DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS				0	0				
11/15/2019	11/15/2019				FIRE DRILL				0	0				
						MOVING OUT OF WAY OF TRAFFIC				0	0			
						MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0			
						TOTAL NON-EFFECTIVE TIME				9	31			
						PCT. OF NON-EFFECTIVE				40%				
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				24	0			

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO.	
						Page 46 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		23	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/07/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Tender Vessel	Rebel	0	24:00	MAJOR REPAIRS		0	0
Dredge	Kelly L	3600	24:00	CESSATION		0	0
Tender Vessel	Mr. Gus	0	24:00	COLLISIONS		0	0
Tender Vessel	Tiger	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.	
										Page 47 of 123	
CONTRACT NO.		CONTRACT TITLE				CONTRACTOR				REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC				Inland Dredging				24	
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE		12/08/2019	
DREDGE		NAME AND TYPE				SHIFTS PER DAY		DAYS PER WEEK			
		Kelly L - Cutter/Suction				2		7			
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS				
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL	
		24	0	3500	24	0	31	0	0	31	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)		
		Station 136+38 to Station 143+68			DA 64		15,062		64,671		
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER	
		0 %	80 %	0 %	0 %	20 %	0 %	0 %	0 %	0 %	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING		AFTER DREDGING				
					7.10		11.50				
RIVER/TIDE STAGE		MIN	0.50	TIME	09:00	MAX	1	TIME	02:00	GAGE LOCATION Green Day Marker #7	
		MIN	0	TIME	00:00	MAX	1.20	TIME	21:00	GAGE DATUM MLLW	
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND		
		Weather Caused No Delay			52 °F / 70 °F		5 MI		E 6.4 MPH		
WORK PERFORMED						DISTRIBUTION OF WORK					
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.
AVERAGE WIDTH OF CUT		FT		110		PUMPING OR DREDGING				16	41
TOTAL ADVANCE THIS PERIOD		FT		648		PCT OF EFFECTIVE TIME				70%	
TOTAL ADVANCE PREVIOUSLY		FT		2,268		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		2,916		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				3	38
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				2	18
FLOATING PIPE 9,470		SHORE PIPE 0		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES				0	23
TOTAL LENGTH OF DISCHARGE PIPE		FT		9,470		CLEARING CUTTER AND SUCTION HEAD				0	0
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS				0	0
AMOUNT DREDGE THIS DATE		15,062		15,062		TO AND FROM WHARF OR ANCHORAGE				0	0
AMOUNT PREVIOUSLY REPORTED		49,609		49,609		CHANGING LOCATION OF PLANT ON JOB				0	0
TOTAL AMOUNT DREDGED TO DATE		64,671		64,671		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0
AMOUNT DREDGED PER PUMPING/CUTTING HR		902.82		902.82		SHORE LINE AND SHORE WORK				0	0
OPERATING SUPPLIES						WAITING FOR BOOSTER				0	0
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT				0	0
FUEL		BBL		1,575		PREPARATION AND MAKING UP TOW				0	0
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS				0	0
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS				0	0
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS				0	0
11/15/2019		11/15/2019				FIRE DRILL				0	0
						MOVING OUT OF WAY OF TRAFFIC				0	0
						MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0
						TOTAL NON-EFFECTIVE TIME				6	19
						PCT. OF NON-EFFECTIVE				26%	
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				23	0

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO. Page 48 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		24	
DREDGE		Kelly L - Cutter/Suction				DATE 12/08/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		1	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		1	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	4%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 25	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/09/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET					DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET			DREDGE		SHORE		OTHER	TOTAL									
24					0					3500		24		0			31		0		0	31									
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION Station 143+68 to Station 149+29					DISPOSAL AREA USED DA 64					QTY DEPOSITED GROSS (CY) 13,402			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 78,073													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 80%		CLAY 0%		MUD 0%		SILT 20%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 0%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 7.10					AFTER DREDGING 11.50																
RIVER/TIDE STAGE					MIN 0.60		TIME 08:00		MAX 1.30		TIME 02:00		GAGE LOCATION Green Day Marker #7																		
					MIN 0		TIME 00:00		MAX 2		TIME 21:00		GAGE DATUM MLLW																		
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 57 °F / 74 °F			VISIBILITY 5 MI			WIND S 9.2 MPH															
WORK PERFORMED											DISTRIBUTION OF WORK																				
ITEM			UNIT			QUANTITY					EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)								HR.	MIN.											
AVERAGE WIDTH OF CUT			FT			110					PUMPING OR DREDGING								12	24											
TOTAL ADVANCE THIS PERIOD			FT			561					PCT OF EFFECTIVE TIME								52%												
TOTAL ADVANCE PREVIOUSLY			FT			2,916					BOOSTER (IN LINE)																				
TOTAL ADVANCE TO DATE			FT			3,477					NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																				
SCOWS LOADED			NUMBER			0					HANDLING PIPE LINES								6	56											
AVERAGE LOAD PER SCOW			CY			0					HANDLING ANCHOR LINES								2	11											
FLOATING PIPE			10,350			SHORE PIPE			0			SUBMERGED PIPE			0			CLEARING PUMP AND PUMP LINES								0	29				
TOTAL LENGTH OF DISCHARGE PIPE			FT			10,350					CLEARING CUTTER AND SUCTION HEAD								0	0											
CUBIC YARDS REMOVED			GROSS			CREDITED					WAITING FOR SCOWS								0	0											
AMOUNT DREDGE THIS DATE			13,402			13,402					TO AND FROM WHARF OR ANCHORAGE								0	0											
AMOUNT PREVIOUSLY REPORTED			64,671			64,671					CHANGING LOCATION OF PLANT ON JOB								0	0											
TOTAL AMOUNT DREDGED TO DATE			78,073			78,073					LOSS DUE TO OPPOSING NATURAL ELEMENTS								0	0											
AMOUNT DREDGED PER PUMPING/CUTTING HR			1,080.81			1,080.81					SHORE LINE AND SHORE WORK								0	0											
OPERATING SUPPLIES											WAITING FOR BOOSTER											0	0								
COMMODITY			CONSUMED			CREDITED					MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)								0	0											
ITEM		UNIT	QUANTITY			QUANTITY					WAITING FOR ATTENDANT PLANT								0	0											
FUEL		BBL	1,365			1,365					PREPARATION AND MAKING UP TOW								0	0											
ELECTRICITY		KW	0			0					TRANSFERRING PLANT BETWEEN WORKS								0	0											
LUBRICANTS		GAL	0			0					LAY TIME OFF SHIFT AND SATURDAYS								0	0											
MOB DATE			DREDGE START			DEMOB DATE					SUNDAYS AND HOLIDAYS								0	0											
11/15/2019			11/15/2019			11/15/2019					FIRE DRILL								0	0											
											MOVING OUT OF WAY OF TRAFFIC											0	0								
											MISCELLANEOUS (EXPLAIN IN REMARKS)											0	0								
											TOTAL NON-EFFECTIVE TIME											9	36								
											PCT. OF NON-EFFECTIVE											40%									
											TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)											22	0								

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 50 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		25	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/09/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		2	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		2	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	8%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 26	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/10/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET					DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET			DREDGE		SHORE		OTHER	TOTAL									
24					0					3500		24		0			31		0		0	31									
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION Station 149+29 to Station 151+50					DISPOSAL AREA USED DA 64					QTY DEPOSITED GROSS (CY) 7,735			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 85,808													
CHARACTER OF MATERIAL (%)					GRAVEL 0%		SAND 80%		CLAY 0%		MUD 0%		SILT 20%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 0%										
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 7.10					AFTER DREDGING 11.50																
RIVER/TIDE STAGE					MIN 0.40		TIME 06:00		MAX 2		TIME 02:00		GAGE LOCATION Green Day Marker #7																		
					MIN 0		TIME 00:00		MAX 1.60		TIME 15:00		GAGE DATUM MLLW																		
WEATHER CONDITION					WEATHER Weather Caused Critical Delay					TEMP (min/max) 46 °F / 78 °F			VISIBILITY 5 MI			WIND N 14.1 MPH															
WORK PERFORMED											DISTRIBUTION OF WORK																				
ITEM			UNIT			QUANTITY					EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)								HR.	MIN.											
AVERAGE WIDTH OF CUT			FT			200					PUMPING OR DREDGING								10	53											
TOTAL ADVANCE THIS PERIOD			FT			221					PCT OF EFFECTIVE TIME								45%												
TOTAL ADVANCE PREVIOUSLY			FT			3,477					BOOSTER (IN LINE)																				
TOTAL ADVANCE TO DATE			FT			3,698					NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																				
SCOWS LOADED			NUMBER			0					HANDLING PIPE LINES								1	53											
AVERAGE LOAD PER SCOW			CY			0					HANDLING ANCHOR LINES								0	48											
FLOATING PIPE			10,350			SHORE PIPE 0					SUBMERGED PIPE 0					CLEARING PUMP AND PUMP LINES								0	56						
TOTAL LENGTH OF DISCHARGE PIPE			FT			10,350					CLEARING CUTTER AND SUCTION HEAD								0	55											
CUBIC YARDS REMOVED			GROSS			CREDITED					WAITING FOR SCOWS								0	0											
AMOUNT DREDGE THIS DATE			7,735			7,735					TO AND FROM WHARF OR ANCHORAGE								0	0											
AMOUNT PREVIOUSLY REPORTED			78,073			78,073					CHANGING LOCATION OF PLANT ON JOB								0	0											
TOTAL AMOUNT DREDGED TO DATE			85,808			85,808					LOSS DUE TO OPPOSING NATURAL ELEMENTS								8	35											
AMOUNT DREDGED PER PUMPING/CUTTING HR			710.72			710.72					SHORE LINE AND SHORE WORK								0	0											
OPERATING SUPPLIES											WAITING FOR BOOSTER											0	0								
COMMODITY			CONSUMED			CREDITED					MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)								0	0											
ITEM		UNIT	QUANTITY			QUANTITY					WAITING FOR ATTENDANT PLANT								0	0											
FUEL		BBL	1,785			1,785					PREPARATION AND MAKING UP TOW								0	0											
ELECTRICITY		KW	0			0					TRANSFERRING PLANT BETWEEN WORKS								0	0											
LUBRICANTS		GAL	0			0					LAY TIME OFF SHIFT AND SATURDAYS								0	0											
MOB DATE			DREDGE START			DEMOB DATE					SUNDAYS AND HOLIDAYS								0	0											
11/15/2019			11/15/2019								FIRE DRILL								0	0											
											MOVING OUT OF WAY OF TRAFFIC											0	0								
											MISCELLANEOUS (EXPLAIN IN REMARKS)											0	0								
											TOTAL NON-EFFECTIVE TIME											13	7								
											PCT. OF NON-EFFECTIVE											55%									
											TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)											24	0								

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 52 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		26	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/10/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																							
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 27		Page 53 of 123	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/11/2019													
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7															
										SIZE		HORSEPOWER			NO. OF CREW MEMBERS																		
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER	TOTAL																		
24		0		3500		24		0		31		0		0	31																		
LOCATION/CHANNEL OF WORK																																	
LOCATION OF WORK				REACH DREDGED; STATION TO STATION Station 151+50 to Station 151+50				DISPOSAL AREA USED DA 64				QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 85,808																		
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 80%		CLAY 0%		MUD 0%		SILT 20%		HARDPAN 0%		STONE 0%		SHELL 0%	OTHER 0%																
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 7.10				AFTER DREDGING 11.50																					
RIVER/TIDE STAGE				MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION Green Day Marker #7																					
				MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM MLLW																					
WEATHER CONDITION				WEATHER Weather Caused Critical Delay				TEMP (min/max) 41 °F / 54 °F		VISIBILITY 5 MI		WIND N 13.2 MPH																					
WORK PERFORMED								DISTRIBUTION OF WORK																									
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.	MIN.																				
AVERAGE WIDTH OF CUT		FT		200		PUMPING OR DREDGING						0	0																				
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME						0%																					
TOTAL ADVANCE PREVIOUSLY		FT		3,698		BOOSTER (IN LINE)																											
TOTAL ADVANCE TO DATE		FT		3,698		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																											
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES						0	0																				
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES						0	0																				
FLOATING PIPE		10,350		SHORE PIPE		0		SUBMERGED PIPE		0		CLEARING PUMP AND PUMP LINES		0	0																		
TOTAL LENGTH OF DISCHARGE PIPE		FT		10,350		CLEARING CUTTER AND SUCTION HEAD						0	0																				
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS						0	0																				
AMOUNT DREDGE THIS DATE		0		0		TO AND FROM WHARF OR ANCHORAGE						0	0																				
AMOUNT PREVIOUSLY REPORTED		85,808		85,808		CHANGING LOCATION OF PLANT ON JOB						0	0																				
TOTAL AMOUNT DREDGED TO DATE		85,808		85,808		LOSS DUE TO OPPOSING NATURAL ELEMENTS						24	0																				
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		SHORE LINE AND SHORE WORK						0	0																				
OPERATING SUPPLIES						WAITING FOR BOOSTER						0	0																				
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0	0																				
ITEM	UNIT	QUANTITY		QUANTITY		WAITING FOR ATTENDANT PLANT						0	0																				
FUEL	BBL	1,890		1,890		PREPARATION AND MAKING UP TOW						0	0																				
ELECTRICITY	KW	0		0		TRANSFERRING PLANT BETWEEN WORKS						0	0																				
LUBRICANTS	GAL	0		0		LAY TIME OFF SHIFT AND SATURDAYS						0	0																				
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS						0	0																				
11/15/2019		11/15/2019				FIRE DRILL						0	0																				
						MOVING OUT OF WAY OF TRAFFIC						0	0																				
						MISCELLANEOUS (EXPLAIN IN REMARKS)						0	0																				
						TOTAL NON-EFFECTIVE TIME						24	0																				
						PCT. OF NON-EFFECTIVE						100%																					
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						24	0																				

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 54 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		27	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/11/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 28	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/12/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER			NO. OF CREW MEMBERS																
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL															
24		0		3500		24		0		28		0		0		28															
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION None Today				DISPOSAL AREA USED				QTY DEPOSITED GROSS (CY) 0				CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 85,808															
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 0				AFTER DREDGING 0																			
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																					
WEATHER CONDITION				WEATHER Weather Caused Critical Delay				TEMP (min/max) 45 °F / 64 °F				VISIBILITY 3 MI				WIND NE 20-25 MPH															
WORK PERFORMED									DISTRIBUTION OF WORK																						
ITEM			UNIT			QUANTITY			EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.	MIN.															
AVERAGE WIDTH OF CUT			FT			0			PUMPING OR DREDGING						0	0															
TOTAL ADVANCE THIS PERIOD			FT			0			PCT OF EFFECTIVE TIME						0%																
TOTAL ADVANCE PREVIOUSLY			FT			3,698			BOOSTER (IN LINE)																						
TOTAL ADVANCE TO DATE			FT			3,698			NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																						
SCOWS LOADED			NUMBER			0			HANDLING PIPE LINES						0	0															
AVERAGE LOAD PER SCOW			CY			0			HANDLING ANCHOR LINES						0	0															
FLOATING PIPE			0			SHORE PIPE			0			SUBMERGED PIPE			0			CLEARING PUMP AND PUMP LINES						0	0						
TOTAL LENGTH OF DISCHARGE PIPE			FT			0			CLEARING CUTTER AND SUCTION HEAD						0	0															
CUBIC YARDS REMOVED			GROSS			CREDITED			WAITING FOR SCOWS						0	0															
AMOUNT DREDGE THIS DATE			0			0			TO AND FROM WHARF OR ANCHORAGE						0	0															
AMOUNT PREVIOUSLY REPORTED			85,808			85,808			CHANGING LOCATION OF PLANT ON JOB						0	0															
TOTAL AMOUNT DREDGED TO DATE			85,808			85,808			LOSS DUE TO OPPOSING NATURAL ELEMENTS						24	0															
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA			SHORE LINE AND SHORE WORK						0	0															
OPERATING SUPPLIES									WAITING FOR BOOSTER						0	0															
COMMODITY			CONSUMED			CREDITED			MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0	0															
ITEM		UNIT	QUANTITY		QUANTITY		WAITING FOR ATTENDANT PLANT						0	0																	
FUEL		BBL	945		945		PREPARATION AND MAKING UP TOW						0	0																	
ELECTRICITY		KW	0		0		TRANSFERRING PLANT BETWEEN WORKS						0	0																	
LUBRICANTS		GAL	0		0		LAY TIME OFF SHIFT AND SATURDAYS						0	0																	
MOB DATE			DREDGE START			DEMOB DATE			SUNDAYS AND HOLIDAYS						0	0															
11/15/2019			11/15/2019						FIRE DRILL						0	0															
									MOVING OUT OF WAY OF TRAFFIC						0	0															
									MISCELLANEOUS (EXPLAIN IN REMARKS)						0	0															
									TOTAL NON-EFFECTIVE TIME						24	0															
									PCT. OF NON-EFFECTIVE						100%																
									TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						24	0															

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 56 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		28	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/12/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Tender Vessel	Tiger	0	24:00	MAJOR REPAIRS		0	0
Dredge	Kelly L	3600	24:00	CESSATION		0	0
Tender Vessel	Mr. Gus	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS	DATE	

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 29	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/13/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL												
24					0		3500		24		0		31		0		0		31												
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION None Today					DISPOSAL AREA USED					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 85,808													
CHARACTER OF MATERIAL (%)					GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%										
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																		
WEATHER CONDITION					WEATHER Weather Caused Critical Delay					TEMP (min/max) 49 °F / 68 °F		VISIBILITY 2 MI		WIND NE 10-15 MPH																	
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)					HR.	MIN.															
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING					0	0															
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME					0%																
TOTAL ADVANCE PREVIOUSLY			FT			3,698				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			3,698				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES					0	0															
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES					0	0															
FLOATING PIPE			0			SHORE PIPE				0				SUBMERGED PIPE				0													
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				CLEARING PUMP AND PUMP LINES					0	0															
										CLEARING CUTTER AND SUCTION HEAD					0	0															
										WAITING FOR SCOWS					0	0															
										TO AND FROM WHARF OR ANCHORAGE					0	0															
										CHANGING LOCATION OF PLANT ON JOB					0	0															
CUBIC YARDS REMOVED			GROSS			CREDITED				LOSS DUE TO OPPOSING NATURAL ELEMENTS					24	0															
AMOUNT DREDGE THIS DATE			0			0				SHORE LINE AND SHORE WORK					0	0															
AMOUNT PREVIOUSLY REPORTED			85,808			85,808				WAITING FOR BOOSTER					0	0															
TOTAL AMOUNT DREDGED TO DATE			85,808			85,808				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)					0	0															
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				WAITING FOR ATTENDANT PLANT					0	0															
										PREPARATION AND MAKING UP TOW					0	0															
										TRANSFERRING PLANT BETWEEN WORKS					0	0															
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS					0	0															
ITEM		UNIT	QUANTITY			QUANTITY				SUNDAYS AND HOLIDAYS					0	0															
FUEL		BBL	840			840				FIRE DRILL					0	0															
ELECTRICITY		KW	0			0				MOVING OUT OF WAY OF TRAFFIC					0	0															
LUBRICANTS		GAL	0			0				MISCELLANEOUS (EXPLAIN IN REMARKS)					0	0															
MOB DATE			DREDGE START			DEMOB DATE				TOTAL NON-EFFECTIVE TIME					24	0															
11/15/2019			11/15/2019							PCT. OF NON-EFFECTIVE					100%																
										TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)					24	0															

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 58 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		29	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/13/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Fuel 028-932	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 30	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/14/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER			NO. OF CREW MEMBERS																
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL															
24		0		3500		24		0		31		0		0		31															
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION Station 151+43 to Station 152+86				DISPOSAL AREA USED DA 64				QTY DEPOSITED GROSS (CY) 5,243				CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 91,051															
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 60%		CLAY 0%		MUD 0%		SILT 40%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 0%													
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 6.70				AFTER DREDGING 11.50																			
RIVER/TIDE STAGE				MIN 0		TIME 00:00		MAX 0.20		TIME 10:00		GAGE LOCATION Dock inside the Basin																			
				MIN 1.10		TIME 16:00		MAX 2.10		TIME 23:00		GAGE DATUM MLLW																			
WEATHER CONDITION				WEATHER Weather Caused Critical Delay				TEMP (min/max) 51 °F / 67 °F		VISIBILITY 1 MI		WIND NE 5-10 MPH																			
WORK PERFORMED									DISTRIBUTION OF WORK																						
ITEM			UNIT			QUANTITY			EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.	MIN.															
AVERAGE WIDTH OF CUT			FT			220			PUMPING OR DREDGING						6	36															
TOTAL ADVANCE THIS PERIOD			FT			143			PCT OF EFFECTIVE TIME						28%																
TOTAL ADVANCE PREVIOUSLY			FT			3,698			BOOSTER (IN LINE)																						
TOTAL ADVANCE TO DATE			FT			3,841			NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																						
SCOWS LOADED			NUMBER			0			HANDLING PIPE LINES						0	0															
AVERAGE LOAD PER SCOW			CY			0			HANDLING ANCHOR LINES						0	0															
FLOATING PIPE			10,350			SHORE PIPE			0			SUBMERGED PIPE						0	0												
TOTAL LENGTH OF DISCHARGE PIPE			FT			10,350			WAITING FOR SCOWS						0	0															
TOTAL LENGTH OF DISCHARGE PIPE			FT			10,350			TO AND FROM WHARF OR ANCHORAGE						0	0															
CUBIC YARDS REMOVED			GROSS			CREDITED			CHANGING LOCATION OF PLANT ON JOB						0	0															
AMOUNT DREDGE THIS DATE			5,243			5,243			LOSS DUE TO OPPOSING NATURAL ELEMENTS						6	59															
AMOUNT PREVIOUSLY REPORTED			85,808			85,808			SHORE LINE AND SHORE WORK						0	0															
TOTAL AMOUNT DREDGED TO DATE			91,051			91,051			WAITING FOR BOOSTER						0	0															
AMOUNT DREDGED PER PUMPING/CUTTING HR			794.39			794.39			MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0	0															
									WAITING FOR ATTENDANT PLANT						0	0															
									PREPARATION AND MAKING UP TOW						0	0															
									TRANSFERRING PLANT BETWEEN WORKS						0	0															
COMMODITY			CONSUMED			CREDITED			LAY TIME OFF SHIFT AND SATURDAYS						0	0															
ITEM		UNIT	QUANTITY		QUANTITY		SUNDAYS AND HOLIDAYS						0	0																	
FUEL		BBL	420		420		FIRE DRILL						0	0																	
ELECTRICITY		KW	0		0		MOVING OUT OF WAY OF TRAFFIC						0	0																	
LUBRICANTS		GAL	0		0		MISCELLANEOUS (EXPLAIN IN REMARKS)						6	13																	
MOB DATE			DREDGE START			DEMOB DATE			TOTAL NON-EFFECTIVE TIME						14	26															
11/15/2019			11/15/2019						PCT. OF NON-EFFECTIVE						60%																
									TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						21	2															

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO.	
						Page 60 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		30	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/14/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		2	58
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		2	58
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	12%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.	
										Page 61 of 123	
CONTRACT NO.		CONTRACT TITLE			CONTRACTOR			REPORT NO.			
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC			Inland Dredging			31			
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE		12/15/2019	
DREDGE		NAME AND TYPE				SHIFTS PER DAY		DAYS PER WEEK			
		Kelly L - Cutter/Suction				2		7			
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS				
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL	
		24	0	3500	24	0	31	0	0	31	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)		
		Dredge with no stations due to direction of dredging ops			DA 64		6,710		97,761		
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER	
		0%	50%	0%	0%	50%	0%	0%	0%	0%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING		AFTER DREDGING				
					7.10		11.60				
RIVER/TIDE STAGE		MIN	-0.30	TIME	09:00	MAX	1.90	TIME	00:00	GAGE LOCATION Dock inside Basin	
		MIN	-0.30	TIME	13:00	MAX	0.80	TIME	16:00	GAGE DATUM MLLW	
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND		
		Weather Caused No Delay			52 °F / 69 °F		3 MI		N 5-10 MPH		
WORK PERFORMED						DISTRIBUTION OF WORK					
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.
AVERAGE WIDTH OF CUT		FT		220		PUMPING OR DREDGING				9	48
TOTAL ADVANCE THIS PERIOD		FT		287		PCT OF EFFECTIVE TIME				41%	
TOTAL ADVANCE PREVIOUSLY		FT		3,841		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		4,128		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				2	32
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				0	36
FLOATING PIPE 10,510		SHORE PIPE 0		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES				0	59
TOTAL LENGTH OF DISCHARGE PIPE		FT		10,510		CLEARING CUTTER AND SUCTION HEAD				2	8
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS				0	0
AMOUNT DREDGE THIS DATE		6,710		6,710		TO AND FROM WHARF OR ANCHORAGE				0	0
AMOUNT PREVIOUSLY REPORTED		91,051		91,051		CHANGING LOCATION OF PLANT ON JOB				0	54
TOTAL AMOUNT DREDGED TO DATE		97,761		97,761		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0
AMOUNT DREDGED PER PUMPING/CUTTING HR		684.69		684.69		SHORE LINE AND SHORE WORK				0	0
OPERATING SUPPLIES						WAITING FOR BOOSTER				0	0
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT				0	0
FUEL		BBL		1,700		PREPARATION AND MAKING UP TOW				0	0
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS				0	0
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS				0	0
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS				0	0
11/15/2019		11/15/2019				FIRE DRILL				0	0
						MOVING OUT OF WAY OF TRAFFIC				0	0
						MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0
						TOTAL NON-EFFECTIVE TIME				7	9
						PCT. OF NON-EFFECTIVE				30%	
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				16	57

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 62 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		31	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/15/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		7	3
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		7	3
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	29%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.	
										Page 63 of 123	
CONTRACT NO.		CONTRACT TITLE			CONTRACTOR			REPORT NO.			
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC			Inland Dredging			32			
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE		12/16/2019	
DREDGE		NAME AND TYPE				SHIFTS PER DAY		DAYS PER WEEK			
		Kelly L - Cutter/Suction				2		7			
		SIZE		HORSEPOWER			NO. OF CREW MEMBERS				
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL	
		24	0	3500	24	0	29	0	0	29	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY)		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY)		
		Dredged with no stations due to direction of dredging ops			DA 64		6,493		104,254		
CHARACTER OF MATERIAL (%)		GRAVEL	SAND	CLAY	MUD	SILT	HARDPAN	STONE	SHELL	OTHER	
		0 %	50 %	0 %	0 %	50 %	0 %	0 %	0 %	0 %	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING		AFTER DREDGING				
					6.90		11.40				
RIVER/TIDE STAGE		MIN	0	TIME	00:00	MAX	0	TIME	11:00	GAGE LOCATION Dock inside the basin	
		MIN	0.10	TIME	12:00	MAX	2	TIME	21:00	GAGE DATUM MLLW	
WEATHER CONDITION		WEATHER			TEMP (min/max)		VISIBILITY		WIND		
		Weather Caused No Delay			51 °F / 68 °F		3 MI		W 10-15 MPH		
WORK PERFORMED						DISTRIBUTION OF WORK					
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.
AVERAGE WIDTH OF CUT		FT		210		PUMPING OR DREDGING				8	5
TOTAL ADVANCE THIS PERIOD		FT		195		PCT OF EFFECTIVE TIME				34%	
TOTAL ADVANCE PREVIOUSLY		FT		4,128		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		4,323		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				0	0
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				0	19
FLOATING PIPE 10,510		SHORE PIPE 0		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES				0	0
TOTAL LENGTH OF DISCHARGE PIPE		FT		10,510		CLEARING CUTTER AND SUCTION HEAD				2	19
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS				0	0
AMOUNT DREDGE THIS DATE		6,493		6,493		TO AND FROM WHARF OR ANCHORAGE				0	0
AMOUNT PREVIOUSLY REPORTED		97,761		97,761		CHANGING LOCATION OF PLANT ON JOB				0	0
TOTAL AMOUNT DREDGED TO DATE		104,254		104,254		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0
AMOUNT DREDGED PER PUMPING/CUTTING HR		803.26		803.26		SHORE LINE AND SHORE WORK				0	0
OPERATING SUPPLIES						WAITING FOR BOOSTER				0	0
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0
ITEM	UNIT	QUANTITY	QUANTITY	WAITING FOR ATTENDANT PLANT				0	0		
FUEL	BBL	1,365	1,365	PREPARATION AND MAKING UP TOW				0	0		
ELECTRICITY	KW	0	0	TRANSFERRING PLANT BETWEEN WORKS				0	0		
LUBRICANTS	GAL	0	0	LAY TIME OFF SHIFT AND SATURDAYS				0	0		
MOB DATE	DREDGE START	DEMOB DATE	SUNDAYS AND HOLIDAYS				0	0			
11/15/2019	11/15/2019		FIRE DRILL				0	0			
			MOVING OUT OF WAY OF TRAFFIC				0	0			
			MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0			
			TOTAL NON-EFFECTIVE TIME				2	38			
			PCT. OF NON-EFFECTIVE				11%				
			TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				10	43			

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 64 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		32	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/16/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Tiger	0	24:00	CESSATION		0	0
Tender Vessel	Rebel	0	24:00	COLLISIONS		0	0
Towing Vessel	Cardinal	0	00:00	MISCELLANEOUS		13	17
Barge	Anchor 028-954	0	24:00	TOTAL LOST TIME		13	17
Barge	Crane	0	24:00	PERCENTAGE OF TOTAL TIME	55%		
Barge	Deck 028-951	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 33	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/17/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL												
24					0		3500		24		0		29		0		0		29												
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION Dredge completed Village Channel Basin					DISPOSAL AREA USED DA 64					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 50%		CLAY 0%		MUD 0%		SILT 50%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 0%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM MLLW																		
WEATHER CONDITION					WEATHER Weather Caused Critical Delay					TEMP (min/max) 38 °F / 72 °F		VISIBILITY 5 MI		WIND N 16.4 MPH																	
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.		MIN.													
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING						0		0													
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME						0%															
TOTAL ADVANCE PREVIOUSLY			FT			4,323				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			4,323				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES						0		0													
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES						0		0													
FLOATING PIPE			10,510			SHORE PIPE 0				SUBMERGED PIPE 0						0		0													
TOTAL LENGTH OF DISCHARGE PIPE			FT			10,510				TO AND FROM WHARF OR ANCHORAGE						0		0													
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB						0		0													
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS						0		0													
AMOUNT PREVIOUSLY REPORTED			104,254			104,254				SHORE LINE AND SHORE WORK						0		0													
TOTAL AMOUNT DREDGED TO DATE			104,254			104,254				WAITING FOR BOOSTER						0		0													
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0		0													
										WAITING FOR ATTENDANT PLANT						0		0													
										PREPARATION AND MAKING UP TOW						0		0													
										TRANSFERRING PLANT BETWEEN WORKS						0		0													
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS						0		0													
ITEM		UNIT	QUANTITY		QUANTITY		SUNDAYS AND HOLIDAYS						0		0																
FUEL		BBL	525		525		FIRE DRILL						0		0																
ELECTRICITY		KW	0		0		MOVING OUT OF WAY OF TRAFFIC						0		0																
LUBRICANTS		GAL	0		0		MISCELLANEOUS (EXPLAIN IN REMARKS)						24		0																
										TOTAL NON-EFFECTIVE TIME						24		0													
MOB DATE			DREDGE START			DEMOB DATE				PCT. OF NON-EFFECTIVE						100%															
11/15/2019			11/15/2019							TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						24		0													

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO. Page 66 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		33	
DREDGE		Kelly L - Cutter/Suction				DATE 12/17/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 34	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/18/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL												
24					0		3500		24		0		29		0		0		29												
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION Dredge completed Village Channel Basin					DISPOSAL AREA USED DA 64					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 50%		CLAY 0%		MUD 0%		SILT 50%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 0%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM MLLW																		
WEATHER CONDITION					WEATHER Weather Caused Critical Delay					TEMP (min/max) 30 °F / 52 °F		VISIBILITY 6 MI		WIND N 11.6 MPH																	
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.		MIN.													
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING						0		0													
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME						0%															
TOTAL ADVANCE PREVIOUSLY			FT			4,323				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			4,323				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES						0		0													
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES						0		0													
FLOATING PIPE			10,510			SHORE PIPE 0				SUBMERGED PIPE 0						0		0													
TOTAL LENGTH OF DISCHARGE PIPE			FT			10,510				TO AND FROM WHARF OR ANCHORAGE						0		0													
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB						0		0													
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS						0		0													
AMOUNT PREVIOUSLY REPORTED			104,254			104,254				SHORE LINE AND SHORE WORK						0		0													
TOTAL AMOUNT DREDGED TO DATE			104,254			104,254				WAITING FOR BOOSTER						0		0													
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0		0													
										WAITING FOR ATTENDANT PLANT						0		0													
										PREPARATION AND MAKING UP TOW						0		0													
										TRANSFERRING PLANT BETWEEN WORKS						0		0													
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS						0		0													
ITEM		UNIT	QUANTITY		QUANTITY		SUNDAYS AND HOLIDAYS						0		0																
FUEL		BBL	1,890		1,890		FIRE DRILL						0		0																
ELECTRICITY		KW	0		0		MOVING OUT OF WAY OF TRAFFIC						0		0																
LUBRICANTS		GAL	0		0		MISCELLANEOUS (EXPLAIN IN REMARKS)						24		0																
MOB DATE			DREDGE START			DEMOB DATE				TOTAL NON-EFFECTIVE TIME						24		0													
11/15/2019			11/15/2019							PCT. OF NON-EFFECTIVE						100%															
										TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						24		0													

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 68 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		34	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/18/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Tender Vessel	Mr. Gus	0	24:00	MAJOR REPAIRS		0	0
Dredge	Kelly L	3600	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 35	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/19/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
		SIZE			HORSEPOWER					NO. OF CREW MEMBERS																					
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE	OTHER	TOTAL																	
24		0		3500		24		0		29		0	0	29																	
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK			REACH DREDGED; STATION TO STATION Dredge completed Village Channel Basin				DISPOSAL AREA USED DA 64			QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254																		
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 50%		CLAY 0%		MUD 0%		SILT 50%		HARDPAN 0%	STONE 0%	SHELL 0%	OTHER 0%																
CHANNEL CONDITION			AVERAGE DEPTH				BEFORE DREDGING 0			AFTER DREDGING 0																					
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM MLLW																					
WEATHER CONDITION			WEATHER Weather Caused No Delay				TEMP (min/max) 31 °F / 56 °F		VISIBILITY 8 MI		WIND N 6.1 MPH																				
WORK PERFORMED							DISTRIBUTION OF WORK																								
ITEM		UNIT		QUANTITY			EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)					HR.	MIN.																		
AVERAGE WIDTH OF CUT		FT		0			PUMPING OR DREDGING					0	0																		
TOTAL ADVANCE THIS PERIOD		FT		0			PCT OF EFFECTIVE TIME					0%																			
TOTAL ADVANCE PREVIOUSLY		FT		4,323			BOOSTER (IN LINE)																								
TOTAL ADVANCE TO DATE		FT		4,323			NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																								
SCOWS LOADED		NUMBER		0			HANDLING PIPE LINES					0	0																		
AVERAGE LOAD PER SCOW		CY		0			HANDLING ANCHOR LINES					0	0																		
FLOATING PIPE		10,510		SHORE PIPE		0		SUBMERGED PIPE			0																				
TOTAL LENGTH OF DISCHARGE PIPE		FT		10,510			CLEARING PUMP AND PUMP LINES					0	0																		
							CLEARING CUTTER AND SUCTION HEAD					0	0																		
							WAITING FOR SCOWS					0	0																		
							TO AND FROM WHARF OR ANCHORAGE					0	0																		
							CHANGING LOCATION OF PLANT ON JOB					0	0																		
CUBIC YARDS REMOVED		GROSS		CREDITED			LOSS DUE TO OPPOSING NATURAL ELEMENTS					0	0																		
AMOUNT DREDGE THIS DATE		0		0			SHORE LINE AND SHORE WORK					0	0																		
AMOUNT PREVIOUSLY REPORTED		104,254		104,254			WAITING FOR BOOSTER					0	0																		
TOTAL AMOUNT DREDGED TO DATE		104,254		104,254			MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)					0	0																		
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA			WAITING FOR ATTENDANT PLANT					0	0																		
							PREPARATION AND MAKING UP TOW					0	0																		
							TRANSFERRING PLANT BETWEEN WORKS					0	0																		
COMMODITY		CONSUMED		CREDITED			LAY TIME OFF SHIFT AND SATURDAYS					0	0																		
ITEM		UNIT		QUANTITY		QUANTITY		SUNDAYS AND HOLIDAYS					0	0																	
FUEL		BBL		1,475		1,475		FIRE DRILL					0	0																	
ELECTRICITY		KW		0		0		MOVING OUT OF WAY OF TRAFFIC					0	0																	
LUBRICANTS		GAL		0		0		MISCELLANEOUS (EXPLAIN IN REMARKS)					24	0																	
							TOTAL NON-EFFECTIVE TIME					24	0																		
MOB DATE		DREDGE START		DEMOB DATE			PCT. OF NON-EFFECTIVE					100%																			
11/15/2019		11/15/2019					TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)					24	0																		

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO.	
						Page 70 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		35	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/19/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 36	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/20/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL												
24					0		3500		24		0		29		0		0		29												
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION Dredge completed Village Channel Basin					DISPOSAL AREA USED DA 64					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 50%		CLAY 0%		MUD 0%		SILT 50%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 0%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM MLLW																		
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 32 °F / 61 °F		VISIBILITY 8 MI		WIND E 5.7 MPH																	
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)					HR.		MIN.														
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING					0		0														
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME					0%																
TOTAL ADVANCE PREVIOUSLY			FT			4,323				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			4,323				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES					0		0														
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES					0		0														
FLOATING PIPE			0			SHORE PIPE				0				SUBMERGED PIPE				0													
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				TO AND FROM WHARF OR ANCHORAGE					0		0														
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB					0		0														
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS					0		0														
AMOUNT PREVIOUSLY REPORTED			104,254			104,254				SHORE LINE AND SHORE WORK					0		0														
TOTAL AMOUNT DREDGED TO DATE			104,254			104,254				WAITING FOR BOOSTER					0		0														
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)					0		0														
										WAITING FOR ATTENDANT PLANT					0		0														
										PREPARATION AND MAKING UP TOW					0		0														
										TRANSFERRING PLANT BETWEEN WORKS					0		0														
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS					0		0														
ITEM		UNIT	QUANTITY			QUANTITY				SUNDAYS AND HOLIDAYS					0		0														
FUEL		BBL	50			50				FIRE DRILL					0		0														
ELECTRICITY		KW	0			0				MOVING OUT OF WAY OF TRAFFIC					0		0														
LUBRICANTS		GAL	0			0				MISCELLANEOUS (EXPLAIN IN REMARKS)					24		0														
										TOTAL NON-EFFECTIVE TIME					24		0														
MOB DATE			DREDGE START			DEMOB DATE				PCT. OF NON-EFFECTIVE					100%																
11/15/2019			11/15/2019							TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)					24		0														

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 72 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		36	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/20/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Tender Vessel	Rebel	0	24:00	MAJOR REPAIRS		0	0
Dredge	Kelly L	3600	24:00	CESSATION		0	0
Tender Vessel	Mr. Gus	0	24:00	COLLISIONS		0	0
Tender Vessel	Tiger	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 37	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/21/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL												
24					0		3500		24		0		15		0		0		15												
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION None Today					DISPOSAL AREA USED DA 64					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																		
WEATHER CONDITION					WEATHER Weather Caused Critical Delay					TEMP (min/max) 51 °F / 59 °F		VISIBILITY 3 MI		WIND NE 20-25 with gust up to MPH																	
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.		MIN.													
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING						0		0													
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME						0%															
TOTAL ADVANCE PREVIOUSLY			FT			4,323				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			4,323				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES						0		0													
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES						0		0													
FLOATING PIPE			0			SHORE PIPE				0				SUBMERGED PIPE				0													
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				CLEARING PUMP AND PUMP LINES						0		0													
										CLEARING CUTTER AND SUCTION HEAD						0		0													
										WAITING FOR SCOWS						0		0													
										TO AND FROM WHARF OR ANCHORAGE						0		0													
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB						0		0													
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS						0		0													
AMOUNT PREVIOUSLY REPORTED			104,254			104,254				SHORE LINE AND SHORE WORK						0		0													
TOTAL AMOUNT DREDGED TO DATE			104,254			104,254				WAITING FOR BOOSTER						0		0													
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0		0													
										WAITING FOR ATTENDANT PLANT						0		0													
										PREPARATION AND MAKING UP TOW						0		0													
										TRANSFERRING PLANT BETWEEN WORKS						0		0													
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS						0		0													
ITEM		UNIT	QUANTITY		QUANTITY		SUNDAYS AND HOLIDAYS						0		0																
FUEL		BBL	50		50		FIRE DRILL						0		0																
ELECTRICITY		KW	0		0		MOVING OUT OF WAY OF TRAFFIC						0		0																
LUBRICANTS		GAL	0		0		MISCELLANEOUS (EXPLAIN IN REMARKS)						24		0																
										TOTAL NON-EFFECTIVE TIME						24		0													
MOB DATE			DREDGE START			DEMOB DATE				PCT. OF NON-EFFECTIVE						100%															
11/15/2019			11/15/2019							TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						24		0													

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO.	
						Page 74 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		37	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/21/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO. Page 75 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC				CONTRACTOR Inland Dredging				REPORT NO. 38	
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE 12/22/2019			
DREDGE		NAME AND TYPE Kelly L - Cutter/Suction				SHIFTS PER DAY 2		DAYS PER WEEK 7			
		SIZE		HORSEPOWER		NO. OF CREW MEMBERS					
		PIPELINE 24	DIPPER OR BUCKET 0	DREDGE PUMP 3500	SUCTION PIPE JET 24	CUTTER OR BUCKET 0	DREDGE 10	SHORE 0	OTHER 0	TOTAL 10	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION No Dredging			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY) 0		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254		
CHARACTER OF MATERIAL (%)		GRAVEL 0%	SAND 0%	CLAY 0%	MUD 0%	SILT 0%	HARDPAN 0%	STONE 0%	SHELL 0%	OTHER 100%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING 0		AFTER DREDGING 0				
RIVER/TIDE STAGE		MIN 0	TIME 00:00	MAX 0	TIME 00:00	GAGE LOCATION					
		MIN 0	TIME 00:00	MAX 0	TIME 00:00	GAGE DATUM					
WEATHER CONDITION		WEATHER Weather Caused No Delay			TEMP (min/max) 50 °F / 59 °F		VISIBILITY 2 MI		WIND NE 15-20 gusts up to 25 MPH		
WORK PERFORMED					DISTRIBUTION OF WORK						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING				0	0
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME				0%	
TOTAL ADVANCE PREVIOUSLY		FT		4,323		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		4,323		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				0	0
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				0	0
FLOATING PIPE 0		SHORE PIPE 0		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES				0	0
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		CLEARING CUTTER AND SUCTION HEAD				0	0
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS				0	0
AMOUNT DREDGE THIS DATE		0		0		TO AND FROM WHARF OR ANCHORAGE				0	0
AMOUNT PREVIOUSLY REPORTED		104,254		104,254		CHANGING LOCATION OF PLANT ON JOB				0	0
TOTAL AMOUNT DREDGED TO DATE		104,254		104,254		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		SHORE LINE AND SHORE WORK				0	0
OPERATING SUPPLIES						WAITING FOR BOOSTER				0	0
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT				0	0
FUEL		BBL		55		PREPARATION AND MAKING UP TOW				0	0
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS				0	0
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS				0	0
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS				0	0
11/15/2019		11/15/2019				FIRE DRILL				0	0
						MOVING OUT OF WAY OF TRAFFIC				0	0
						MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0
						TOTAL NON-EFFECTIVE TIME				0	0
						PCT. OF NON-EFFECTIVE				0%	
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				0	0

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO. Page 76 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		38	
DREDGE						DATE	
Kelly L - Cutter/Suction						12/22/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		24	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		24	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	100%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 39	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/23/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL															
24		0		3500		24		0		10		0		0		10															
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION None Today				DISPOSAL AREA USED				QTY DEPOSITED GROSS (CY) 0				CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254															
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 0				AFTER DREDGING 0																			
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																					
WEATHER CONDITION				WEATHER Weather Caused No Delay				TEMP (min/max) 51 °F / 70 °F		VISIBILITY 3 MI		WIND NE 15-20 MPH																			
WORK PERFORMED									DISTRIBUTION OF WORK																						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.		MIN.																	
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING						0		0																	
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME						0%																			
TOTAL ADVANCE PREVIOUSLY		FT		4,323		BOOSTER (IN LINE)																									
TOTAL ADVANCE TO DATE		FT		4,323		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																									
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES						0		0																	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES						0		0																	
FLOATING PIPE		0		SHORE PIPE		0		SUBMERGED PIPE		0		CLEARING PUMP AND PUMP LINES		0		0															
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		CLEARING CUTTER AND SUCTION HEAD						0		0																	
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS						0		0																	
AMOUNT DREDGE THIS DATE		0		0		TO AND FROM WHARF OR ANCHORAGE						0		0																	
AMOUNT PREVIOUSLY REPORTED		104,254		104,254		CHANGING LOCATION OF PLANT ON JOB						0		0																	
TOTAL AMOUNT DREDGED TO DATE		104,254		104,254		LOSS DUE TO OPPOSING NATURAL ELEMENTS						0		0																	
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		SHORE LINE AND SHORE WORK						0		0																	
OPERATING SUPPLIES						WAITING FOR BOOSTER						0		0																	
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0		0																	
ITEM		UNIT		QUANTITY		QUANTITY		WAITING FOR ATTENDANT PLANT						0		0															
FUEL		BBL		218		218		PREPARATION AND MAKING UP TOW						0		0															
ELECTRICITY		KW		0		0		TRANSFERRING PLANT BETWEEN WORKS						0		0															
LUBRICANTS		GAL		0		0		LAY TIME OFF SHIFT AND SATURDAYS						0		0															
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS						24		0																	
11/15/2019		11/15/2019				FIRE DRILL						0		0																	
						MOVING OUT OF WAY OF TRAFFIC						0		0																	
						MISCELLANEOUS (EXPLAIN IN REMARKS)						0		0																	
						TOTAL NON-EFFECTIVE TIME						24		0																	
						PCT. OF NON-EFFECTIVE						100%																			
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						24		0																	

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO. Page 78 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		39	
DREDGE		ATTENDANT PLANT				DATE	
		Kelly L - Cutter/Suction				12/23/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 40	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/24/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET					DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET			DREDGE		SHORE		OTHER		TOTAL								
24					0					3500		24		0			6		0		0		6								
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION					DISPOSAL AREA USED					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																		
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 53 °F / 62 °F			VISIBILITY 3 MI		WIND NE 10-15 MPH																
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)								HR.		MIN.											
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING								0		0											
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME								0%													
TOTAL ADVANCE PREVIOUSLY			FT			4,323				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			4,323				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES								0		0											
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES								0		0											
FLOATING PIPE			0			SHORE PIPE				0				SUBMERGED PIPE				0				0		0							
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				TO AND FROM WHARF OR ANCHORAGE								0		0											
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB								0		0											
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS								0		0											
AMOUNT PREVIOUSLY REPORTED			104,254			104,254				SHORE LINE AND SHORE WORK								0		0											
TOTAL AMOUNT DREDGED TO DATE			104,254			104,254				WAITING FOR BOOSTER								0		0											
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)								0		0											
										WAITING FOR ATTENDANT PLANT								0		0											
										PREPARATION AND MAKING UP TOW								0		0											
										TRANSFERRING PLANT BETWEEN WORKS								0		0											
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS								0		0											
ITEM		UNIT	QUANTITY			QUANTITY				SUNDAYS AND HOLIDAYS								24		0											
FUEL		BBL	50			50				FIRE DRILL								0		0											
ELECTRICITY		KW	0			0				MOVING OUT OF WAY OF TRAFFIC								0		0											
LUBRICANTS		GAL	0			0				MISCELLANEOUS (EXPLAIN IN REMARKS)								0		0											
										TOTAL NON-EFFECTIVE TIME								24		0											
MOB DATE			DREDGE START			DEMOB DATE				PCT. OF NON-EFFECTIVE								100%													
11/15/2019			11/15/2019							TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)								24		0											

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.						
					Page 80 of 123						
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.					
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		40					
DREDGE		Kelly L - Cutter/Suction				DATE					
						12/24/2019					
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)							
ITEM		NAME OR NUMBER		H.P.		HOURS		HR		MIN	
Dredge		Kelly L		3600		24:00		MAJOR REPAIRS		0 0	
Tender Vessel		Mr. Gus		0		24:00		CESSATION		0 0	
Tender Vessel		Tiger		0		24:00		COLLISIONS		0 0	
Tender Vessel		Rebel		0		24:00		MISCELLANEOUS		0 0	
Towing Vessel		Cardinal		0		00:00		TOTAL LOST TIME		0 0	
Barge		Anchor 028-954		0		24:00		PERCENTAGE OF TOTAL TIME		0%	
Barge		Crane		0		24:00		TOTAL TIME IN PERIOD		24 0	

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE		DATE		SUPERINTENDENT'S INITIALS		DATE	

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 41	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/25/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER			NO. OF CREW MEMBERS																
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL															
24		0		3500		24		0		6		0		0		6															
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION				DISPOSAL AREA USED				QTY DEPOSITED GROSS (CY) 0				CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254															
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 0				AFTER DREDGING 0																			
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																					
WEATHER CONDITION				WEATHER Weather Caused No Delay				TEMP (min/max) 54 °F / 67 °F				VISIBILITY 3 MI		WIND N 5-10 MPH																	
WORK PERFORMED									DISTRIBUTION OF WORK																						
ITEM			UNIT			QUANTITY			EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.	MIN.															
AVERAGE WIDTH OF CUT			FT			0			PUMPING OR DREDGING						0	0															
TOTAL ADVANCE THIS PERIOD			FT			0			PCT OF EFFECTIVE TIME						0%																
TOTAL ADVANCE PREVIOUSLY			FT			4,323			BOOSTER (IN LINE)																						
TOTAL ADVANCE TO DATE			FT			4,323			NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																						
SCOWS LOADED			NUMBER			0			HANDLING PIPE LINES						0	0															
AVERAGE LOAD PER SCOW			CY			0			HANDLING ANCHOR LINES						0	0															
FLOATING PIPE			0			SHORE PIPE			0			SUBMERGED PIPE			0																
TOTAL LENGTH OF DISCHARGE PIPE			FT			0			CLEARING PUMP AND PUMP LINES						0	0															
									CLEARING CUTTER AND SUCTION HEAD						0	0															
									WAITING FOR SCOWS						0	0															
									TO AND FROM WHARF OR ANCHORAGE						0	0															
CUBIC YARDS REMOVED			GROSS			CREDITED			CHANGING LOCATION OF PLANT ON JOB						0	0															
AMOUNT DREDGE THIS DATE			0			0			LOSS DUE TO OPPOSING NATURAL ELEMENTS						0	0															
AMOUNT PREVIOUSLY REPORTED			104,254			104,254			SHORE LINE AND SHORE WORK						0	0															
TOTAL AMOUNT DREDGED TO DATE			104,254			104,254			WAITING FOR BOOSTER						0	0															
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA			MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0	0															
									WAITING FOR ATTENDANT PLANT						0	0															
									PREPARATION AND MAKING UP TOW						0	0															
									TRANSFERRING PLANT BETWEEN WORKS						0	0															
COMMODITY			CONSUMED			CREDITED			LAY TIME OFF SHIFT AND SATURDAYS						0	0															
ITEM		UNIT	QUANTITY		QUANTITY		SUNDAYS AND HOLIDAYS						24	0																	
FUEL		BBL	50		50		FIRE DRILL						0	0																	
ELECTRICITY		KW	0		0		MOVING OUT OF WAY OF TRAFFIC						0	0																	
LUBRICANTS		GAL	0		0		MISCELLANEOUS (EXPLAIN IN REMARKS)						0	0																	
MOB DATE			DREDGE START			DEMOB DATE			TOTAL NON-EFFECTIVE TIME						24	0															
11/15/2019			11/15/2019						PCT. OF NON-EFFECTIVE						100%																
									TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						24	0															

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO. Page 82 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		41	
DREDGE		ATTENDANT PLANT				DATE	
Kelly L - Cutter/Suction						12/25/2019	
				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Barge	Crane	0	24:00	MISCELLANEOUS		0	0
Tender Vessel	Rebel	0	24:00	TOTAL LOST TIME		0	0
Towing Vessel	Cardinal	0	00:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Anchor 028-954	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 42	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/26/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER			NO. OF CREW MEMBERS																
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER	TOTAL																
24		0		3500		24		0		7		0		0	7																
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION				DISPOSAL AREA USED				QTY DEPOSITED GROSS (CY) 0		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254																	
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%	OTHER 100%														
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 0				AFTER DREDGING 0																			
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																					
WEATHER CONDITION				WEATHER Weather Caused No Delay				TEMP (min/max) 59 °F / 74 °F		VISIBILITY 3 MI		WIND E 5-10 MPH																			
WORK PERFORMED								DISTRIBUTION OF WORK																							
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.		MIN.																			
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING				0		0																			
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME				0%																					
TOTAL ADVANCE PREVIOUSLY		FT		4,323		BOOSTER (IN LINE)																									
TOTAL ADVANCE TO DATE		FT		4,323		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																									
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				0		0																			
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				0		0																			
FLOATING PIPE		0		SHORE PIPE		0		SUBMERGED PIPE		0		0																			
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		CLEARING PUMP AND PUMP LINES				0		0																			
						CLEARING CUTTER AND SUCTION HEAD				0		0																			
						WAITING FOR SCOWS				0		0																			
						TO AND FROM WHARF OR ANCHORAGE				0		0																			
						CHANGING LOCATION OF PLANT ON JOB				0		0																			
CUBIC YARDS REMOVED		GROSS		CREDITED		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0		0																			
AMOUNT DREDGE THIS DATE		0		0		SHORE LINE AND SHORE WORK				0		0																			
AMOUNT PREVIOUSLY REPORTED		104,254		104,254		WAITING FOR BOOSTER				0		0																			
TOTAL AMOUNT DREDGED TO DATE		104,254		104,254		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0		0																			
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		WAITING FOR ATTENDANT PLANT				0		0																			
						PREPARATION AND MAKING UP TOW				0		0																			
						TRANSFERRING PLANT BETWEEN WORKS				0		0																			
COMMODITY		CONSUMED		CREDITED		LAY TIME OFF SHIFT AND SATURDAYS				0		0																			
ITEM		UNIT		QUANTITY		SUNDAYS AND HOLIDAYS				24		0																			
FUEL		BBL		55		FIRE DRILL				0		0																			
ELECTRICITY		KW		0		MOVING OUT OF WAY OF TRAFFIC				0		0																			
LUBRICANTS		GAL		0		MISCELLANEOUS (EXPLAIN IN REMARKS)				0		0																			
MOB DATE		DREDGE START		DEMOB DATE		TOTAL NON-EFFECTIVE TIME				24		0																			
11/15/2019		11/15/2019				PCT. OF NON-EFFECTIVE				100%																					
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				24		0																			

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 84 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		42	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/26/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 43	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/27/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER			NO. OF CREW MEMBERS																
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER	TOTAL																
24		0		3500		24		0		8		0		0	8																
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION				DISPOSAL AREA USED				QTY DEPOSITED GROSS (CY) 0		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254																	
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%	OTHER 100%														
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 0				AFTER DREDGING 0																			
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																					
WEATHER CONDITION				WEATHER Weather Caused No Delay				TEMP (min/max) 59 °F / 72 °F		VISIBILITY 3 MI		WIND E 5-10 MPH																			
WORK PERFORMED								DISTRIBUTION OF WORK																							
ITEM		UNIT		QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.																		
AVERAGE WIDTH OF CUT		FT		0				PUMPING OR DREDGING				0	0																		
TOTAL ADVANCE THIS PERIOD		FT		0				PCT OF EFFECTIVE TIME				0%																			
TOTAL ADVANCE PREVIOUSLY		FT		4,323				BOOSTER (IN LINE)																							
TOTAL ADVANCE TO DATE		FT		4,323				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																							
SCOWS LOADED		NUMBER		0				HANDLING PIPE LINES				0	0																		
AVERAGE LOAD PER SCOW		CY		0				HANDLING ANCHOR LINES				0	0																		
FLOATING PIPE		0		SHORE PIPE		0		SUBMERGED PIPE		0		CLEARING PUMP AND PUMP LINES		0	0																
TOTAL LENGTH OF DISCHARGE PIPE		FT		0				CLEARING CUTTER AND SUCTION HEAD				0	0																		
CUBIC YARDS REMOVED		GROSS		CREDITED				WAITING FOR SCOWS				0	0																		
AMOUNT DREDGE THIS DATE		0		0				TO AND FROM WHARF OR ANCHORAGE				0	0																		
AMOUNT PREVIOUSLY REPORTED		104,254		104,254				CHANGING LOCATION OF PLANT ON JOB				0	0																		
TOTAL AMOUNT DREDGED TO DATE		104,254		104,254				LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0																		
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA				SHORE LINE AND SHORE WORK				0	0																		
OPERATING SUPPLIES						WAITING FOR BOOSTER				0	0																				
COMMODITY		CONSUMED		CREDITED				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0																		
ITEM		UNIT		QUANTITY		QUANTITY		WAITING FOR ATTENDANT PLANT				0	0																		
FUEL		BBL		50		50		PREPARATION AND MAKING UP TOW				0	0																		
ELECTRICITY		KW		0		0		TRANSFERRING PLANT BETWEEN WORKS				0	0																		
LUBRICANTS		GAL		0		0		LAY TIME OFF SHIFT AND SATURDAYS				0	0																		
MOB DATE		DREDGE START		DEMOB DATE				SUNDAYS AND HOLIDAYS				24	0																		
11/15/2019		11/15/2019						FIRE DRILL				0	0																		
								MOVING OUT OF WAY OF TRAFFIC				0	0																		
								MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0																		
								TOTAL NON-EFFECTIVE TIME				24	0																		
								PCT. OF NON-EFFECTIVE				100%																			
								TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				24	0																		

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 86 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		43	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/27/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Tender Vessel	Rebel	0	24:00	MAJOR REPAIRS		0	0
Dredge	Kelly L	3600	24:00	CESSATION		0	0
Tender Vessel	Mr. Gus	0	24:00	COLLISIONS		0	0
Tender Vessel	Tiger	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 44	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/28/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET					DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET			DREDGE		SHORE		OTHER		TOTAL								
24					0					3500		24		0			10		0		0		10								
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION					DISPOSAL AREA USED					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254													
CHARACTER OF MATERIAL (%)					GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%										
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																		
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 54 °F / 72 °F			VISIBILITY MI		WIND SE 5-10 MPH																
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)								HR.		MIN.											
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING								0		0											
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME								0%													
TOTAL ADVANCE PREVIOUSLY			FT			4,323				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			4,323				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES								0		0											
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES								0		0											
FLOATING PIPE			0			SHORE PIPE				0				SUBMERGED PIPE				0				0		0							
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				TO AND FROM WHARF OR ANCHORAGE								0		0											
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB								0		0											
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS								0		0											
AMOUNT PREVIOUSLY REPORTED			104,254			104,254				SHORE LINE AND SHORE WORK								0		0											
TOTAL AMOUNT DREDGED TO DATE			104,254			104,254				WAITING FOR BOOSTER								0		0											
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)								0		0											
										WAITING FOR ATTENDANT PLANT								0		0											
										PREPARATION AND MAKING UP TOW								0		0											
										TRANSFERRING PLANT BETWEEN WORKS								0		0											
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS								0		0											
ITEM		UNIT	QUANTITY			QUANTITY				SUNDAYS AND HOLIDAYS								24		0											
FUEL		BBL	850			850				FIRE DRILL								0		0											
ELECTRICITY		KW	0			0				MOVING OUT OF WAY OF TRAFFIC								0		0											
LUBRICANTS		GAL	0			0				MISCELLANEOUS (EXPLAIN IN REMARKS)								0		0											
MOB DATE			DREDGE START			DEMOB DATE				TOTAL NON-EFFECTIVE TIME								24		0											
11/15/2019			11/15/2019							PCT. OF NON-EFFECTIVE								100%													
										TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)								24		0											

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO.	
						Page 88 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		44	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/28/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 45	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/29/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL												
24					0		3500		24		0		10		0		0		10												
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION					DISPOSAL AREA USED					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																		
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 51 °F / 66 °F		VISIBILITY 3 MI		WIND N 5-10 MPH																	
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)					HR.		MIN.														
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING					0		0														
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME					0%																
TOTAL ADVANCE PREVIOUSLY			FT			4,323				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			4,323				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES					0		0														
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES					0		0														
FLOATING PIPE			0			SHORE PIPE				0				SUBMERGED PIPE				0													
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				TO AND FROM WHARF OR ANCHORAGE					0		0														
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB					0		0														
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS					0		0														
AMOUNT PREVIOUSLY REPORTED			104,254			104,254				SHORE LINE AND SHORE WORK					0		0														
TOTAL AMOUNT DREDGED TO DATE			104,254			104,254				WAITING FOR BOOSTER					0		0														
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)					0		0														
										WAITING FOR ATTENDANT PLANT					0		0														
										PREPARATION AND MAKING UP TOW					0		0														
										TRANSFERRING PLANT BETWEEN WORKS					0		0														
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS					0		0														
ITEM		UNIT		QUANTITY		QUANTITY				SUNDAYS AND HOLIDAYS					24		0														
FUEL		BBL		50		50				FIRE DRILL					0		0														
ELECTRICITY		KW		0		0				MOVING OUT OF WAY OF TRAFFIC					0		0														
LUBRICANTS		GAL		0		0				MISCELLANEOUS (EXPLAIN IN REMARKS)					0		0														
MOB DATE			DREDGE START			DEMOB DATE				TOTAL NON-EFFECTIVE TIME					24		0														
11/15/2019			11/15/2019							PCT. OF NON-EFFECTIVE					100%																
										TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)					24		0														

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO.	
						Page 90 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		45	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/29/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 46	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/30/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL															
24		0		3500		24		0		10		0		0		10															
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION				DISPOSAL AREA USED				QTY DEPOSITED GROSS (CY) 0				CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254															
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 0				AFTER DREDGING 0																			
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																					
WEATHER CONDITION				WEATHER Weather Caused No Delay				TEMP (min/max) 62 °F / 73 °F		VISIBILITY 3 MI		WIND NE 5-10 MPH																			
WORK PERFORMED									DISTRIBUTION OF WORK																						
ITEM			UNIT			QUANTITY			EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.	MIN.															
AVERAGE WIDTH OF CUT			FT			0			PUMPING OR DREDGING						0	0															
TOTAL ADVANCE THIS PERIOD			FT			0			PCT OF EFFECTIVE TIME						0%																
TOTAL ADVANCE PREVIOUSLY			FT			4,323			BOOSTER (IN LINE)																						
TOTAL ADVANCE TO DATE			FT			4,323			NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																						
SCOWS LOADED			NUMBER			0			HANDLING PIPE LINES						0	0															
AVERAGE LOAD PER SCOW			CY			0			HANDLING ANCHOR LINES						0	0															
FLOATING PIPE			0			SHORE PIPE			0			SUBMERGED PIPE			0																
TOTAL LENGTH OF DISCHARGE PIPE			FT			0			CLEARING PUMP AND PUMP LINES						0	0															
									CLEARING CUTTER AND SUCTION HEAD						0	0															
									WAITING FOR SCOWS						0	0															
									TO AND FROM WHARF OR ANCHORAGE						0	0															
CUBIC YARDS REMOVED			GROSS			CREDITED			CHANGING LOCATION OF PLANT ON JOB						0	0															
AMOUNT DREDGE THIS DATE			0			0			LOSS DUE TO OPPOSING NATURAL ELEMENTS						0	0															
AMOUNT PREVIOUSLY REPORTED			104,254			104,254			SHORE LINE AND SHORE WORK						0	0															
TOTAL AMOUNT DREDGED TO DATE			104,254			104,254			WAITING FOR BOOSTER						0	0															
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA			MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0	0															
									WAITING FOR ATTENDANT PLANT						0	0															
									PREPARATION AND MAKING UP TOW						0	0															
									TRANSFERRING PLANT BETWEEN WORKS						0	0															
COMMODITY			CONSUMED			CREDITED			LAY TIME OFF SHIFT AND SATURDAYS						0	0															
ITEM		UNIT	QUANTITY		QUANTITY		SUNDAYS AND HOLIDAYS						24	0																	
FUEL		BBL	150		150		FIRE DRILL						0	0																	
ELECTRICITY		KW	0		0		MOVING OUT OF WAY OF TRAFFIC						0	0																	
LUBRICANTS		GAL	0		0		MISCELLANEOUS (EXPLAIN IN REMARKS)						0	0																	
MOB DATE			DREDGE START			DEMOB DATE			TOTAL NON-EFFECTIVE TIME						24	0															
11/15/2019			11/15/2019						PCT. OF NON-EFFECTIVE						100%																
									TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						24	0															

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO.	
						Page 92 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		46	
DREDGE		Kelly L - Cutter/Suction				DATE	
						12/30/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 47	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 12/31/2019											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER			NO. OF CREW MEMBERS																
PIPELINE		DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER	TOTAL																
24		0		3500		24		0		10		0		0	10																
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK				REACH DREDGED; STATION TO STATION				DISPOSAL AREA USED				QTY DEPOSITED GROSS (CY) 0		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254																	
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%	OTHER 100%														
CHANNEL CONDITION				AVERAGE DEPTH				BEFORE DREDGING 0				AFTER DREDGING 0																			
RIVER/TIDE STAGE		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																					
		MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																					
WEATHER CONDITION				WEATHER Weather Caused No Delay				TEMP (min/max) 47 °F / 64 °F		VISIBILITY 3 MI		WIND NE 10-15 MPH																			
WORK PERFORMED								DISTRIBUTION OF WORK																							
ITEM		UNIT		QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.																		
AVERAGE WIDTH OF CUT		FT		0				PUMPING OR DREDGING				0	0																		
TOTAL ADVANCE THIS PERIOD		FT		0				PCT OF EFFECTIVE TIME				0%																			
TOTAL ADVANCE PREVIOUSLY		FT		4,323				BOOSTER (IN LINE)																							
TOTAL ADVANCE TO DATE		FT		4,323				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																							
SCOWS LOADED		NUMBER		0				HANDLING PIPE LINES				0	0																		
AVERAGE LOAD PER SCOW		CY		0				HANDLING ANCHOR LINES				0	0																		
FLOATING PIPE		0		SHORE PIPE		0		SUBMERGED PIPE		0		CLEARING PUMP AND PUMP LINES		0	0																
TOTAL LENGTH OF DISCHARGE PIPE		FT		0				CLEARING CUTTER AND SUCTION HEAD				0	0																		
CUBIC YARDS REMOVED		GROSS		CREDITED				WAITING FOR SCOWS				0	0																		
AMOUNT DREDGE THIS DATE		0		0				TO AND FROM WHARF OR ANCHORAGE				0	0																		
AMOUNT PREVIOUSLY REPORTED		104,254		104,254				CHANGING LOCATION OF PLANT ON JOB				0	0																		
TOTAL AMOUNT DREDGED TO DATE		104,254		104,254				LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0																		
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA				SHORE LINE AND SHORE WORK				0	0																		
OPERATING SUPPLIES						WAITING FOR BOOSTER				0	0																				
COMMODITY		CONSUMED		CREDITED				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0																		
ITEM		UNIT		QUANTITY		QUANTITY		WAITING FOR ATTENDANT PLANT				0	0																		
FUEL		BBL		100		100		PREPARATION AND MAKING UP TOW				0	0																		
ELECTRICITY		KW		0		0		TRANSFERRING PLANT BETWEEN WORKS				0	0																		
LUBRICANTS		GAL		0		0		LAY TIME OFF SHIFT AND SATURDAYS				0	0																		
MOB DATE		DREDGE START		DEMOB DATE				SUNDAYS AND HOLIDAYS				24	0																		
11/15/2019		11/15/2019						FIRE DRILL				0	0																		
								MOVING OUT OF WAY OF TRAFFIC				0	0																		
								MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0																		
								TOTAL NON-EFFECTIVE TIME				24	0																		
								PCT. OF NON-EFFECTIVE				100%																			
								TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				24	0																		

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO. Page 94 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		47	
DREDGE		Kelly L - Cutter/Suction				DATE 12/31/2019	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO. Page 95 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC				CONTRACTOR Inland Dredging				REPORT NO. 48	
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE 01/01/2020			
DREDGE		NAME AND TYPE Kelly L - Cutter/Suction				SHIFTS PER DAY 2		DAYS PER WEEK 7			
		SIZE		HORSEPOWER		NO. OF CREW MEMBERS					
		PIPELINE 24	DIPPER OR BUCKET 0	DREDGE PUMP 3500	SUCTION PIPE JET 24	CUTTER OR BUCKET 0	DREDGE 8	SHORE 0	OTHER 0	TOTAL 8	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY) 0		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254		
CHARACTER OF MATERIAL (%)		GRAVEL 0%	SAND 0%	CLAY 0%	MUD 0%	SILT 0%	HARDPAN 0%	STONE 0%	SHELL 0%	OTHER 100%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING 0		AFTER DREDGING 0				
RIVER/TIDE STAGE		MIN 0	TIME 00:00	MAX 0	TIME 00:00	GAGE LOCATION					
		MIN 0	TIME 00:00	MAX 0	TIME 00:00	GAGE DATUM					
WEATHER CONDITION		WEATHER Weather Caused No Delay			TEMP (min/max) 48 °F / 67 °F		VISIBILITY 3 MI		WIND SE 5-10 MPH		
WORK PERFORMED					DISTRIBUTION OF WORK						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)			HR.	MIN.	
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING			0	0	
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME			0%		
TOTAL ADVANCE PREVIOUSLY		FT		4,323		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		4,323		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES			0	0	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES			0	0	
FLOATING PIPE 0		SHORE PIPE 0		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES			0	0	
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		CLEARING CUTTER AND SUCTION HEAD			0	0	
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS			0	0	
AMOUNT DREDGE THIS DATE		0		0		TO AND FROM WHARF OR ANCHORAGE			0	0	
AMOUNT PREVIOUSLY REPORTED		104,254		104,254		CHANGING LOCATION OF PLANT ON JOB			0	0	
TOTAL AMOUNT DREDGED TO DATE		104,254		104,254		LOSS DUE TO OPPOSING NATURAL ELEMENTS			0	0	
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		SHORE LINE AND SHORE WORK			0	0	
OPERATING SUPPLIES						WAITING FOR BOOSTER			0	0	
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)			0	0	
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT			0	0	
FUEL		BBL		110		PREPARATION AND MAKING UP TOW			0	0	
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS			0	0	
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS			0	0	
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS			24	0	
11/15/2019		11/15/2019				FIRE DRILL			0	0	
						MOVING OUT OF WAY OF TRAFFIC			0	0	
						MISCELLANEOUS (EXPLAIN IN REMARKS)			0	0	
						TOTAL NON-EFFECTIVE TIME			24	0	
						PCT. OF NON-EFFECTIVE			100%		
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)			24	0	

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO. Page 96 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		48	
DREDGE		Kelly L - Cutter/Suction				DATE 01/01/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Towing Vessel	Cardinal	0	00:00	CESSATION		0	0
Tender Vessel	Mr. Gus	0	24:00	COLLISIONS		0	0
Tender Vessel	Tiger	0	24:00	MISCELLANEOUS		0	0
Tender Vessel	Rebel	0	24:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 49	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 01/02/2020											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET					DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET			DREDGE		SHORE		OTHER		TOTAL								
24					0					3500		24		0			10		0		0		10								
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION					DISPOSAL AREA USED					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																		
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 61 °F / 74 °F			VISIBILITY 3 MI		WIND SSE 10-15 MPH																
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)								HR.		MIN.											
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING								0		0											
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME								0%													
TOTAL ADVANCE PREVIOUSLY			FT			4,323				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			4,323				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES								0		0											
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES								0		0											
FLOATING PIPE			0			SHORE PIPE				0				SUBMERGED PIPE				0				0		0							
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				TO AND FROM WHARF OR ANCHORAGE								0		0											
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB								0		0											
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS								0		0											
AMOUNT PREVIOUSLY REPORTED			104,254			104,254				SHORE LINE AND SHORE WORK								0		0											
TOTAL AMOUNT DREDGED TO DATE			104,254			104,254				WAITING FOR BOOSTER								0		0											
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)								0		0											
										WAITING FOR ATTENDANT PLANT								0		0											
										PREPARATION AND MAKING UP TOW								0		0											
										TRANSFERRING PLANT BETWEEN WORKS								0		0											
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS								0		0											
ITEM		UNIT	QUANTITY			QUANTITY				SUNDAYS AND HOLIDAYS								24		0											
FUEL		BBL	100			100				FIRE DRILL								0		0											
ELECTRICITY		KW	0			0				MOVING OUT OF WAY OF TRAFFIC								0		0											
LUBRICANTS		GAL	0			0				MISCELLANEOUS (EXPLAIN IN REMARKS)								0		0											
MOB DATE			DREDGE START			DEMOB DATE				TOTAL NON-EFFECTIVE TIME								24		0											
11/15/2019			11/15/2019							PCT. OF NON-EFFECTIVE								100%													
										TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)								24		0											

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO.	
						Page 98 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		49	
DREDGE		Kelly L - Cutter/Suction				DATE	
						01/02/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 50	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 01/03/2020											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL												
24					0		3500		24		0		22		0		0		22												
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION					DISPOSAL AREA USED					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																		
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 55 °F / 71 °F			VISIBILITY 2 MI		WIND SSW 10-15 MPH																
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)								HR.		MIN.											
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING								0		0											
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME								0%													
TOTAL ADVANCE PREVIOUSLY			FT			4,323				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			4,323				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES								0		0											
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES								0		0											
FLOATING PIPE			0			SHORE PIPE			0			SUBMERGED PIPE			0			CLEARING PUMP AND PUMP LINES								0		0			
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				CLEARING CUTTER AND SUCTION HEAD								0		0											
CUBIC YARDS REMOVED			GROSS			CREDITED				WAITING FOR SCOWS								0		0											
AMOUNT DREDGE THIS DATE			0			0				TO AND FROM WHARF OR ANCHORAGE								0		0											
AMOUNT PREVIOUSLY REPORTED			104,254			104,254				CHANGING LOCATION OF PLANT ON JOB								0		0											
TOTAL AMOUNT DREDGED TO DATE			104,254			104,254				LOSS DUE TO OPPOSING NATURAL ELEMENTS								0		0											
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				SHORE LINE AND SHORE WORK								0		0											
OPERATING SUPPLIES										WAITING FOR BOOSTER								0		0											
COMMODITY			CONSUMED			CREDITED				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)								0		0											
ITEM		UNIT		QUANTITY		QUANTITY		WAITING FOR ATTENDANT PLANT								0		0													
FUEL		BBL		100		100		PREPARATION AND MAKING UP TOW								0		0													
ELECTRICITY		KW		0		0		TRANSFERRING PLANT BETWEEN WORKS								0		0													
LUBRICANTS		GAL		0		0		LAY TIME OFF SHIFT AND SATURDAYS								0		0													
MOB DATE			DREDGE START			DEMOB DATE			SUNDAYS AND HOLIDAYS								0		0												
11/15/2019			11/15/2019			11/15/2019			FIRE DRILL								0		0												
									MOVING OUT OF WAY OF TRAFFIC								0		0												
									MISCELLANEOUS (EXPLAIN IN REMARKS)								0		0												
									TOTAL NON-EFFECTIVE TIME								0		0												
									PCT. OF NON-EFFECTIVE								0%														
									TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)								0		0												

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO. Page 100 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		50	
DREDGE		Kelly L - Cutter/Suction				DATE 01/03/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS		HR	MIN	
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS	0	0	
Towing Vessel	Cardinal	0	00:00	CESSATION	0	0	
Tender Vessel	Mr. Gus	0	24:00	COLLISIONS	0	0	
Tender Vessel	Tiger	0	24:00	MISCELLANEOUS	24	0	
Tender Vessel	Rebel	0	24:00	TOTAL LOST TIME	24	0	
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	100%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD	24	0	

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO. Page 101 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC				CONTRACTOR Inland Dredging				REPORT NO. 51	
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE 01/04/2020			
DREDGE		NAME AND TYPE Kelly L - Cutter/Suction				SHIFTS PER DAY 2		DAYS PER WEEK 7			
		SIZE		HORSEPOWER		NO. OF CREW MEMBERS					
		PIPELINE 24	DIPPER OR BUCKET 0	DREDGE PUMP 3500	SUCTION PIPE JET 24	CUTTER OR BUCKET 0	DREDGE 31	SHORE 0	OTHER 0	TOTAL 31	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION			DISPOSAL AREA USED		QTY DEPOSITED GROSS (CY) 0		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254		
CHARACTER OF MATERIAL (%)		GRAVEL 0%	SAND 0%	CLAY 0%	MUD 0%	SILT 0%	HARDPAN 0%	STONE 0%	SHELL 0%	OTHER 100%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING 0		AFTER DREDGING 0				
RIVER/TIDE STAGE		MIN 0	TIME 00:00	MAX 0	TIME 00:00	GAGE LOCATION					
		MIN 0	TIME 00:00	MAX 0	TIME 00:00	GAGE DATUM					
WEATHER CONDITION		WEATHER Weather Caused No Delay			TEMP (min/max) 50 °F / 73 °F		VISIBILITY 3 MI		WIND NW 15-20 MPH		
WORK PERFORMED					DISTRIBUTION OF WORK						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)			HR.	MIN.	
AVERAGE WIDTH OF CUT		FT		0		PUMPING OR DREDGING			0	0	
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME			0%		
TOTAL ADVANCE PREVIOUSLY		FT		4,323		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		4,323		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES			0	0	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES			0	0	
FLOATING PIPE 0		SHORE PIPE 0		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES			0	0	
TOTAL LENGTH OF DISCHARGE PIPE		FT		0		CLEARING CUTTER AND SUCTION HEAD			0	0	
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS			0	0	
AMOUNT DREDGE THIS DATE		0		0		TO AND FROM WHARF OR ANCHORAGE			0	0	
AMOUNT PREVIOUSLY REPORTED		104,254		104,254		CHANGING LOCATION OF PLANT ON JOB			0	0	
TOTAL AMOUNT DREDGED TO DATE		104,254		104,254		LOSS DUE TO OPPOSING NATURAL ELEMENTS			0	0	
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		SHORE LINE AND SHORE WORK			0	0	
OPERATING SUPPLIES						WAITING FOR BOOSTER			0	0	
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)			0	0	
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT			0	0	
FUEL		BBL		455		PREPARATION AND MAKING UP TOW			0	0	
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS			0	0	
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS			0	0	
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS			0	0	
11/15/2019		11/15/2019				FIRE DRILL			0	0	
						MOVING OUT OF WAY OF TRAFFIC			0	0	
						MISCELLANEOUS (EXPLAIN IN REMARKS)			0	0	
						TOTAL NON-EFFECTIVE TIME			0	0	
						PCT. OF NON-EFFECTIVE			0%		
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)			0	0	

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO. Page 102 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		51	
DREDGE		Kelly L - Cutter/Suction				DATE 01/04/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Towing Vessel	Cardinal	0	00:00	CESSATION		0	0
Tender Vessel	Mr. Gus	0	24:00	COLLISIONS		0	0
Tender Vessel	Tiger	0	24:00	MISCELLANEOUS		24	0
Tender Vessel	Rebel	0	24:00	TOTAL LOST TIME		24	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	100%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 52	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 01/05/2020											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL												
24					0		3500		24		0		31		0		0		31												
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION					DISPOSAL AREA USED					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 104,254													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 0%		CLAY 0%		MUD 0%		SILT 0%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 100%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 0					AFTER DREDGING 0																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM																		
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 34 °F / 62 °F		VISIBILITY 3 MI		WIND W 5-10 MPH																	
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)						HR.		MIN.													
AVERAGE WIDTH OF CUT			FT			0				PUMPING OR DREDGING						0		0													
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME						0%															
TOTAL ADVANCE PREVIOUSLY			FT			4,323				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			4,323				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES						0		0													
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES						0		0													
FLOATING PIPE			0			SHORE PIPE				0				SUBMERGED PIPE				0													
TOTAL LENGTH OF DISCHARGE PIPE			FT			0				TO AND FROM WHARF OR ANCHORAGE						0		0													
CUBIC YARDS REMOVED			GROSS			CREDITED				CHANGING LOCATION OF PLANT ON JOB						0		0													
AMOUNT DREDGE THIS DATE			0			0				LOSS DUE TO OPPOSING NATURAL ELEMENTS						0		0													
AMOUNT PREVIOUSLY REPORTED			104,254			104,254				SHORE LINE AND SHORE WORK						0		0													
TOTAL AMOUNT DREDGED TO DATE			104,254			104,254				WAITING FOR BOOSTER						0		0													
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)						0		0													
										WAITING FOR ATTENDANT PLANT						0		0													
										PREPARATION AND MAKING UP TOW						0		0													
										TRANSFERRING PLANT BETWEEN WORKS						0		0													
COMMODITY			CONSUMED			CREDITED				LAY TIME OFF SHIFT AND SATURDAYS						0		0													
ITEM		UNIT	QUANTITY			QUANTITY				SUNDAYS AND HOLIDAYS						0		0													
FUEL		BBL	100			100				FIRE DRILL						0		0													
ELECTRICITY		KW	0			0				MOVING OUT OF WAY OF TRAFFIC						0		0													
LUBRICANTS		GAL	0			0				MISCELLANEOUS (EXPLAIN IN REMARKS)						0		0													
MOB DATE			DREDGE START			DEMOB DATE				TOTAL NON-EFFECTIVE TIME						0		0													
11/15/2019			11/15/2019							PCT. OF NON-EFFECTIVE						0%															
										TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)						0		0													

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO. Page 104 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		52	
DREDGE		ATTENDANT PLANT				DATE	
		Kelly L - Cutter/Suction				01/05/2020	
				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		24	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		24	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	100%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO. Page 105 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC				CONTRACTOR Inland Dredging				REPORT NO. 53	
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE 01/06/2020			
DREDGE		NAME AND TYPE Kelly L - Cutter/Suction				SHIFTS PER DAY 2		DAYS PER WEEK 7			
		SIZE		HORSEPOWER		NO. OF CREW MEMBERS					
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL	
		24	0	3500	24	0	28	6	0	34	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION Sta. 8+88 to 9+65			DISPOSAL AREA USED Upland		QTY DEPOSITED GROSS (CY) 1,460		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 105,714		
CHARACTER OF MATERIAL (%)		GRAVEL 0%	SAND 80%	CLAY 0%	MUD 0%	SILT 20%	HARDPAN 0%	STONE 0%	SHELL 0%	OTHER 0%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING 7.60		AFTER DREDGING 11.60				
RIVER/TIDE STAGE		MIN	0	TIME	00:00	MAX	0	TIME	00:00	GAGE LOCATION dock by the ferry	
		MIN	0	TIME	00:00	MAX	1	TIME	23:00	GAGE DATUM MLLW	
WEATHER CONDITION		WEATHER Weather Caused No Delay			TEMP (min/max) 47 °F / 62 °F		VISIBILITY 5 MI		WIND S 5-10 MPH		
WORK PERFORMED					DISTRIBUTION OF WORK						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.
AVERAGE WIDTH OF CUT		FT		120		PUMPING OR DREDGING				1	28
TOTAL ADVANCE THIS PERIOD		FT		77		PCT OF EFFECTIVE TIME				6%	
TOTAL ADVANCE PREVIOUSLY		FT		4,323		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		4,400		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				0	0
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				0	22
FLOATING PIPE 1,080		SHORE PIPE 210		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES				0	0
TOTAL LENGTH OF DISCHARGE PIPE		FT		1,290		CLEARING CUTTER AND SUCTION HEAD				0	37
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS				0	0
AMOUNT DREDGE THIS DATE		1,460		1,460		TO AND FROM WHARF OR ANCHORAGE				0	0
AMOUNT PREVIOUSLY REPORTED		104,254		104,254		CHANGING LOCATION OF PLANT ON JOB				0	0
TOTAL AMOUNT DREDGED TO DATE		105,714		105,714		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0
AMOUNT DREDGED PER PUMPING/CUTTING HR		995.45		995.45		SHORE LINE AND SHORE WORK				0	53
OPERATING SUPPLIES						WAITING FOR BOOSTER				0	0
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				0	0
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT				0	0
FUEL		BBL		1,050		PREPARATION AND MAKING UP TOW				0	0
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS				0	0
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS				0	0
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS				0	0
11/15/2019		11/15/2019				FIRE DRILL				0	0
						MOVING OUT OF WAY OF TRAFFIC				0	0
						MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0
						TOTAL NON-EFFECTIVE TIME				1	52
						PCT. OF NON-EFFECTIVE				8%	
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				3	20

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 106 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		53	
DREDGE		Kelly L - Cutter/Suction				DATE	
						01/06/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM		NAME OR NUMBER		H.P.	HOURS		
						HR	MIN
Dredge		Kelly L		3600	24:00	0	0
Tender Vessel		Mr. Gus		0	24:00	0	0
Tender Vessel		Tiger		0	24:00	0	0
Tender Vessel		Rebel		0	24:00	20	40
Towing Vessel		Cardinal		0	00:00	20	40
Barge		Anchor 028-954		0	24:00	86%	
Barge		Crane		0	24:00		
TOTAL TIME IN PERIOD						24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO. Page 107 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC				CONTRACTOR Inland Dredging				REPORT NO. 54	
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE 01/07/2020			
DREDGE		NAME AND TYPE Kelly L - Cutter/Suction				SHIFTS PER DAY 2		DAYS PER WEEK 7			
		SIZE		HORSEPOWER		NO. OF CREW MEMBERS					
		PIPELINE 24	DIPPER OR BUCKET 0	DREDGE PUMP 3500	SUCTION PIPE JET 24	CUTTER OR BUCKET 0	DREDGE 28	SHORE 6	OTHER 0	TOTAL 34	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION Sta. 9+65 to 13+82			DISPOSAL AREA USED Upland		QTY DEPOSITED GROSS (CY) 7,923		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 113,637		
CHARACTER OF MATERIAL (%)		GRAVEL 0%	SAND 80%	CLAY 0%	MUD 0%	SILT 20%	HARDPAN 0%	STONE 0%	SHELL 0%	OTHER 0%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING 7.60		AFTER DREDGING 11.60				
RIVER/TIDE STAGE		MIN	-0.50	TIME	05:00	MAX	0.50	TIME	01:00	GAGE LOCATION dock by the ferry	
		MIN	0	TIME	00:00	MAX	1.30	TIME	20:00	GAGE DATUM MLLW	
WEATHER CONDITION		WEATHER Weather Caused No Delay			TEMP (min/max) 34 °F / 63 °F		VISIBILITY 7 MI		WIND N 8.3 MPH		
WORK PERFORMED						DISTRIBUTION OF WORK					
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)			HR.	MIN.	
AVERAGE WIDTH OF CUT		FT		120		PUMPING OR DREDGING			13	54	
TOTAL ADVANCE THIS PERIOD		FT		417		PCT OF EFFECTIVE TIME			58%		
TOTAL ADVANCE PREVIOUSLY		FT		4,400		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		4,817		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES			0	36	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES			2	19	
FLOATING PIPE 1,330		SHORE PIPE 160		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES			2	59	
TOTAL LENGTH OF DISCHARGE PIPE		FT		1,490		CLEARING CUTTER AND SUCTION HEAD			0	46	
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS			0	0	
AMOUNT DREDGE THIS DATE		7,923		7,923		TO AND FROM WHARF OR ANCHORAGE			0	0	
AMOUNT PREVIOUSLY REPORTED		105,714		105,714		CHANGING LOCATION OF PLANT ON JOB			0	0	
TOTAL AMOUNT DREDGED TO DATE		113,637		113,637		LOSS DUE TO OPPOSING NATURAL ELEMENTS			0	0	
AMOUNT DREDGED PER PUMPING/CUTTING HR		570.00		570.00		SHORE LINE AND SHORE WORK			0	0	
OPERATING SUPPLIES						WAITING FOR BOOSTER			0	0	
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)			0	44	
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT			0	0	
FUEL		BBL		1,050		PREPARATION AND MAKING UP TOW			0	0	
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS			0	0	
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS			0	0	
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS			0	0	
11/15/2019		11/15/2019				FIRE DRILL			0	0	
						MOVING OUT OF WAY OF TRAFFIC			0	45	
						MISCELLANEOUS (EXPLAIN IN REMARKS)			1	57	
						TOTAL NON-EFFECTIVE TIME			10	6	
						PCT. OF NON-EFFECTIVE			42%		
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)			24	0	

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO.	
						Page 108 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		54	
DREDGE		Kelly L - Cutter/Suction				DATE	
						01/07/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 55	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 01/08/2020											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL												
24					0		3500		24		0		28		6		0		34												
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION Sta. 13+82 to 17+09					DISPOSAL AREA USED Upland					QTY DEPOSITED GROSS (CY) 7,267			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 120,904													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 80%		CLAY 0%		MUD 0%		SILT 20%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 0%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 7.60					AFTER DREDGING 11.60																
RIVER/TIDE STAGE		MIN		-0.50		TIME		06:00		MAX		0.70		TIME		01:00		GAGE LOCATION dock by the ferry													
		MIN		0		TIME		00:00		MAX		1.60		TIME		21:00		GAGE DATUM MLLW													
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 31 °F / 64 °F			VISIBILITY 6 MI			WIND E 4.1 MPH															
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM		UNIT			QUANTITY					EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)							HR.		MIN.												
AVERAGE WIDTH OF CUT		FT			150					PUMPING OR DREDGING							13		36												
TOTAL ADVANCE THIS PERIOD		FT			327					PCT OF EFFECTIVE TIME							57%														
TOTAL ADVANCE PREVIOUSLY		FT			4,817					BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE		FT			5,144					NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED		NUMBER			0					HANDLING PIPE LINES							4		27												
AVERAGE LOAD PER SCOW		CY			0					HANDLING ANCHOR LINES							1		6												
FLOATING PIPE		1,490			SHORE PIPE		240			SUBMERGED PIPE					0			CLEARING PUMP AND PUMP LINES							0		27				
TOTAL LENGTH OF DISCHARGE PIPE		FT			1,730					CLEARING CUTTER AND SUCTION HEAD							0		31												
CUBIC YARDS REMOVED		GROSS			CREDITED					WAITING FOR SCOWS							0		0												
AMOUNT DREDGE THIS DATE		7,267			7,267					TO AND FROM WHARF OR ANCHORAGE							0		0												
AMOUNT PREVIOUSLY REPORTED		113,637			113,637					CHANGING LOCATION OF PLANT ON JOB							0		0												
TOTAL AMOUNT DREDGED TO DATE		120,904			120,904					LOSS DUE TO OPPOSING NATURAL ELEMENTS							0		0												
AMOUNT DREDGED PER PUMPING/CUTTING HR		534.34			534.34					SHORE LINE AND SHORE WORK							2		19												
OPERATING SUPPLIES										WAITING FOR BOOSTER							0		0												
COMMODITY										CONSUMED			CREDITED					MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)							0		0				
ITEM		UNIT		QUANTITY			QUANTITY					WAITING FOR ATTENDANT PLANT							0		0										
FUEL		BBL		1,050			1,050					PREPARATION AND MAKING UP TOW							0		0										
ELECTRICITY		KW		0			0					TRANSFERRING PLANT BETWEEN WORKS							0		0										
LUBRICANTS		GAL		0			0					LAY TIME OFF SHIFT AND SATURDAYS							0		0										
MOB DATE		DREDGE START			DEMOB DATE					SUNDAYS AND HOLIDAYS							0		0												
11/15/2019		11/15/2019			11/15/2019					FIRE DRILL							0		0												
										MOVING OUT OF WAY OF TRAFFIC							1		34												
										MISCELLANEOUS (EXPLAIN IN REMARKS)							0		0												
										TOTAL NON-EFFECTIVE TIME							10		24												
										PCT. OF NON-EFFECTIVE							43%														
										TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)							24		0												

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 110 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		55	
DREDGE		Kelly L - Cutter/Suction				DATE	
						01/08/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO. Page 111 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC				CONTRACTOR Inland Dredging				REPORT NO. 56	
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE 01/09/2020			
DREDGE		NAME AND TYPE Kelly L - Cutter/Suction				SHIFTS PER DAY 2		DAYS PER WEEK 7			
		SIZE		HORSEPOWER		NO. OF CREW MEMBERS					
		PIPELINE 24	DIPPER OR BUCKET 0	DREDGE PUMP 3500	SUCTION PIPE JET 24	CUTTER OR BUCKET 0	DREDGE 28	SHORE 6	OTHER 0	TOTAL 34	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION Sta. 17+09 to 18+75			DISPOSAL AREA USED Upland		QTY DEPOSITED GROSS (CY) 3,689		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 124,593		
CHARACTER OF MATERIAL (%)		GRAVEL 0%	SAND 80%	CLAY 0%	MUD 0%	SILT 20%	HARDPAN 0%	STONE 0%	SHELL 0%	OTHER 0%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING 7.60		AFTER DREDGING 11.60				
RIVER/TIDE STAGE		MIN	0.40	TIME	08:00	MAX	1.60	TIME	01:00	GAGE LOCATION dock by the ferry	
		MIN	0	TIME	00:00	MAX	0.70	TIME	14:00	GAGE DATUM MLLW	
WEATHER CONDITION		WEATHER Weather Caused Critical Delay			TEMP (min/max) 40 °F / 68 °F		VISIBILITY 6 MI		WIND SE 9.6 MPH		
WORK PERFORMED						DISTRIBUTION OF WORK					
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)			HR.	MIN.	
AVERAGE WIDTH OF CUT		FT		150		PUMPING OR DREDGING			8	16	
TOTAL ADVANCE THIS PERIOD		FT		166		PCT OF EFFECTIVE TIME			34%		
TOTAL ADVANCE PREVIOUSLY		FT		5,144		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		5,310		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES			1	45	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES			0	47	
FLOATING PIPE 1,810		SHORE PIPE 240		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES			0	32	
TOTAL LENGTH OF DISCHARGE PIPE		FT		2,050		CLEARING CUTTER AND SUCTION HEAD			0	0	
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS			0	0	
AMOUNT DREDGE THIS DATE		3,689		3,689		TO AND FROM WHARF OR ANCHORAGE			0	0	
AMOUNT PREVIOUSLY REPORTED		120,904		120,904		CHANGING LOCATION OF PLANT ON JOB			0	0	
TOTAL AMOUNT DREDGED TO DATE		124,593		124,593		LOSS DUE TO OPPOSING NATURAL ELEMENTS			5	34	
AMOUNT DREDGED PER PUMPING/CUTTING HR		446.25		446.25		SHORE LINE AND SHORE WORK			1	9	
OPERATING SUPPLIES						WAITING FOR BOOSTER			0	0	
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)			0	0	
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT			0	0	
FUEL		BBL		1,470		PREPARATION AND MAKING UP TOW			0	0	
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS			0	0	
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS			0	0	
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS			0	0	
11/15/2019		11/15/2019				FIRE DRILL			0	0	
						MOVING OUT OF WAY OF TRAFFIC			1	52	
						MISCELLANEOUS (EXPLAIN IN REMARKS)			3	20	
						TOTAL NON-EFFECTIVE TIME			14	59	
						PCT. OF NON-EFFECTIVE			62%		
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)			23	15	

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO.	
						Page 112 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		56	
DREDGE		Kelly L - Cutter/Suction				DATE	
						01/09/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	45
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	45
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	3%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 57	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 01/10/2020											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET					DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET			DREDGE		SHORE		OTHER	TOTAL									
24					0					3500		24		0			28		6		0	34									
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION None					DISPOSAL AREA USED Upland					QTY DEPOSITED GROSS (CY) 0			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 124,593													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 80%		CLAY 0%		MUD 0%		SILT 20%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 0%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 7.60					AFTER DREDGING 11.60																
RIVER/TIDE STAGE					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE LOCATION dock by the ferry																		
					MIN 0		TIME 00:00		MAX 0		TIME 00:00		GAGE DATUM MLLW																		
WEATHER CONDITION					WEATHER Weather Caused Critical Delay					TEMP (min/max) 62 °F / 70 °F			VISIBILITY 4 MI			WIND SE 16.1 MPH															
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)								HR.		MIN.											
AVERAGE WIDTH OF CUT			FT			150				PUMPING OR DREDGING								0		0											
TOTAL ADVANCE THIS PERIOD			FT			0				PCT OF EFFECTIVE TIME								0%													
TOTAL ADVANCE PREVIOUSLY			FT			5,310				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			5,310				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES								0		0											
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES								0		0											
FLOATING PIPE 1,810			SHORE PIPE 240			SUBMERGED PIPE 0				CLEARING PUMP AND PUMP LINES								0		0											
TOTAL LENGTH OF DISCHARGE PIPE			FT			2,050				CLEARING CUTTER AND SUCTION HEAD								0		0											
CUBIC YARDS REMOVED			GROSS			CREDITED				WAITING FOR SCOWS								0		0											
AMOUNT DREDGE THIS DATE			0			0				TO AND FROM WHARF OR ANCHORAGE								0		0											
AMOUNT PREVIOUSLY REPORTED			124,593			124,593				CHANGING LOCATION OF PLANT ON JOB								0		0											
TOTAL AMOUNT DREDGED TO DATE			124,593			124,593				LOSS DUE TO OPPOSING NATURAL ELEMENTS								24		0											
AMOUNT DREDGED PER PUMPING/CUTTING HR			NA			NA				SHORE LINE AND SHORE WORK								0		0											
OPERATING SUPPLIES										WAITING FOR BOOSTER								0		0											
COMMODITY										CONSUMED				CREDITED				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)								0		0			
ITEM		UNIT		QUANTITY				QUANTITY				WAITING FOR ATTENDANT PLANT								0		0									
FUEL		BBL		100				100				PREPARATION AND MAKING UP TOW								0		0									
ELECTRICITY		KW		0				0				TRANSFERRING PLANT BETWEEN WORKS								0		0									
LUBRICANTS		GAL		0				0				LAY TIME OFF SHIFT AND SATURDAYS								0		0									
MOB DATE			DREDGE START			DEMOB DATE			SUNDAYS AND HOLIDAYS								0		0												
11/15/2019			11/15/2019						FIRE DRILL								0		0												
										MOVING OUT OF WAY OF TRAFFIC								0		0											
										MISCELLANEOUS (EXPLAIN IN REMARKS)								0		0											
										TOTAL NON-EFFECTIVE TIME								24		0											
										PCT. OF NON-EFFECTIVE								100%													
										TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)								24		0											

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 114 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		57	
DREDGE		Kelly L - Cutter/Suction				DATE	
						01/10/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Fuel 028-932	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO. Page 115 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC				CONTRACTOR Inland Dredging				REPORT NO. 58	
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE 01/11/2020			
DREDGE		NAME AND TYPE Kelly L - Cutter/Suction				SHIFTS PER DAY 2		DAYS PER WEEK 7			
		SIZE		HORSEPOWER		NO. OF CREW MEMBERS					
		PIPELINE 24	DIPPER OR BUCKET 0	DREDGE PUMP 3500	SUCTION PIPE JET 24	CUTTER OR BUCKET 0	DREDGE 28	SHORE 6	OTHER 0	TOTAL 34	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION None			DISPOSAL AREA USED Upland		QTY DEPOSITED GROSS (CY) 0		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 124,593		
CHARACTER OF MATERIAL (%)		GRAVEL 0%	SAND 80%	CLAY 0%	MUD 0%	SILT 20%	HARDPAN 0%	STONE 0%	SHELL 0%	OTHER 0%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING 7.60		AFTER DREDGING 11.60				
RIVER/TIDE STAGE		MIN 0	TIME 00:00	MAX 0	TIME 00:00	GAGE LOCATION dock by the ferry					
		MIN 0	TIME 00:00	MAX 0	TIME 00:00	GAGE DATUM MLLW					
WEATHER CONDITION		WEATHER Weather Caused Critical Delay			TEMP (min/max) 56 °F / 75 °F		VISIBILITY 4 MI		WIND SW 14.9 MPH		
WORK PERFORMED					DISTRIBUTION OF WORK						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)			HR.	MIN.	
AVERAGE WIDTH OF CUT		FT		150		PUMPING OR DREDGING			0	0	
TOTAL ADVANCE THIS PERIOD		FT		0		PCT OF EFFECTIVE TIME			0%		
TOTAL ADVANCE PREVIOUSLY		FT		5,310		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		5,310		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES			0	0	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES			0	0	
FLOATING PIPE 1,810		SHORE PIPE 240		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES			0	0	
TOTAL LENGTH OF DISCHARGE PIPE		FT		2,050		CLEARING CUTTER AND SUCTION HEAD			0	0	
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS			0	0	
AMOUNT DREDGE THIS DATE		0		0		TO AND FROM WHARF OR ANCHORAGE			0	0	
AMOUNT PREVIOUSLY REPORTED		124,593		124,593		CHANGING LOCATION OF PLANT ON JOB			0	0	
TOTAL AMOUNT DREDGED TO DATE		124,593		124,593		LOSS DUE TO OPPOSING NATURAL ELEMENTS			24	0	
AMOUNT DREDGED PER PUMPING/CUTTING HR		NA		NA		SHORE LINE AND SHORE WORK			0	0	
OPERATING SUPPLIES						WAITING FOR BOOSTER			0	0	
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)			0	0	
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT			0	0	
FUEL		BBL		100		PREPARATION AND MAKING UP TOW			0	0	
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS			0	0	
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS			0	0	
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS			0	0	
11/15/2019		11/15/2019				FIRE DRILL			0	0	
						MOVING OUT OF WAY OF TRAFFIC			0	0	
						MISCELLANEOUS (EXPLAIN IN REMARKS)			0	0	
						TOTAL NON-EFFECTIVE TIME			24	0	
						PCT. OF NON-EFFECTIVE			100%		
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)			24	0	

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO.	
						Page 116 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		58	
DREDGE		Kelly L - Cutter/Suction				DATE	
						01/11/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO. Page 117 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC				CONTRACTOR Inland Dredging				REPORT NO. 59	
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE 01/12/2020			
DREDGE		NAME AND TYPE Kelly L - Cutter/Suction				SHIFTS PER DAY 2		DAYS PER WEEK 7			
		SIZE		HORSEPOWER		NO. OF CREW MEMBERS					
		PIPELINE	DIPPER OR BUCKET	DREDGE PUMP	SUCTION PIPE JET	CUTTER OR BUCKET	DREDGE	SHORE	OTHER	TOTAL	
		24	0	3500	24	0	28	6	0	34	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION Station 3+44 to 7+20			DISPOSAL AREA USED Upland		QTY DEPOSITED GROSS (CY) 5,849		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 130,442		
CHARACTER OF MATERIAL (%)		GRAVEL 0%	SAND 80%	CLAY 0%	MUD 0%	SILT 20%	HARDPAN 0%	STONE 0%	SHELL 0%	OTHER 0%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING 7.60		AFTER DREDGING 11.60				
RIVER/TIDE STAGE		MIN	0.60	TIME	11:00	MAX	2.20	TIME	22:00	GAGE LOCATION dock by the ferry	
		MIN	0	TIME	00:00	MAX	0	TIME	00:00	GAGE DATUM MLLW	
WEATHER CONDITION		WEATHER Weather Caused No Delay			TEMP (min/max) 51 °F / 64 °F		VISIBILITY 4 MI		WIND N 5.2 MPH		
WORK PERFORMED						DISTRIBUTION OF WORK					
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)			HR.	MIN.	
AVERAGE WIDTH OF CUT		FT		100		PUMPING OR DREDGING			7	26	
TOTAL ADVANCE THIS PERIOD		FT		376		PCT OF EFFECTIVE TIME			31%		
TOTAL ADVANCE PREVIOUSLY		FT		5,310		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		5,686		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES			0	0	
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES			0	11	
FLOATING PIPE 1,120		SHORE PIPE 240		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES			2	5	
TOTAL LENGTH OF DISCHARGE PIPE		FT		1,360		CLEARING CUTTER AND SUCTION HEAD			0	34	
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS			0	0	
AMOUNT DREDGE THIS DATE		5,849		5,849		TO AND FROM WHARF OR ANCHORAGE			0	0	
AMOUNT PREVIOUSLY REPORTED		124,593		124,593		CHANGING LOCATION OF PLANT ON JOB			0	0	
TOTAL AMOUNT DREDGED TO DATE		130,442		130,442		LOSS DUE TO OPPOSING NATURAL ELEMENTS			7	0	
AMOUNT DREDGED PER PUMPING/CUTTING HR		786.86		786.86		SHORE LINE AND SHORE WORK			0	11	
OPERATING SUPPLIES						WAITING FOR BOOSTER			0	0	
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)			0	0	
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT			0	0	
FUEL		BBL		630		PREPARATION AND MAKING UP TOW			0	0	
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS			0	0	
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS			0	0	
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS			0	0	
11/15/2019		11/15/2019				FIRE DRILL			0	0	
						MOVING OUT OF WAY OF TRAFFIC			3	15	
						MISCELLANEOUS (EXPLAIN IN REMARKS)			3	18	
						TOTAL NON-EFFECTIVE TIME			16	34	
						PCT. OF NON-EFFECTIVE			69%		
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)			24	0	

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 118 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		59	
DREDGE		Kelly L - Cutter/Suction				DATE	
						01/12/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO. Page 119 of 123	
CONTRACT NO. W9127819D0039 W9127819F0388		CONTRACT TITLE Main. Dredging of Dauphin Island VC				CONTRACTOR Inland Dredging				REPORT NO. 60	
CHARACTER OF REPORT		<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL						DATE 01/13/2020			
DREDGE		NAME AND TYPE Kelly L - Cutter/Suction				SHIFTS PER DAY 2		DAYS PER WEEK 7			
		SIZE		HORSEPOWER		NO. OF CREW MEMBERS					
		PIPELINE 24	DIPPER OR BUCKET 0	DREDGE PUMP 3500	SUCTION PIPE JET 24	CUTTER OR BUCKET 0	DREDGE 28	SHORE 6	OTHER 0	TOTAL 34	
LOCATION/CHANNEL OF WORK											
LOCATION OF WORK		REACH DREDGED; STATION TO STATION Station 7+20 to 8+84, 18+65 to 20+50, 4+25 to 2+30			DISPOSAL AREA USED Upland		QTY DEPOSITED GROSS (CY) 12,088		CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 142,530		
CHARACTER OF MATERIAL (%)		GRAVEL 0%	SAND 80%	CLAY 0%	MUD 0%	SILT 20%	HARDPAN 0%	STONE 0%	SHELL 0%	OTHER 0%	
CHANNEL CONDITION		AVERAGE DEPTH			BEFORE DREDGING 7.60		AFTER DREDGING 11.60				
RIVER/TIDE STAGE		MIN 0.40	TIME 11:00	MAX 2.20	TIME 01:00	GAGE LOCATION dock by the ferry					
		MIN 0	TIME 00:00	MAX 2	TIME 23:00	GAGE DATUM MLLW					
WEATHER CONDITION		WEATHER Weather Caused No Delay			TEMP (min/max) 60 °F / 68 °F		VISIBILITY .5 MI		WIND SE 4.8 MPH		
WORK PERFORMED					DISTRIBUTION OF WORK						
ITEM		UNIT		QUANTITY		EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)				HR.	MIN.
AVERAGE WIDTH OF CUT		FT		150		PUMPING OR DREDGING				12	4
TOTAL ADVANCE THIS PERIOD		FT		544		PCT OF EFFECTIVE TIME				50%	
TOTAL ADVANCE PREVIOUSLY		FT		5,686		BOOSTER (IN LINE)					
TOTAL ADVANCE TO DATE		FT		6,230		NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)					
SCOWS LOADED		NUMBER		0		HANDLING PIPE LINES				1	20
AVERAGE LOAD PER SCOW		CY		0		HANDLING ANCHOR LINES				1	8
FLOATING PIPE 1,930		SHORE PIPE 240		SUBMERGED PIPE 0		CLEARING PUMP AND PUMP LINES				1	15
TOTAL LENGTH OF DISCHARGE PIPE		FT		2,170		CLEARING CUTTER AND SUCTION HEAD				0	55
CUBIC YARDS REMOVED		GROSS		CREDITED		WAITING FOR SCOWS				0	0
AMOUNT DREDGE THIS DATE		12,088		12,088		TO AND FROM WHARF OR ANCHORAGE				0	0
AMOUNT PREVIOUSLY REPORTED		130,442		130,442		CHANGING LOCATION OF PLANT ON JOB				5	46
TOTAL AMOUNT DREDGED TO DATE		142,530		142,530		LOSS DUE TO OPPOSING NATURAL ELEMENTS				0	0
AMOUNT DREDGED PER PUMPING/CUTTING HR		1,001.77		1,001.77		SHORE LINE AND SHORE WORK				0	0
OPERATING SUPPLIES						WAITING FOR BOOSTER				0	0
COMMODITY		CONSUMED		CREDITED		MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)				1	32
ITEM		UNIT		QUANTITY		WAITING FOR ATTENDANT PLANT				0	0
FUEL		BBL		1,890		PREPARATION AND MAKING UP TOW				0	0
ELECTRICITY		KW		0		TRANSFERRING PLANT BETWEEN WORKS				0	0
LUBRICANTS		GAL		0		LAY TIME OFF SHIFT AND SATURDAYS				0	0
MOB DATE		DREDGE START		DEMOB DATE		SUNDAYS AND HOLIDAYS				0	0
11/15/2019		11/15/2019				FIRE DRILL				0	0
						MOVING OUT OF WAY OF TRAFFIC				0	0
						MISCELLANEOUS (EXPLAIN IN REMARKS)				0	0
						TOTAL NON-EFFECTIVE TIME				11	56
						PCT. OF NON-EFFECTIVE				50%	
						TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)				24	0

QUALITY CONTROL REPORT-BUCKET/PIPELINE						PAGE NO. Page 120 of 123	
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		60	
DREDGE		ATTENDANT PLANT				DATE	
		Kelly L - Cutter/Suction				01/13/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Dredge	Kelly L	3600	24:00	MAJOR REPAIRS		0	0
Tender Vessel	Mr. Gus	0	24:00	CESSATION		0	0
Tender Vessel	Tiger	0	24:00	COLLISIONS		0	0
Tender Vessel	Rebel	0	24:00	MISCELLANEOUS		0	0
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		0	0
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	0%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.					
QC REPRESENTATIVE'S SIGNATURE			DATE		SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE										PAGE NO.																					
CONTRACT NO. W9127819D0039 W9127819F0388										CONTRACT TITLE Main. Dredging of Dauphin Island VC										CONTRACTOR Inland Dredging										REPORT NO. 61	
CHARACTER OF REPORT										<input checked="" type="checkbox"/> MAINTENANCE <input type="checkbox"/> NEW WORK <input type="checkbox"/> ENVIRONMENTAL										DATE 01/14/2020											
DREDGE										NAME AND TYPE Kelly L - Cutter/Suction					SHIFTS PER DAY 2			DAYS PER WEEK 7													
										SIZE		HORSEPOWER					NO. OF CREW MEMBERS														
PIPELINE					DIPPER OR BUCKET		DREDGE PUMP		SUCTION PIPE JET		CUTTER OR BUCKET		DREDGE		SHORE		OTHER		TOTAL												
24					0		3500		24		0		28		6		0		34												
LOCATION/CHANNEL OF WORK																															
LOCATION OF WORK					REACH DREDGED; STATION TO STATION Station 2+30 to 0+44					DISPOSAL AREA USED Upland					QTY DEPOSITED GROSS (CY) 2,902			CUMMULATIVE AND QTY DEPOSIT FOR DA (CY) 145,432													
CHARACTER OF MATERIAL (%)		GRAVEL 0%		SAND 80%		CLAY 0%		MUD 0%		SILT 20%		HARDPAN 0%		STONE 0%		SHELL 0%		OTHER 0%													
CHANNEL CONDITION					AVERAGE DEPTH					BEFORE DREDGING 7.60					AFTER DREDGING 11.60																
RIVER/TIDE STAGE		MIN		1.20		TIME		07:00		MAX		2		TIME		01:00		GAGE LOCATION dock by the ferry													
		MIN		0		TIME		00:00		MAX		0		TIME		00:00		GAGE DATUM MLLW													
WEATHER CONDITION					WEATHER Weather Caused No Delay					TEMP (min/max) 60 °F / 70 °F					VISIBILITY .5 MI			WIND SE 4.5 MPH													
WORK PERFORMED										DISTRIBUTION OF WORK																					
ITEM			UNIT			QUANTITY				EFFECTIVE WORKING TIME (CHARGEABLE TO COST OF WORK)								HR.		MIN.											
AVERAGE WIDTH OF CUT			FT			100				PUMPING OR DREDGING								5		45											
TOTAL ADVANCE THIS PERIOD			FT			186				PCT OF EFFECTIVE TIME								24%													
TOTAL ADVANCE PREVIOUSLY			FT			6,230				BOOSTER (IN LINE)																					
TOTAL ADVANCE TO DATE			FT			6,416				NON-EFFECTIVE WORKING TIME (CHARGEABLE COST OF WORK)																					
SCOWS LOADED			NUMBER			0				HANDLING PIPE LINES								0		0											
AVERAGE LOAD PER SCOW			CY			0				HANDLING ANCHOR LINES								0		8											
FLOATING PIPE			1,370			SHORE PIPE 280				SUBMERGED PIPE 0				CLEARING PUMP AND PUMP LINES								2		9							
TOTAL LENGTH OF DISCHARGE PIPE			FT			1,650				CLEARING CUTTER AND SUCTION HEAD								0		20											
CUBIC YARDS REMOVED			GROSS			CREDITED				WAITING FOR SCOWS								0		0											
AMOUNT DREDGE THIS DATE			2,902			2,902				TO AND FROM WHARF OR ANCHORAGE								0		0											
AMOUNT PREVIOUSLY REPORTED			142,530			142,530				CHANGING LOCATION OF PLANT ON JOB								0		0											
TOTAL AMOUNT DREDGED TO DATE			145,432			145,432				LOSS DUE TO OPPOSING NATURAL ELEMENTS								0		0											
AMOUNT DREDGED PER PUMPING/CUTTING HR			504.70			504.70				SHORE LINE AND SHORE WORK								3		0											
OPERATING SUPPLIES										WAITING FOR BOOSTER								0		0											
COMMODITY										CONSUMED								CREDITED													
ITEM		UNIT		QUANTITY				QUANTITY				MINOR OPERATING REPAIRS (EXPLAIN IN REMARKS)								0		0									
FUEL		BBL		630				630				WAITING FOR ATTENDANT PLANT								0		0									
ELECTRICITY		KW		0				0				PREPARATION AND MAKING UP TOW								0		0									
LUBRICANTS		GAL		0				0				TRANSFERRING PLANT BETWEEN WORKS								0		0									
MOB DATE			DREDGE START			DEMOB DATE			LAY TIME OFF SHIFT AND SATURDAYS								0		0												
11/15/2019			11/15/2019						SUNDAYS AND HOLIDAYS								0		0												
										FIRE DRILL								0		0											
										MOVING OUT OF WAY OF TRAFFIC								0		0											
										MISCELLANEOUS (EXPLAIN IN REMARKS)								0		0											
										TOTAL NON-EFFECTIVE TIME								5		37											
										PCT. OF NON-EFFECTIVE								23%													
										TOTAL EFFECTIVE AND NON-EFFECTIVE TIME (CHARGEABLE TO COST OF WORK)								11		22											

QUALITY CONTROL REPORT-BUCKET/PIPELINE					PAGE NO.		
					Page 122 of 123		
CONTRACT NO.		CONTRACT TITLE		CONTRACTOR		REPORT NO.	
W9127819D0039 W9127819F0388		Main. Dredging of Dauphin Island VC		Inland Dredging		61	
DREDGE		Kelly L - Cutter/Suction				DATE	
						01/14/2020	
ATTENDANT PLANT				LOST TIME (NOT CHARGEABLE TO COST OF WORK)			
ITEM	NAME OR NUMBER	H.P.	HOURS			HR	MIN
Tender Vessel	Rebel	0	24:00	MAJOR REPAIRS		0	0
Dredge	Kelly L	3600	24:00	CESSATION		0	0
Tender Vessel	Mr. Gus	0	24:00	COLLISIONS		0	0
Tender Vessel	Tiger	0	24:00	MISCELLANEOUS		12	38
Towing Vessel	Cardinal	0	00:00	TOTAL LOST TIME		12	38
Barge	Anchor 028-954	0	24:00	PERCENTAGE OF TOTAL TIME	53%		
Barge	Crane	0	24:00	TOTAL TIME IN PERIOD		24	0

QC NARRATIVE(S)

CONTRACTOR CERTIFICATION		On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.			
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE

QUALITY CONTROL REPORT-BUCKET/PIPELINE

CONTRACT NO. W9127819D0039 W9127819F0388	CONTRACT TITLE Main. Dredging of Dauphin Island VC	CONTRACTOR Inland Dredging	REPORT NO. 61
--	--	--------------------------------------	-------------------------

ATTENDANT PLANT OVERFLOW

ITEM	NAME OR NUMBER	H.P.	HOURS
Barge	Deck 028-951	0	24:00
Crane	Dragline American 7250	0	02:00
Barge	Fuel 028-932	0	24:00
Barge	Hopper 028-942	0	24:00
Barge	Hopper 028-943	0	24:00
Barge	Ramp 028-949	0	24:00
Survey Boat	ARC	0	12:00
Barge	Spill 028-939	0	24:00