

BOREHOLE NO.: MW-222 TOTAL DEPTH: 96 ft.

PROJECT INFORMATION

PROJECT: Dunn Field Fluvial SVE

PROJECT NO.: 3202-031 SITE LOCATION: DF

PROJECT MANAGER: T. Holmes

FIELD STAFF: J. Anstaett

BOREHOLE STARTED: 5/2/07 08:25 BOREHOLE FINISHED: 5/2/07 11:00

DRILLING INFORMATION

DRILLING CO.: Prosonic


DRILLER: J. Asua

DRILLING METHOD/RIG: Sonic BOREHOLE DIAMETER: 6-in.

GROUND SURFACE ELEVATION: 301.06 (ft, msl) WATER DEPTH/ DATE: 80.05 -ft. toc -5/9/07

BOREHOLE USE: Monitoring Well

NOTES: Well completed above grade with 2.76 ft. stick up.



Created By: WTR

Checked By: KMS

PAGE: 1 of 4



BOREHOLE NO.: MW-222 TOTAL DEPTH: 96 ft.

| Depth | Soil Symbol | Soil Description | Well Completion | Well Description |
|----------------------|----------------|---|--------------------|---------------------|
| | | CL Sandy clay - red 2.5YR (4/6), with gray mottling, medium plasticity, soft fine grained sand, moist. | | |
| _ _ _ | | SP Clayey sand - red 2.5YR (4/8), fine grained sand, poorly graded, moist. | | |
| - - - 40- | | SP Clayey sand - red 2.5YR (4/6), fine grained sand, poorly graded, moist. Odor | | |
| _ | | SP Sand - yellow 10YR (7/8), with few gravel, fine grained, sub-rounded gravel, poorly graded, moist. Odor | | |
| - - - | | SP Silty sand - yellow 10YR (8/6), with some gravel, fine grained sand, sub-rounded to rounded gravel, poorly graded, dry. Odor | | |
| 50 - - | | | | |
| | | SW Gravely sand - yellowish brown 10YR (7/8), fine to coarse grained sand, sub-angular to sub-rounded gravel, well graded, dry. Odor | | |
| | | SP Sand - yellow 10YR (7/8), with few gravel, fine grained sand, sub-rounded to rounded gravel, poorly graded, moist. Odor | | |
| 60- | | | 绘 | |

Created By: WTR

Checked By: KMS



BOREHOLE NO.: MW-222 TOTAL DEPTH: 96 ft.

| - | | 252 | _ |
|-------------|---|------------|------------------|
| | | | Bentonite Plug |
| - - - | SP Silty sand - reddish yellow 5YR (6/8), fine grained sand, poorly graded, moist. Odor | | Sand Pack |
| 70- | | - ft. bgs. | Screened Interva |
| - | SW Gravely sand - strong brown 7.5YR (5/6), fine grained sand, sub-rounded to rounded gravel, well graded, moist. Odor | 77.29 | |
| 80- | CH Clay - pinkish gray 7.5YR (7/2), medium plasticity, soft, moist. SW Sand - reddish yellow 7.5YR (6/8), with few gravel, fine to coarse grained sand, subrounded gravel, well graded, wet. | | |
| - - - | CL Silty clay - dark gray 2.5Y (4/1), medium plasticity, hard, moist. | | |

Checked By: KMS



BOREHOLE NO.: MW-222 TOTAL DEPTH: 96 ft.

| Depth | Soil Symbol | Soil Description | Well Completion | Well Description |
|-------|----------------|------------------|--------------------|---------------------|
| _ | | | | |
| | | End of Log | | |
| - | | | | |
| - | | | | |
| 100- | | | | |
| | | | | |
| - | | | | |
| - | | | | |
| - | | | | |
| | | | | |
| - | | | | |
| - | | | | |
| 110- | | | | |
| | | | | |
| - | | | | |
| - | | | | |
| | | | | |
| - | | | | |
| - | | | | |
| - | | | | |

Created By: WTR

Checked By: KMS