

BOREHOLE NO.: MW-223 TOTAL DEPTH: 96 ft.

#### **PROJECT INFORMATION**

**PROJECT: Dunn Field Fluvial SVE** 

PROJECT NO.: 3202-031
SITE LOCATION: DF

**PROJECT MANAGER: T. Holmes** 

FIELD STAFF: J. Anstaett

BOREHOLE STARTED: 4/30/07 12:20 BOREHOLE FINISHED: 5/1/07 07:45

#### **DRILLING INFORMATION**

**DRILLING CO.: Prosonic** 

DRILLER: J. Asua

DRILLING METHOD/RIG: Sonic BOREHOLE DIAMETER: 6-in.

GROUND SURFACE ELEVATION: 300.41 (ft, msl) WATER DEPTH/ DATE: 78.90 -ft. toc - 5/8/07

**BOREHOLE USE: Monitoring Well** 

NOTES: Well completed above grade with 2.59 ft. stick up.

Depth	Soil Symbol	Soil Description	Well Completion	Well Description
		Grass and roots.		
10-		CL Silty clay - dark yellowish brown 10YR (3/4), medium plasticity, soft, moist.		Grouted Annulus
- - -		CL		
20-		Silty clay - strong brown 7.5YR (4/6), medium plasticity, soft, moist.		
-		CL Sandy clay - red 2.5YR (4/6), low plasticity, hard, moist.		
30		<b>CL</b> Sandy clay - red 2.5YR (4/8), gray mottling, fine grained sand, low plasticity, hard, moist.		
30-	324 63 324 63 324 69 324 10	Sandy clay - red 2.5YR (4/8), gray mottling,		

Created By: WTR

Checked By: KMS

PAGE: 1 of 4



BOREHOLE NO.: MW-223 TOTAL DEPTH: 96 ft.

Depth	Soil Symbol	Soil Description	Well Completion	Well Description
		SP Clayey sand - yellowish red 5YR (5/8), fine grained sand, poorly graded, moist.		
40-		SP Silty sand - yellowish red 5YR (5/8), fine grained sand, poorly graded, dry.		
-		SP Silty sand - reddish yellow 5YR (6/8), fine grained sand, poorly graded, dry.		
50-		SP Sand - reddish brown 5YR (4/4), fine to coarse grained sand, poorly graded, moist.		
		SW Gravely sand - yellowish red 5YR (5/8), fine to coarse grained sand, sub-rounded to rounded gravel, well graded, dry.		
60-				

Created By: WTR

Checked By: KMS



BOREHOLE NO.: MW-223 TOTAL DEPTH: 96 ft.

epth	Soil Symbol	Soil Description	Well Completion	Well Description
		SP Silty sand - yellow 10YR (7/8), fine grained sand with few coarse grained sand, poorly graded, dry.		Bentonite Plug
		SP Silty sand - yellowish red 5YR (5/8), fine grained sand, poorly graded, dry.		Sand Pack
70-			3.31- ft. bgs.	Screened Interv
		SP Silty sand - reddish yellow 7.5YR (7/6), fine grained sand with trace medium to coarse grained sand, poorly graded, wet.		
80-		CH Clay - weak red 10R (5/4), medium plasticity, soft, moist.		
		SW Gravely sand - reddish yellow 7.5YR (6/6), fine to coarse grained sand, sub-rounded to rounded, well graded, wet.  CH Silty clay - dark gray 2.5Y (4/1), medium plasticity, hard, moist.		
90-			<del>7'-7'-7'-7'-7</del>	

Created By: WTR

Checked By: KMS

PAGE: 3 of 4



BOREHOLE NO.: MW-223 TOTAL DEPTH: 96 ft.

End of Log  100	Depth	Soil Symbol	Soil Description	Well Completion	Well Description
100-	-				
			End of Log		
	-				
110-	100-				
110-	-				
110-	-				
110-	-				
110-	-				
	110-				
	-				
	_				
	_				
120-	-				

Created By: WTR

Checked By: KMS