

BOREHOLE NO.: MW-226 TOTAL DEPTH: 96 ft.

PROJECT INFORMATION

PROJECT: Dunn Field Fluvial SVE

PROJECT NO.: 3202-031
SITE LOCATION: DF

PROJECT MANAGER: T. Holmes

FIELD STAFF: J. Anstaett

BOREHOLE STARTED: 5/1/07 11:25 BOREHOLE FINISHED: 5/1/07 14:00

DRILLING INFORMATION

DRILLING CO.: Prosonic

DRILLER: J. Asua

DRILLING METHOD/RIG: Sonic BOREHOLE DIAMETER: 6-in.

GROUND SURFACE ELEVATION: 300.56 (ft, msl) WATER DEPTH/ DATE: 79.30 -ft. toc - 5/8/07

BOREHOLE USE: Monitoring Well

NOTES: Well completed above grade with 2.63 ft. stick up.

Depth	Soil Symbol	Soil Description	Well Completion	Well Description
		Topsoil grass and root zone.		
10-		CL Silty clay - dark yellowish brown 10YR (4/4), medium plasticity, soft, moist.		Grouted Annulus
20-		CH Sandy clay - strong brown 7.5YR (5/6), high plasticity, soft, fine grained sand, moist. CL Sandy clay - red 2.5YR (4/8), medium		
30-	V 10 V 10 V 10 V 10	Sandy clay - red 2.5YR (4/8), medium plasticity, soft, fine grained sand, moist.		

Created By: WTR

Checked By: KMS

PAGE: 1 of 4



BOREHOLE NO.: MW-226 TOTAL DEPTH: 96 ft.

Depth	Soil Symbol	Soil Description	Well Completion	Well Description
- - -		SP Clayey sand - yellowish red 5YR (5/8), fine grained sand, poorly graded, dry.		
40-		SP Silty sand - yellowish red 5YR (5/8), fine grained sand with few medium to coarse grained sand, poorly graded, dry.		
-		SW Gravely sand - yellow 10YR (7/8), fine to medium grained sand, sub-rounded to subangular gravel, well graded, dry.		
50-		SP Silty sand - yellowish red 5YR (5/6), trace gravel, fine grained sand with trace coarse grained sand, sub-rounded gravel, poorly graded, dry.		
-		SP Silty sand - reddish yellow 5YR (7/6), fine grained sand, poorly graded, dry.		
-		SW Gravely sand - strong brown 7.5YR (5/8), fine to coarse grained sand, sub-rounded to rounded gravel, well graded, moist.		
60-				

Created By: WTR

Checked By: KMS



BOREHOLE NO.: MW-226 TOTAL DEPTH: 96 ft.

Depth	Soil Symbol	Soil Description	Well Completion	Well Description
-				Bentonite Plug
- - -		SP Silty sand - reddish yellow 7.5YR (6/8), fine grained sand, poorly graded, dry.		Sand Pack
70- - - - -			.67- ft. bgs.	Screened Interva
- - -		SP Sand - strong brown 7.5YR (5/8), with few gravel, fine grained sand, sub-rounded gravel, poorly graded, wet.	92	
- 80 - - -		CH Clay - red 10R (4/6), high plasticity, soft, moist. SP Sand - reddish yellow 7.5YR (6/6), with some gravel, fine to coarse grained sand, subrounded gravel, poorly graded, wet.		
-		CH Clay - light gray 2.5Y (7/2), high plasticity, soft, moist. CH Clay - light gray 2.5Y (7/2), high plasticity, soft, moist.		
90-	ed By: WTR		ZN(ZN(ZN)	

Checked By: KMS

PAGE: 3 of 4



BOREHOLE NO.: MW-226 TOTAL DEPTH: 96 ft.

Depth	Soil Symbol	Soil Description	Well Completion	Well Description
- - - -		CL Clay - dark gray 5Y (4/1), medium plasticity, hard, moist.		
		End of Log		
-		Ç		
-				
-				
100-				
_				
_				
_				
_				
-				
-				
-				
-				
-				
110-				
_				
_				
_				
_				
_				
_				
_				
_				
_				
120-				

Created By: WTR

Checked By: KMS