



283 Rucker Street
Anniston, Alabama 36205
Phone: 256.847.0780
Fax: 256.847.0905
matrixdesigngroup.com

January 10, 2019

Tom Lederle
US Army – BRAC Division
2530 Crystal Drive, Room 5000
Taylor Bldg/NC 3
Arlington, VA 22202

Mr. Jason Wilson, Chief
c/o Mrs. Brandi Little
Governmental Hazardous Waste Branch Land Division
Alabama Department of Environmental Management
1400 Coliseum Boulevard
Montgomery, AL 36110

Subject: Land Use Control Effectiveness Report – 2018

Dear Mr. Lederle and Mr. Wilson,

On behalf of the McClellan Development Authority (MDA), Matrix Environmental Services, LLC (MES) is pleased to submit the 2018 Land Use Control Effectiveness Report (LUCER). The LUCER documents the land use controls that are in place as well as violations of land use controls and corrective measures completed to prevent future violations. The LUCER also includes the *2018 Annual Closure System Report, Landfill 3, Parcel 80(6) and Fill Area Northwest of Reilly Airfield, Parcel 229(7)*, the 2018 cap inspection reports for Landfill 1, Parcel 78(6); Landfill 2, Parcel 79(6); Landfill 4, Parcel 81(5) including the active cell Industrial Landfill, Parcel 175(5); the Fill Area North of Landfill 2, Parcel 230(7); Former Post Garbage Dump, Parcel 126(7); and Fill Area East of Reilly, Parcel 227(7); and the 2018 inspection for Range 12: Iron Mountain Road Ranges Maintenance and Inspection Plan, Parcel 70Q.

Please contact me at (256) 847-0780 (Anniston) or (770) 594-0331 (Atlanta) if you have any questions or require further information.

Sincerely,

A handwritten signature in black ink that reads "Richard Satkin".

Richard Satkin, P.G.
McClellan Program Manager

cc: Jason Odom – MDA
Lisa Holstein -Transition Force
MDA File Copy
MES File Copy